

ASS. REC. BY:

REF:

CS/FCL18006003/Kgb⁰²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

CWS May Chua

of

FCL

Date/Time:

29032018 5:11pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 4156D

Insured:

SHC 8080E

at Workshop m/s

Estem Performance

Tel:

6484 1221

of

3033 Amk Ind Park 2 # 01-2B1

Policy No:

Claim No:

DIS002557MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11-03-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'w/p'

H.O.D. Endorsement:

Date/Time:

02042018 1003am

Person Contacted:

Carmen

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLH 4156D - x
	SHC 8080E - DOA / AXA 17016273 / K1wa392 DOA: 210817
10/4/18 @ 2:11pm	Revised to May Chua by email.
	81230.85 Carbur (Red & 235.55, 162)

REF:

FCL

ASSIGNMENT

From:

Date:

09/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLH 4156D

at Workshop n/s

Eastern Performance

of

AMK

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

After 11:30am



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

C1

days

Res.: Yes or No

Lum Sum:

1. B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 4156D

Yr Regn:

09, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius A)

c.c

1798

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

123828

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4503535208

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SiRim / STD A/Rim or

Tyre Size:

R: Mexen

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

3

mm

L/Bal.

9

mm

L/Bal.

3

mm

D.O.A.

11/3/18

D.O.I.

9/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear of down mirror

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

14 file pass to Cathrin

RECEIVED 04 JUL 2018.

Date/Time, File Pass to?



Preli. Report



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Survey Fee:

Transportation:

) \$ + R5 \$

) Photos

) Other

TOTAL

100

50

50

10

210

Report Format:

7e

Lump Sum / I.B.I. (\$

1230.65



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006003/Kqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 02-04-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8080E		Veh. Inspected	SLG 4156D
Policy No.			Coverage (\$)	0.00
Claim No.	D18002557MFSH		Excess (\$)	0.00
Assign From	CWS (MAY CHUA)		Assign Date	29/03/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	11/03/2018		Inspection Date	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002557MFSH

Date: 10 April 2018

Our Ref: CS/FCI18006003/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 4156D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 09/04/2018 at the premises of M/s ESTEEM PERFORMANCE. and have the following to report:-

Workshop Estimate Amount	: S\$ 1,466.20 .
Revised Estimate Amount	: S\$ 1,230.65 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the front o/s door mirror.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	29-03-2018	Our Ref No. D18002557MFSH
Accident Date	11-03-2018	Claim Type. Third Party
Insured Vehicle	SHC8080E	Third Party Vehicle. SLG4156D
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 87990066	Fax No. 64847829
Survey Type	WITHOUT PREJUDICE: ACCIDENT NOT REPORTED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

*01042018 @ 1003am
 Carmen rth not in*

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 10 April 2018 2:11 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002557MFSH/1
Attachments: CSFC118006003Kqb.pdf

Dear May,

Enclosed herewith preliminary advice of SLG 4156D.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 2 April 2018 10:05 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002557MFSH/1

Dear Sir / madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 29 March, 2018 5:11 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002557MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SLG 4156 D

Parts	(a) Cost / List Price Items	\$	1,461.60
	Plus/Less 25%	\$	365.40
	Total of Cost / List	\$	1,096.20
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	1,096.20
Labour		\$	370.00
Total		\$	1,466.20

Not Authorized
1.B.1
Resurvey B6paim

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : CKC
Survey conducted on : 9/4/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 01 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 9/4/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Spare Parts

Vehicle No. : **SLG 4156 D**
Make & Model : **TOYOTA PRIUS**
Chassis No. : **JTDKB3FU503535208**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH wing mirror (arm)	1			
2	RH wing mirror (signal lamp)	1	\$1,374.20		✓
3	RH wing mirror (glass)	1			
4	RH wing mirror (cover)	1	\$87.40		X
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006003/Kqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-07-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8080E	Veh. Inspected	SLG 4156D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18002557MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	29/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDKB3FU503535208	Colour	METALLIC SILVER	
Odometer	123828	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	9 mm	
R/H Rear Tyre	195/65 R15	NEXEN	3 mm	
L/H Rear Tyre	195/65 R15	NEXEN	3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/03/2018	Inspection Date	09/04/2018	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		1 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 4156D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	RH WING MIRROR (SIGNAL LAMP) }	CRACKED	1,374.20	1,374.20
1	RH WING MIRROR (ARM) }		-	-
1	RH WING MIRROR (GLASS) }		-	-
1	RH WING MIRROR (COVER)	TO REPAIR SEE LABOUR	87.40	-
	LESS 25% DISCOUNT		-365.40	-343.55
			1,096.20	1,030.65
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(RH SIDE MIRROR).INCLUSIVE OF THE REPAIR OF RH WING MIRROR (COVER).		100.00	60.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RH SIDE MIRROR).		100.00	60.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT DOOR TRIM,DOOR GLASS,WINDOW REGULATOR,DOOR LOCK TO ASSIST WORK LOAD.		120.00	60.00
			370.00	200.00
	GRAND TOTAL		1,466.20	1,230.65
	RECOMMENDED COST OF REPAIRS			1,230.65

Report Ref No. CS/FCI18006003/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.