

REPAIR ESTIMATE*

VEHICLE NO : SHC 1844P

MAKE :

MODEL : HYUNDAI SONATA

CHINA / LKK

DATE 20/3/2018 11:02

F2

P-1

Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet			\$ 1,151.80
	Bonnet Hinge (LH/RH)		\$ 87.50	\$ 175.00
	Bonnet Moulding			\$ 120.90
	Bonnet Lock			\$ 48.80
	Bonnet Absorber			\$ 70.80
	Bonnet Insulator			\$ 232.80
	Bonnet Insulator Clips			\$ 10.00
	Bonnet Cable			\$ 45.50
	Radiator Grille			\$ 282.10
	Radiator Grille U Moulding			\$ 108.90
	Front Bumper Cover			\$ 538.80
	Front Bumper Sponge			\$ 136.30
	Front Bumper Reinforcement			\$ 504.10
	Front Bumper Grille (LH/RH)		\$ 17.60	\$ 35.20
	Front Bumper Centre Grille			\$ 131.10
	Front Bumper Lip			\$ 59.90
	Front Bumper Bracket Top (LH/RH)		\$ 22.40	\$ 44.80
	Front Bumper Protector (LH/RH)		\$ 29.20	\$ 58.40
	Front Bumper Bracket (LH/RH)		\$ 20.10	\$ 40.20
	Headlamp Support Panel Assy			\$ 1,023.00
	Headlamp (LH/RH)		\$ 797.90	\$ 1,595.80
	Headlamp Halogen Bulb (LH/RH)		\$ 13.80	\$ 27.60
	Radiator			\$ 814.80
	Radiator Fan Blade,Cowling,Motor Assy			\$ 651.30
	Radiator Bracket		\$ 6.20	\$ 12.40
	Radiator Hose Upper			\$ 45.40
	Radiator Hose Lower			\$ 45.40
	Radiator Expansion Tank			\$ 46.00
	Horn Unit (RH)			\$ 83.10
	Horn Wire			\$ 150.00
	Front Fender (LH/RH)		\$ 593.00	\$ 1,186.00
	Front Fender Apron Panel (RH)			\$ 1,120.50
	Front Fender Shield (LH/RH)		\$ 86.00	\$ 172.00
	Front Fender Mudflap (RH)			\$ 15.50
	Air Cleaner Assy			\$ 254.30
	Air Duct			\$ 197.50
	Aircon Condenser			\$ 1,089.90
	Aircon Suction & Liquid Hose			\$ 631.40
	Aircon Discharge Hose			\$ 223.50
	Aircon Compressor			\$ 2,738.50
	Battery Tray			\$ 53.00
	Front Door (RH)			\$ 1,345.00
	Front Door Inner Lock (RH)			\$ 334.40
	Front Door Protector (RH)			\$ 74.90
	Rocker Panel Outer Garnish			\$ 463.40
	Front Windscreen Glass			\$ 1,015.00
	Front Windscreen Moulding			\$ 60.00

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Wiper Panel Top Garnish			\$ 87.40
	Wiper Container			\$ 59.00
	Wiper Container Motor			\$ 63.00
	Front Wheel Rim (RH)			\$ 284.70
	Front Wheel Hub Cap (RH)			\$ 145.00
	Front Wheel Bearing	\$	258.50	\$ 517.00
	Front Shock Absorber (Assy) (LH/RH)	\$	203.70	\$ 407.40
	Front Shock Absorber Mounting (LH/RH)	\$	72.00	\$ 144.00
	Front Shock Absorber Fork (LH/RH)	\$	203.30	\$ 406.60
	Front Suspension Upper Arm (LH/RH)	\$	240.00	\$ 480.00
	Front Drive Shaft (LH/RH)	\$	1,025.00	\$ 2,049.99
	Rack & Pinion Assy			\$ 2,093.00
	STG Tie End	\$	66.50	\$ 133.00
	Stabilizer Bar			\$ 213.20
	Stabilizer Bar Bush (LH/RH)	\$	12.80	\$ 25.60
	Stabilizer Bar Link	\$	78.30	\$ 156.60
	Stabilizer Bracket	\$	23.00	\$ 46.00
	Front Suspension Lower Arm (LH/RH)	\$	685.20	\$ 1,370.40
	Front Chasis Member (LH/RH)	\$	1,219.80	\$ 2,439.60
	Knuckle Arm (LH/RH)	\$	558.60	\$ 1,117.20
	Timing Cover Upper			\$ 121.40
	Timing Cover Lower			\$ 110.00
	Timing Tensioner Assy			\$ 228.00
	Fan Belt			\$ 155.00
	Brake Master Pump			\$ 416.70
	Brake Booster Pump			\$ 981.50
	Engine Mounting			\$ 461.80
	Engine Under Cover			\$ 328.70
	Engine Crossmember			\$ 2,143.70
	Engine Mtg (Front)			\$ 225.50
	Engine Mtg (Rear)			\$ 268.00
	Gearbox Mounting			\$ 328.20
	Instrumental Panel			\$ 1,595.00
	Pstg Hose & Bracket			\$ 73.20
	Power Steering Pump			\$ 722.70
	Power Steering Tank			\$ 174.10
	Power Steering Pressure Hose Assy			\$ 588.60
	Power Steering Outlet Hose & Bracket			\$ 73.20
	Power Steering Pipe Assy			\$ 73.20
	Power Steering Pulley			\$ 65.30
	Alt / P.Stg V-Belt CRDI			\$ 70.90
	Alternator Assy			\$ 1,077.30
	Starter Motor Assy			\$ 1,092.50
	ECU Bracket			\$ 78.30
	ECU Unit			\$ 4,028.30
	Oil Cooler - Tube Assy-P/Stg			\$ 256.00
	Inter Cooler			\$ 771.50
	Inter Cooler Mounting (2 PCS)			\$ 24.80
	Hose B To Inter Cooler			\$ 220.10
	Hose C To Inter Cooler Inlet			\$ 108.50

F2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Pipe To Inter Cooler			\$ 160.00
	Pipe To Inter Cooler Outlet			\$ 234.30
	Controller (PWN)			\$ 495.80
	Oil Cooles Assy-Gearbox			\$ 272.00
	ABS Sensor			\$ 250.50
	Wiring-Engine			\$ 3,187.40
	Wiring-Front			\$ 1,879.00
	Wiring-ECM			\$ 3,107.80
	Actuator - Swirl Control			\$ 800.20
	Auto Gear Oil			\$ 105.80
	Engine Top Cover			\$ 369.90
	Throttle Body Assy			\$ 1,077.40
	Intake Manifold Assy			\$ 1,212.40
	SUB TOTAL			\$ 61,518.19
	LESS 20%			\$ 12,303.64
	DISCOUNTED TOTAL			\$ 49,214.55
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
	Front Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	New Battery			\$ 207.00
	Front Door Comfort Logo (RH)			\$ 75.00
	Front Door Advertisement Logo (RH)			\$ 100.00
	Front Windscreen Sealant			\$ 46.00
	Front ERP Sticker			\$ 30.00
	Front Tyre (RH)			\$ 207.00
	Gearbox			\$ 5,800.00
				\$ 6,720.00
	Labour Charge			
	Panel Beating			\$ 2,500.00
	Spray Painting Charge			\$ 1,750.00
	Wiring Charge			\$ 100.00
	Tuff Kote			\$ 150.00
	Towing Charge			\$ 50.00
	Front Chassis Alignment Charge			\$ 400.00
	Transfer of Door			\$ 120.00
	Remove/Refix Undercarriage (FRT)			\$ 400.00
	FRT Wheel Alignment			\$ 120.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
	Remove/Refix Engine/Gearbox			\$ 650.00
	Remove/Refix Dashboard			\$ 450.00
	Remove/Refix Fuse Box			\$ 180.00
	Remove/Refix Front Windscreen Glass			\$ 120.00
	Remove/Refix Cushion & Upholstery Front			\$ 90.00
	Remove/Refix Power Steering Pump			\$ 120.00
	TOTAL LABOUR			\$ 7,350.00
	ESTIMATE TOTAL			\$ 63,284.55

Fauzy

Nett
Nett
Nett
Nett
Nett
Nett
Nett
Nett
Nett
Nett

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHC 1844P

DATE 20/3/2018 11:27

MAKE :

MODEL : HYUNDAI SONATA

CHINA/LKK

P-4 F2

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Hinge (LH/RH)		\$ 170.60	\$ 341.20
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (RH)			\$ 230.20
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Bracket (LH/RH)		\$ 49.00	\$ 98.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00
	Tail Lamp (RH)			\$ 344.00
	Tail Lamp Quarter Panel (RH)			\$ 93.80
	Tail Lamp Panel Top (RH)			\$ 217.40
	Panel Assy-Rear Floor Side (LH/RH)		\$ 88.55	\$ 177.10
	Rear Floor Chassis Member (RH)			\$ 1,280.50
	Rear Fender (RH)			\$ 1,935.90
	Rear Fender Inner Panel (RH)			\$ 1,255.00
	Rear Fender Inner Lining (RH)			\$ 74.10
	Rear Fender Outer Corner Garnish (RH)			\$ 32.20
	Rear Tray Lugg Side (RH)			\$ 37.40
	Rear Fender Mudflap (RH)			\$ 15.50
	Rear Fender Trim Board (RH)			\$ 180.90
	Rear Windscreen Moulding			\$ 60.00
	Rear Door (RH)			\$ 1,294.70
	Rear Door Rubber (RH)			\$ 121.20
	Rear Door Outer Moulding (RH)			\$ 203.30
	Rear Door Gear/Regulator (RH)			\$ 300.00
	Rear Door Lock Assy			\$ 308.40
	Rear Door Trim Board (RH)			\$ 855.30
	Rear Door Protector(RH)			\$ 54.50
	Rear Tyre Rim (RH)			\$ 284.70
	Rear Wheel Hup-Cap (RH)			\$ 145.00
	Rear Wheelbearing ING & Hub			\$ 384.60
	Rear Shock Absorber (RH)			\$ 190.60
	Rear Shock Absorber Mounting (RH)			\$ 55.30
	Rear Upper Arm (RH)			\$ 321.70
	Rear Lower Arm (RH)			\$ 195.80
	Rear Knuckle Arm (RH)			\$ 550.80
	Fire Extingusher Holder			\$ 35.00

Fauzy

P-5

SHC 1844P

F₂

Fauzy

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	SUB TOTAL			\$ 14,896.40	
	LESS 20%			\$ 2,979.28	
	DISCOUNTED TOTAL			\$ 11,917.12	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett
	Boot Lid Advertisement Logo			\$ 100.00	Nett
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
	Rear Windscreen Sealant			\$ 46.00	Nett
	Rear Door Advertisement Logo (RH)			\$ 100.00	Nett
	Rear Door Tel No. Sticker (RH)			\$ 10.00	Nett
	Rear Tyre (RH)			\$ 207.00	Nett
				\$ 928.70	
	Labour Charge				
	Panel Beating			\$ 1,750.00	
	Spray Painting Charge			\$ 1,500.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 100.00	
	Rear Chassis Alignment Charge			\$ 400.00	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	
	Remove/Refix Rear Windscreen Glass			\$ 120.00	
	Remove/Refix Reverse Sensor			\$ 120.00	
	Remove/Refix Undercarriage (RR)			\$ 400.00	
	Transfer of Door			\$ 120.00	
	Rear Wheel Alignment			\$ 120.00	
				\$ 4,830.00	
				\$ 17,675.82	
	Rasul CLKK) 22/03/18 @ 1030 hrs Note: Due to vehicle extensive damages, we as the opinion treat this vehicle as uneconomical to repair. Kindly provide the book value, COE value etc and forward email: rasul@kkkauto.com				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					



JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: <u>19/3/18</u> Time Received: <u>1400</u>		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☐ Normal Tow ☒ King Dolly ☐ Flat Bed ☐ Crane-up
2. ☐ New ☐ SPARK Kakis Name of Customer : <u>TP</u> Contact No. : <u>TP</u> Vehicle No. : <u>SAC 0844-P</u> Make / Model / Colour : Email :		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery	6. Parts Replaced/Remarks:
7. Location: <u>TP Pandan</u>		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi <u>No Ray</u>	
9. Preferred Workshop: ☐ Braddell ☐ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others:			

10. Odometer Reading : _____ Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E	11. Radio / CD Player ☒ OK ☐ Faulty ☐ Not tested	 # : Cracked X : Dented / : Scratched O : Missing Signature of Customer: <u>TP</u>
---	---	---

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☒ QA ☐ GAO ☐ TZ ☐ YISHUN ☐ OTHERS Name of Driver : <u>TP</u> Vehicle No. : <u>1K77178</u> Time Dispatch : <u>19/3/18</u> Time of Arrival : <u>1440</u> Time Completed :		
--	--	--

Cash Invoice Details (if applicable)

13. Cash Invoice No. :	
------------------------	--

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
- b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
- c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

Date: <u>19/3/18</u>	Time: _____	Signature of Customer: <u>TP</u>
----------------------	-------------	----------------------------------

14. WORKSHOP

Name of Attending Staff/Guard	Date & Time of Arrival	Signature of Attending Staff/Guard
-------------------------------	------------------------	------------------------------------

CUSTOMER'S COP