



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006015/K1vb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 02-04-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 4888M	Veh. Inspected	SH 8308T
Policy No.	5097190527	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/04/2018	Inspection Date	02/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAUTO)

From: mtreg <mtreg@income.com.sg>
Sent: Monday, 9 April 2018 3:56 PM
To: Veron Chen (LKKAUTO)
Subject: FW: REQUEST FOR CLAIM NUMBER

Hi

All claim created.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1	MT/0989219-002	COMFORT TRANSPORTATION PTE LTD	SH 8308T	SKB 4888M
2	MT/0988775-002	CITYCAB PTE LTD	SHA 9768J	SJL 270E

D.O.A	Time of Accident	Estimate	Tentative repair cost
2/4/2018	6:50	\$9,897.03	7391..75
30/3/2018	13:30	\$8,858.80	\$3,400.00

With Regards

Azlin Rani
Senior Administrator, Motor Insurance
www.income.com.sg



From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 9 April, 2018 11:53 AM
To: mtreg
Subject: REQUEST FOR CLAIM NUMBER

Dear Sir/Madam,

Please provides us the claim number.

S/NO	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle
1		COMFORT TRANSPORTATION PTE LTD	SH 8308T	SKB 4888M
2		CITYCAB PTE LTD	SHA 9768J	SJL 270E

D.O.A	Time of Accident	Estimate	Tentative repair cost
2/4/2018	6:50	\$9,897.03	7391..75
30/3/2018	13:30	\$8,858.80	\$3,400.00

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

eBaoTech

General Claim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.	<input type="text"/>	Date of Accident	<input type="text" value="02/04/2018 19:17"/>						
Vehicle No. (For Motor)	<input type="text" value="SKB4888M"/>								
<input type="button" value="Search"/>									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5097190527	CHANG CHOON WAI	S1760050H	GPC	drive CLASSIC	SKB4888M	SKB4888M	22/01/2018	21/01/2019
<input type="button" value="Continue"/>									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/04/2018 11:10
Date Of Accident	02/04/2018 06:50
Exact Location Of Accident	ALONG PIE TOWARD CHANGI AIRPIRT B4 PAYA LEBAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH8308T
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	EE TECK HIAN
NRIC No	S1831417G
Date Of Birth	26/10/1967
Occupation	OUTDOOR
Date Of Driving Pass	05/06/1987
Driving Experience	30 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	LAYKOON18@YAHOO.COM.SG

Address	1A #42-01 CANTONMENT ROAD
Postcode	085101
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB4888M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	ANDREW WHITMARSH
NRIC/Passport Number	
Contact Number	96552016
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT & REAR

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SFN3989H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LOH CHOU HUAT
NRIC/Passport Number	
Contact Number	81219090
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRT
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 2/4/18 at abt 650 hrs, I was driving along PIE towards Changi Airport before Paya Lebar Exit on lane 1. There are a few cars in front slowed down & broke, I applied brake & Suddenly I felt the impact from the rear of my taxi. I checked & found a chain collision involved vehicle SKB4888M & SFN3989H. My taxi was collided by SKB4888M. 1 male passenger on board No injury was reported.

DECLARATION

I/We declare the foregoing particulars are true in every respect.
COMFORT TRANSPORTATION PTE LTD
CO REG. NO. 199303821R

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel's Signature
Name:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)


I understand, acknowledge, agree and consent that:




- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.





COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:





Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO 305137255

CUSTOMER
R/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65508755 (O)
(P)

REGN NO:	SH 8308T	MILEAGE
MAKE:	TOYOTA	FUEL E.....1/2.....F
MODEL:	PRIUS HYBRID(G4)02.	DATE/TIME IN 04.2018 07:50
YR OF MANU.	30.05.2017	TARGET DATE
CHASSIS CODE	JTDKB3FU803557283	COMPLETION DATE/TIME:

SCOUNT CARD NO.

JOB DESCRIPTION

Accident Date: 02.04.2018
NATURE: 3P 02.04.2018

S/NO	LABOR CODE	DESCRIPTION
------	------------	-------------

CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

Exit Pass

Vehicle No.: SH 8308T
CHIANG @

Vehicle No.: SH 8308T

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

to be returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE

2/4/2018 10:29

VEHICLE NO: SH 8308T

MAKE :

MODEL : TOYOTA PRIUS

Chiang & Tan

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
REAR TRUNK LID COVER — <i>Bo-y</i>			\$ 922.50 ✓
REAR TRUNK LID LOCK X <i>su</i>			\$ 447.70 ✓
REAR TRUNK LID RUBBER X <i>su</i>			\$ 357.00 ✓
REAR TRUNK LID GLASS (BLACK COLOR) — <i>cm</i>			\$ 721.30 ✓
BOARD ASSY, BACK DOOR TRIM X <i>su</i>			\$ 246.90 ✓
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE — <i>cm</i>			\$ 889.70 ✓
REAR BUMPER — <i>Refined</i>			\$ 458.60 ✓
REAR BUMPER RE-INFORCEMENT — <i>Bo-y</i>			\$ 318.80 ✓
REAR BUMPER UNDER COVER — <i>cm</i>			\$ 552.60 ✓
REAR BUMPER SIDE RETAINER + <i>su</i>			\$ 112.70 ✓
REAR BUMPER SPONGE X <i>su</i>			\$ 143.40 ✓
REAR BUMPER UNDER SIDE COVER (RH) — <i>cm</i>			\$ 167.60 ✓
REAR BUMPER UNDER SIDE CENTRE COVER + <i>su</i>			\$ 552.60 ✓
REAR BUMPER CLIPS — <i>all</i>			\$ 22.00 ✓
RETAINER, REAR BUMPER, SIDE, RH X <i>su</i>			\$ 94.80 ✓
SEAL, REAR BUMPER SIDE, RH X <i>su</i>			\$ 148.40 ✓
TAIL LAMP ASSY (UPPER), RH — <i>cm</i>			\$ 557.90 ✓
TAIL LAMP ASSY (LOWER), RH — <i>cm</i>			\$ 548.40 ✓
REAR END PANEL — <i>Bo-y</i>			\$ 602.10 ✓
REAR END PANEL GARNISH X <i>su</i>			\$ 121.60 ✓
REAR WINDSCREEN GLASS — <i>all</i>			\$ 1,555.80 ✓
REAR WINDSCREEN GLASS MOULDING + <i>su</i>			\$ 208.60 ✓
SUB TOTAL			\$ 9,751.00
LESS 25%			\$ 2,437.75
DISCOUNTED TOTAL			\$ 7,313.25
REAR NO. PLATE WITH TRIM COVER + <i>su</i>			\$ 100.00 NETT ✓
REAR TRUNK LID APPS STICKER — <i>all</i>			\$ 40.00 NETT ✓
REAR TRUNK LID COMFORT & TEL NO. STICKER — <i>all</i>			\$ 60.00 NETT ✓
REAR BUMPER REVERSE SENSOR — <i>Shaded</i>			\$ 135.70 NETT ✓
REAR BUMPER ADVERTISEMENT LOGO — <i>all</i>			\$ 50.00 NETT ✓
REAR WINDSCREEN SEALANT — <i>all</i>			\$ 46.00 NETT ✓
			\$ 431.70

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
Labour Charge			600
Panel Beating			\$ 750.00
Spray Painting Charge			\$ 750.00 600
Wiring Charge			\$ 50.00 20
Tuff Kote			\$ 50.00 20
Remove/Refix Cushion & Upholstery Rear			\$ 150.00 50
Remove/Refix Rear Windscreen Glass			\$ 120.00 100
Remove/Refix Reverse Sensor			\$ 120.00 20
TOTAL LABOUR			\$ 1,990.00
ESTIMATE TOTAL			\$ 9,734.95
			9897-03

Kabin Utker

2/4/18 14:00 hrs

4 Days

P/P

Before Paint photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "no prejudice" basis
- No illegal modification is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by: _____

Signature: _____

Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305137255
 REGN NO : SH 8308T
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 30.05.2017
 DATE/TIME IN : 02.04.2018 07:50
 ACCIDENT DATE : 02.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2256-G	PRIG4 PANEL SUB-ASSY BACK	1	922.50	25.00	691.87
0002	04-01-0302-2257-G	PRIG4 GLASS BACK WINDOW F	1	721.30	25.00	540.97
0003	04-01-0302-2258-G	PRIG4 GLASS BACK DOOR	1	1,555.80	25.00	1,166.85
0004	04-01-0302-2346-G	PRIG4 GARNISH SUB ASSY BA	1	889.70	25.00	667.27
0005	04-01-0302-2269-G	PRIG4 ORNAMENT SUB-ASSY B	1	45.80	25.00	34.35
0006	04-01-0302-2270-G	PRIG4 PLATE-BACK DOOR NAM	1	52.30	25.00	39.22
0007	04-01-0302-2271-G	PRIG4 PLATE-BACK DOOR NAM	1	52.30	25.00	39.22
0008	28-01-0302-2013-A	PRIVC REAR BONNET APP TAX	1	40.00	2.50-	40.00
0009	28-01-0302-2015-A	PRIVC REAR BONNET COMFORT	1	30.00	0.25	30.00
0010	28-01-0302-0006-A	PRIVC REAR BOOT 65521111	1	30.00	0.03-	30.00
0011	04-01-0302-2282-G	PRIG4 COVER REAR BUMPER	1	458.60	25.00	343.95
0012	04-01-0302-2288-G	PRIG4 REINFORCEMENT SUB-A	1	318.80	25.00	239.10
0013	04-01-0302-2287-G	PRIG4 GUARD-REAR BUMPER C	1	552.60	25.00	414.45

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305137255
 REGN NO : SH 8308T
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(C
 DATE OF REGN : 30.05.2017
 DATE/TIME IN : 02.04.2018 07:50
 ACCIDENT DATE : 02.04.2018

JOB / PARTS DESCRIPTION		QTY IND UNIT-PRICE DISC% AMOUNT			
0014 04-01-0302-2965-G	PRIG4 FILLER-REAR BUMPER	1	167.60	25.00	125.70
0015 04-01-0302-2267-G	PRIVC BUMPER PIECE	10	22.00	25.00	16.50
0016 04-01-0302-0585-G	PRIG4 LENS & BODY RR COMB	1	548.40	25.00	411.30
0017 04-01-0302-0795-G	PRIG4 LENS AND BODY REAR	1	557.90	25.00	418.42
0018 04-01-0302-2383-G	PRIG4 PANEL SUBASSY BODY	1	602.10	25.00	451.57
0019 09-01-0302-2005-A	PRIG4 REVERSE SENSOR ASSY	1	135.70	2.50-	135.70
0020 05-01-0199-0032-A	(ALL)WINDSCREEN AHESIVE-3	2	46.00	0.25	46.00
0021 04-01-0302-3930-G	PRIG4 COVER REAR COMBINAT	1	65.70	25.00	49.27
SUB-TOTAL :					5,931.71

JOB NATURE

020-05 REAR BUMPER ADVERTISEMENT 50.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 05.04.2018

Time: 15:40:48

REPAIR ESTIMATE

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305137255
REGN NO : SH 8308T
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 30.05.2017
DATE/TIME IN : 02.04.2018 07:50
ACCIDENT DATE : 02.04.2018

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 L	PANEL BEATING rear	600.00				
2 23-502	SPRAYPAINT ON AFFECTED AREA	600.00				
0003 17-01	CHECK ALL LIGHTING	20.00				
0004 20-00	TUFF COAT ON AFFECTED PARTS.	20.00				
0005 20-204	REMOVE/REFIX UPHOLSTERY ASST REPAIR	50.00				
0006 20-06-210R	REMOVE & REPLACE REAR W/SCREEN.	10.00		100.00		
0007 20-22	REMOVE/REFIX REVERSE SENSOR	20.00				
SUB-TOTAL						: 1,370.00
TOTAL						: 7,301.71

MVA NAME & SIGNATURE

TE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE

DATE :

[illegible]

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305137255
Date : 03/04/18

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK
Attn : KALVIN
Vehicle Reg No. : SH 8308T

Fax :


02/04/18


The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SKB4888M
2. The finalized amount shall be:

(a) Spare Parts after List discount	<u>\$5,931.75</u>
(b) Labour Charges	<u>\$1460.00</u>
Total for Part-By-Part Repair Cost	<u>\$7391.75</u>
(c.) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less:	
Final Lumpsum Repair cost	
3. Estimated normal period for repairs: 4 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 
Name : CHIANG
Tel : 62148314
Fax : 65468156

Signature : 
Name : Kalvin
Date : 9/4/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:



Thatcham escribe

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18006015/K1vbn2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 13-04-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 4888M	Veh. Inspected	SH 8308T
Policy No.	5097190527	Coverage (\$)	0.00
Claim No.	MT/0989219-002	Excess (\$)	0.00
Assign From		Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKB3FU803557283	Colour	BLUE
Odometer	169735	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	7 mm
L/H Front Tyre	195/65 R15	WEST LAKE	7 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	7 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/04/2018	Inspection Date	02/04/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 8308T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TRUNK LID COVER	BENT	922.50	922.50
1	REAR TRUNK LID LOCK	SERVICEABLE	447.70	-
1	REAR TRUNK LID RUBBER	SERVICEABLE	357.00	-
1	REAR TRUNK LID GLASS (BLACK COLOR)	CRACKED	721.30	721.30
1	BOARD ASSY, BACK DOOR TRIM	SERVICEABLE	246.90	-
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE	CRACKED	889.70	889.70
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER RE-INFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER UNDER COVER	CRACKED	552.60	552.60
1	REAR BUMPER SIDE RETAINER	SERVICEABLE	112.70	-
1	REAR BUMPER SPONGE	NOT NECESSARY	143.40	-
1	REAR BUMPER UNDER SIDE COVER (RH)	CRACKED	167.60	167.60
1	REAR BUMPER UNDER SIDE CENTRE COVER	SERVICEABLE	552.60	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	RETAINER, REAR BUMPER, SIDE, RH	SERVICEABLE	94.80	-
1	SEAL, REAR BUMPER SIDE, RH	SERVICEABLE	148.40	-
1	TAIL LAMP ASSY (UPPER), RH	CRACKED	557.90	557.90
1	TAIL LAMP ASSY (LOWER), RH	CRACKED	548.40	548.40
1	REAR END PANEL	DENTED	602.10	602.10
1	REAR END PANEL GARNISH	SERVICEABLE	121.60	-
1	REAR WINDSCREEN GLASS	NECESSARY	1,555.80	1,555.80
1	REAR WINDSCREEN GLASS MOULDING	NOT NECESSARY	208.60	-
1	HYBRID EMBLEM	NECESSARY	52.30	52.30
1	PRIUS EMBLEM	NECESSARY	52.30	52.30
1	TOYOTA EMBLEM	NECESSARY	45.80	45.80
1	COVER REAR COMBINATION	NECESSARY	65.70	65.70
	LESS 25% DISCOUNT		-2,491.77	-1,883.35
			7,475.33	5,650.05
SPECIAL NETT ITEMS				
1	REAR NO PLATE WITH TRIM COVER (SN)	SERVICEABLE	100.00	-

Report Ref No. NS/INC18006015/K1vbn2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TRUNK LID APPS STICKER (SN)	NECESSARY	40.00	40.00
1	REAR TRUNK LID COMFORT & TEL NO STICKER (SN)	NECESSARY	60.00	60.00
1	REAR BUMPER REVERSE SENSOR (SN)	SHORTED	135.70	135.70
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	46.00	46.00
			431.70	331.70
	LABOUR			
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,190.00	790.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		800.00	620.00
			1,990.00	1,410.00
GRAND TOTAL			9,897.03	7,391.75
RECOMMENDED COST OF REPAIRS (CONFIRMED)				7,391.75

Report Ref No. NS/INC18006015/K1vbn2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.