

INS. CASE OWNER:

Lemuel

CC³ / AIG 1800 6018 / Swa352

LKK:

IDAC:

Surveyor:

Ymk

DOI:

ASSIGNMENT

28/3/18

Date / Time:

28/3/18

Registered in Merimen:

5-4-18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLG 48312

Name of Insured:

Sim Pui Pen

Insured Tel No.:

HP:

94757708

Excess Sec II :SS

D.O.A:

28/03/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

443359279056

Policy No.:

210475785

Make / Model:

7. WSH

Place of Accident:

BURST TIRE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SHF 155K



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMP7. W



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/4

WMA

SHF 155K - X

SLG 48312, CS/BU17072201/TH607, 05/11/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

7/11/18 W

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

11/4/18

called O2, No response

12/4/18

called O2, No response

17/4/18

called O2, No response

17-04-18

send letter to O2

RECEIVED 16 MAY 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Lee Gef

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. : 27.

If NO or B 28, Ass. Lia :

Repair Cost:

SS 2429.47

Loss of Rental (LOR):

SS 662.09 (3.5 days) x 120.38

Loss of Use (LOU):

SS 275.00 (50 x 3.5 days)

Loss of Income (LOI):

SS (\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

SS 7.00

Medical:

SS

1) Claim status: Normal/Reject/Private Settle

Disbursement:

SS

(e.g. Tow/ Independent)

2) Report Format:

Legal Cost

SS

3) Survey fee:

Total:

SS 3373.56

Global Sum SS: 2350.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 3350.00

Name 1:

SMART Taxis Pte Ltd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT 16/5/18

REF:

ASSIGNMENT

From:

Date:

Veh No:

S4F 155K

Yr Regn:

28/11/2017

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Toyota Prius 9

C.C. 1798

at Workshop m/s

Colour

Platinum

A/C: Insured / Std / NI / NA

of

Sp. Reading

41751

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

JTDK153F4303575335

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

7

mm

R/Bal.

7

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

7

mm

L/Bal.

7

mm

Est. Repairs:

3

days

Res.: Yes or No

D.O.A.

28/3/18

D.O.I.

28/3/18

Lum Sum:

18.2

%

3 Val.: Yes or No

Survey held at

SMART

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/5/18

Confirm I.B. 2 \$2429.47 with 3 working days LKK

TAX/03/18/2131

AIG.

(Red - \$5977.26
71%)

Date/Time, File Pass to?

☐

Prel. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation

) S - RS - SI

) Photos

) Others

Report Format:

Lump Sum / I.B.1: (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18006018/Swa3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 02-04-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh. SLE 4831Z	Veh. Inspected	SHF 155K
	Policy No.	Coverage (\$)	0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	02/04/2018
2. Vehicle Particulars & Condition			
	Make & Model	c.c	0
	Engine No. HIDDEN	Year of Reg.	
	Chassis No.	Colour	
	Odometer -	Steering	
	Brakes	Modification	
	General		
3. Conditions of Tyres			
	Size	Make	Balance
	R/H Front Tyre		mm
	L/H Front Tyre		mm
	R/H Rear Tyre		mm
	L/H Rear Tyre		mm
4. Description of Damages			
5. General Information			
	Accident Date 28/03/2018	Inspection Date	28/03/2018
	Survey held at SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			


W
2-4-18 / 12:16
2-4-18 / 16:16

SMRT Accident Vehicle Repair Estimates

28-3-18 / 16:26

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF155K
Ref. No : TAX/03/18/2131
Reg. Date : 28/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : LAU WEI SUN LAWRENCE
Type of Accident : HEAD TO REAR
Date / Time of Accident : 28/03/2018 09:30:00 AM
Accident Reported Date / Time : 28/03/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024095263
Special Instruction to ARC, if any :
SLF4831Z ALG r/p
BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR SEBASTIAN (LKK)
& Email : sebastianyeang @lkkauto.com HP:90036121
Prepared Date : 28/03/2018 10:32:09 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

Date : 28-3-18

2nd witness

Date :

41751
1 1 3 1
4 2 4 1

3/4/18 12.00 reject

RR End Panel dent 15:23 pass

Supplementary

to Refer to the Supplementary part 11

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

3-4-2018

Vehicle Return Time:

11:00 am

SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303575335

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,014.00	400.00
Total Spray Painting Charges	1,476.00	550.00
Total Material Charges	2,788.84	1,399.47
Other Charges	940.00	80.00
TOTAL	6,218.84	2,429.47
Lum Sum Total	0.00	0.00
No. of Repair Days	6.00	3.00 /
Prepared / Adjusted By		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	28/03/2018 03:34:33 PM	28/03/2018 04:16:29 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/03/2018 03:34:23 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1804-0257

Invoice No :

Quotation Date : 11/4

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	400.00 /
Total Labour	1,014.00	400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	50.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY REAR PANEL	180.00	0.00
Total Spray Painting & Panel Beating	1,476.00	550.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	50.00 /
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	940.00	80.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to change
- Third party labour is not included in the quotation
- No legal modification to be made
- SCV (Remedial) is not included in the quotation
- Is subject to final approval from the insurer

Acknowledged by Repairer:
Signature: _____
Date: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to change
- Third party labour is not included in the quotation
- No legal modification to be made
- SCV (Remedial) is not included in the quotation
- Is subject to final approval from the insurer

Acknowledged by Repairer:
Signature: _____
Date: _____

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No	Defect
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace	No	NK
5246247030			PAD, RR BUMPER, RH & LH, 1	0	3.80	25.00	0.00	Replace	Not given	No	X
5246247020			PAD, RR BUMPER, RH & LH, 2	0	3.80	25.00	0.00	Replace	Not given	No	X
5246247010			PAD, RR BUMPER, RH & LH, 3	0	3.80	25.00	0.00	Replace	Not given	No	X
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Check	No	X
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace S	No	Defect
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace S	No	Defect
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Check	No	X
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Check	No	X
5256647900			FILLER, RR BUMPER, LH	0	119.90	25.00	0.00	Replace	Not given	No	X
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.92	Replace	Replace S	No	Defect
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.63	Replace	Check	No	X
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.53	Replace	Check	No	X
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace	No	Defect
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Check	No	X
5839947030			COVER, REAR FLOOR UNDER, LH	1	234.30	25.00	175.73	Replace	Check	No	X
5839847050			COVER, REAR FLOOR UNDER, RH	1	169.50	25.00	127.13	Replace	Check	No	X
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Check	No	X
9046717026A0			CLIP, FLOOR UNDER COVER, NO.1	6	2.60	25.00	11.70	Replace	Check	No	X
9046717027C0			CLIP, FLOOR UNDER COVER, NO.2	6	3.20	25.00	14.40	Replace	Check	No	X
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	100.00	0.00	Replace	Repair	No	R
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	100.00	0.00	Replace	Repair	No	R
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	0	27.90	25.00	0.00	Replace	Not given	No	X
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	0	29.70	25.00	0.00	Replace	Not given	No	X
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	0	19.70	25.00	0.00	Replace	Not given	No	X

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7557447040			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, LH	0	29.90	25.00	0.00	Replace	Not given	No X
7557347110			TAIL GATE MOULDING LOWER GLASS, BACK DOOR, RH	0	29.90	25.00	0.00	Replace	Not given	No X
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	0	24.90	25.00	0.00	Replace	Not given	No X
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	0	452.10	10.00	0.00	Replace	Not given	No X
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No /
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No /
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No /
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No /
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No /
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Check	No X
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Check	No X
5246147010			PAD, RR BUMPER, CTR	3	2.20 <i>6.60</i>	25.00	4.95	Replace	Check	No X
TOTAL MATERIALS							2,788.87	1,399.48		
TOTAL MATERIALS(Discounted)							2,788.84	1,399.47		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1399.47 /
 + 400.00 /
 + 630.00 /

 2429.47 /

Submitted
 23/4/18

6601.80

SMRT Accident Vehicle Repair Estimates

A16.

C117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF155K
 Ref. No : TAX/03/18/2131
 Reg. Date : 28/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LAU WEI SUN LAWRENCE
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 28/03/2018 09:30:00 AM
 Accident Reported Date / Time : 28/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095263
 Special Instruction to ARC, if any :
 SLF4831Z
 Prepared Date : 28/03/2018 10:32:09 AM



Sebastian
 28/3/18
 - Part by part repair
 - Question Mark Item Photo
 - Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303575335

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,476.00	0.00
Total Material Charges	: 4,921.73	4,921.73
Other Charges	: 940.00	0.00
TOTAL	: 8,351.73	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 28/03/2018 03:34:33 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/03/2018 03:34:23 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 ✕
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 50
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	1,476.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ✕
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 ✕
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 ✕
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 ✕
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 ✕
TO WASH AND VACUUM	60.00	0.00 ✕
Total Other Costs	940.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓	No Deform
5216116010			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓	No N/A
5246247030			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace X	No
5246247020			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace X	No
5246247010			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace X	No
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace ?	No
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
8999730100			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace ?	No
8218347020			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Replace ?	No
5256647900			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace X	No
5256647900			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace R	No
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace ?	No
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace ?	No
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓	No Deform
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace ?	No
5839947030			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.72	Replace	Replace ?	No
5839847050			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.12	Replace	Replace ?	No
6625947010			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace ?	No
9046717026A0			CLIP , FLOOR UNDER COVER , NO.1	6	2.60	25.00	11.70	Replace	Replace ?	No
9046717027C0			CLIP , FLOOR UNDER COVER , NO.2	6	3.20	25.00	14.40	Replace	Replace ?	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace R	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace R	No
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace X	No
7557147010			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace X	No
7557547051			TAIL GATE MOULDING LOWER GLASS , BACK DOOR	1	19.70	25.00	14.77	Replace	Replace X	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
7557447040			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , LH	1	29.90	25.00	22.42	Replace	Replace X	No
7557347110			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , RH	1	29.90	25.00	22.42	Replace	Replace X	No
	COMMO N		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace X	No
6943052050			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace X	No
6935047050			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace X	No
7544147090			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
7544247130			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace ✓ NEC	No
7540348010			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace ✓ NEC	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ✓ NEC	No
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ✓ NEC	No
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace ✓	No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ✓	No
5246147010			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace ✓	No
TOTAL MATERIALS								4,921.81	4,921.73	
TOTAL MATERIALS(Discounted)								4,921.73	4,921.73	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Mar 2018 Edit Reg		28 Mar 2018 00:00 Edit Adj Rpt	S\$2,429.47 Edit Estimates	S\$2,429.47 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	SIM PEI FEN , ID: S8021944Z, Tel: +6594752708		
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHF155K	Date of Loss:	28/03/2018 09:00 - :59 [4 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / 4433592790SG	Policy/Cover Note No.:	2100475785 (Comprehensive)
Vehicle Reg. No. (Insured):	SLE4831Z	Policy No. (Claimant):	D-17087562MFSH
		Excess:	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 16/04/2018]		
Driver/Custodian (Insured):	SIM PEI FEN (), NRIC: S8021944Z, Tel: +6594752708		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHF155K (4433592790SG)**

[SLE4831Z]

TP

SMRT TAXIS PTE LTD

Mar 28 2018 9:00AM

[SIM PEI FEN]

SMRT Automotive Services Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit	

Assessment Reports				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	06/04/18 11:44	Accident Statement From:OD - Reg. No: SLE4831Z, Claimant: SIM PEI FEN	1	Load HTM	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/04/18 10:15	General View	1	Load JPG	☒
2	23/04/18 10:15	General View	1	Load JPG	☒
3	23/04/18 10:15	General View	1	Load JPG	☒
4	23/04/18 10:15	General View	1	Load JPG	☒
5	23/04/18 10:15	General View	1	Load JPG	☒
6	23/04/18 10:15	General View	1	Load JPG	☒
7	23/04/18 10:15	General View	1	Load JPG	☒
8	23/04/18 10:15	General View	1	Load JPG	☒
9	23/04/18 10:15	General View	1	Load JPG	☒
10	23/04/18 10:15	General View	1	Load JPG	☒
11	23/04/18 10:15	General View	1	Load JPG	☒
12	23/04/18 10:15	General View	1	Load JPG	☒
13	23/04/18 10:15	General View	1	Load JPG	☒
14	23/04/18 10:15	General View	1	Load JPG	☒
15	23/04/18 10:15	General View	1	Load JPG	☒
16	23/04/18 10:15	General View	1	Load JPG	☒
17	23/04/18 10:15	General View	1	Load JPG	☒
18	23/04/18 10:15	General View	1	Load JPG	☒
19	23/04/18 10:15	General View	1	Load JPG	☒
20	23/04/18 10:15	General View	1	Load JPG	☒
21	23/04/18 10:15	General View	1	Load JPG	☒
22	23/04/18 10:15	General View	1	Load JPG	☒
23	23/04/18 10:15	General View	1	Load JPG	☒
24	23/04/18 10:15	General View	1	Load JPG	☒
25	23/04/18 10:15	General View	1	Load JPG	☒
26	23/04/18 10:15	General View	1	Load JPG	☒
27	23/04/18 10:15	General View	1	Load JPG	☒
28	23/04/18 10:15	General View	1	Load JPG	☒

Letters/Correspondences			1 per page ▼	✓
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
29	23/04/18 10:15	General View	 Load JPG	✓
30	23/04/18 10:15	General View	 Load JPG	✓
31	23/04/18 10:15	General View	 Load JPG	✓
32	23/04/18 10:15	General View	 Load JPG	✓
33	23/04/18 10:15	General View	 Load JPG	✓
34	23/04/18 10:15	General View	 Load JPG	✓
35	23/04/18 10:15	General View	 Load JPG	✓
36	23/04/18 10:15	General View	 Load JPG	✓
37	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
38	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
39	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
40	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
41	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
42	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
43	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
44	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
45	23/04/18 10:15	Reinspection Photo	 Load JPG	✓
46	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
47	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
48	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
49	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
50	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
51	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
52	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
53	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
54	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
55	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
56	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
57	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
58	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
59	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
60	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
61	23/04/18 10:15	BEFORE PAINT	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 18:23	TP GIA REPORT	 Load PDF	
2	09/04/18 10:20	TP ESTIMATE - MARKED	 Load PDF	
3	21/05/18 10:53	AUTHORISATION TO ACT	 Load PDF	
4	21/05/18 10:53	LETTER TO OI	 Load PDF	
5	21/05/18 10:53	LTA SEARCH	 Load PDF	
6	21/05/18 10:53	RELEASE VOUCHER	 Load PDF	
7	21/05/18 10:53	RENTAL RECEIPT	 Load PDF	
8	21/05/18 10:53	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLE4831Z (Insd veh)	Model:	TOYOTA PRIUS 1.8 HYBRID CVT
	SHF155K (TP veh)		(A)
Date of Accident:	28/03/2018		

Global Sum Settlement	:	[X]	Yes	[]	No	
Repair Estimate	:	\$				9,601.80
Final Repair Cost	:	\$				3,350.00
Loss of Use	:	\$				5.50 days at \$50.00 per day
Rental (if any)	:	\$				5.5 days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (GLOBAL SUM)	:	\$				3,350.00

Is Third Party Workshop GIA Registered?	[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)			
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____			
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.					
Remarks _____					

Payment Instruction: Payee's Breakdown

1)	SMRT TAXIS PTE LTD	:	\$	3,350.00
2)		:	\$	
3)		:	\$	
4)		:	\$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

21 May
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18006018/SWA3S2
Date: 21/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100475785
Claimant Vehicle No: SHF155K Insured Vehicle No: SLE4831Z
Date of Loss: 28/03/2018 Nature of Claim: TP Claim No: 4433592790SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHF155K
Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS108741
Reg. Date: 28/11/2017 (Man. Year: 2017) Chassis No: JTDKB3FU303575335
Colour: Maroon Odometer: 41751 km
Engine Capacity: 1798 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,171.80	1,399.47	4,772.33	77.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,430.00	1,030.00	2,400.00	69.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	9,601.80	2,429.47	7,172.33	74.70
+ Loss of Use (5.5 x S\$50.00/day) (S\$)		275.00		
+ Car Rental (5.5 x S\$120.38/day) (S\$)		662.09		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,373.56		
Global Sum Settlement (S\$)		3,350.00		

INSPECTION

Date of Assignment: 28/03/2018
Date Inspected: 28/03/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705
Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VIVIAN LAU PEI FENG

5/21/2018

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.92 F
2	1	*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
3	1	*REAR BUMPER REINFORCEMENT (DISC 25%)	Dented	318.80 F	*239.10 F
4	1	*FILLER, RR BUMPER RH (DISC 25%)	Cracked	119.90 F	*89.92 F
5	1	*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.72 F
6	1	*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.22 F
7	1	*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (DISC 25%)	Necessary	52.30 F	*39.22 F
8	1	*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	46.30 F	*34.72 F
9	1	*SENSOR REVERSE (SN)	Damaged	180.00 F	*180.00 F
10	1	*SMRT LOGO (SN)	Necessary	7.80 F	*7.80 F
11	1	*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
12	1	*PAD, RR BUMPER, RH & LH, 1	Not Necessary	3.80 F	*- F
13	1	*PAD, RR BUMPER, RH & LH, 2	Not Necessary	3.80 F	*- F
14	1	*PAD, RR BUMPER, RH & LH, 3	Not Necessary	3.80 F	*- F
15	2	*SEAL, RR BUMPER ARM, RH & LH	Not Necessary	22.00 F	*- F
16	1	*ANTENNA, ELECTRICAL KEY	Not Necessary	60.30 F	*- F
17	1	*WIRE, LUGGAGE ROOM	Not Necessary	143.50 F	*- F
18	1	*FILLER, RR BUMPER LH	Not Necessary	119.90 F	*- F
19	1	*RETAINER, RR BUMPER, LH	Not Necessary	111.50 F	*- F
20	1	*RETAINER, RR BUMPER, RH	Not Necessary	112.70 F	*- F
21	1	*COVER, GUARD RR BUMPER LOWER	Not Necessary	14.80 F	*- F
22	1	*COVER, REAR FLOOR UNDER, LH	Not Necessary	234.30 F	*- F
23	1	*COVER, REAR FLOOR UNDER, RH	Not Necessary	169.50 F	*- F
24	1	*COVER, REAR FLOOR UNDER CENTER	Not Necessary	222.60 F	*- F
25	6	*CLIP, FLOOR UNDER COVER, NO.1	Not Necessary	15.60 F	*- F
26	6	*CLIP, FLOOR UNDER COVER, NO.2	Not Necessary	19.20 F	*- F
27	1	*TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	Not Necessary	27.90 F	*- F
28	1	*TAIL GATE MOULDING GLASS, BACK DOOR	Not Necessary	29.70 F	*- F
29	1	*TAIL GATE MOULDING LOWER GLASS, BACK DOOR	Not Necessary	19.70 F	*- F
30	1	*TAIL GATE MOULDING LOWER GLASS, BACK DOOR LH	Not Necessary	29.90 F	*- F
31	1	*TAIL GATE MOULDING LOWER GLASS, BACK DOOR RH	Not Necessary	29.90 F	*- F
32	1	*SEALANT W/SCREEN	Not Necessary	37.00 F	*- F
33	1	*TAIL GATE STRIKER ASSY, BACK DOOR	Not Necessary	24.90 F	*- F
34	1	*TAIL GATE LOCK ASSY, BACK DOOR	Not Necessary	425.10 F	*- F
35	1	*END PANEL SUB-ASSY, BODY LOWER BACK	Not Necessary	629.80 F	*- F
36	1	*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
37	3	*PAD, RR BUMPER, CTR	Not Necessary	6.60 F	*- F
38	1	*TAIL GATE PANEL SUB-ASSY, BACK DOOR	Repair	929.60 F	*- F
39	1	*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	Repair	891.20 F	*- F

F=Franchise part.

Total Parts (\$\$) 6,171.80 1,399.47

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	1,014.00	400.00
2	SPRAY PAINT.	New	1,476.00	550.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	0.00
4	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	0.00
5	TO REMOVE AND REFIX REAR WINDSCREEN.	New	240.00	0.00
6	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
7	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
8	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	50.00
9	TO REPLACE SUNDRY PARTS.	New	100.00	0.00
10	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (\$\$)			3,430.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >