

SMRT Accident Vehicle Repair Estimates

Ala.

G117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF155K
 Ref. No : TAX/03/18/2131
 Reg. Date : 28/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LAU WEI SUN LAWRENCE
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 28/03/2018 09:30:00 AM
 Accident Reported Date / Time : 28/03/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095263
 Special Instruction to ARC,if any :
 SLF4831Z
 Prepared Date : 28/03/2018 10:32:09 AM



Sebastian
 28/3/18.

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKB3FU303575335

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,476.00	0.00
Total Material Charges	: 4,921.73	4,921.73
Other Charges	: 940.00	0.00
TOTAL	: 8,351.73	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	3 days
Arc / Surveyor Sign Off Date	: 28/03/2018 03:34:33 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/03/2018 03:34:23 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 400
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 ✕
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 50
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	1,476.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 ✕
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 ✕
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 ✕
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 ✕
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 ✕
TO WASH AND VACUUM	60.00	0.00 ✕
Total Other Costs	940.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
21594793			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓	No Defect
21611600			CLIPS PIECE, FRT & RR BUMPER	10	1.50	25.00	11.25	Replace	Replace ✓	No Defect
24624700			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace X	No
24624700			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace X	No
24624700			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace X	No
21914700			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace ?	No
20234700			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ?	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
99973010			ANTENNA, ELECTRICAL KEY	1	60.30	10.00	54.27	Replace	Replace ?	No
21834700			WIRE, LUGGAGE ROOM	1	143.50	10.00	129.15	Replace	Replace ?	No
25664790			FILLER, RR BUMPER , LH	1	119.90	25.00	89.92	Replace	Replace X	No
25654790			FILLER, RR BUMPER , RH	1	119.90	25.00	89.92	Replace	Replace R	No
25764700			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.62	Replace	Replace ?	No
25754700			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.52	Replace	Replace ?	No
24534700			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace ✓	No Defect
21694700			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace ?	No
83994700			COVER, REAR FLOOR UNDER , LH	1	234.30	25.00	175.72	Replace	Replace ?	No
83984700			COVER, REAR FLOOR UNDER , RH	1	169.50	25.00	127.12	Replace	Replace ?	No
62594700			COVER, REAR FLOOR UNDER CENTER	1	222.60	25.00	166.95	Replace	Replace ?	No
046717006A0			CLIP , FLOOR UNDER COVER , NO.1	6	2.60	25.00	11.70	Replace	Replace ?	No
046717007C0			CLIP , FLOOR UNDER COVER , NO.2	6	3.20	25.00	14.40	Replace	Replace ?	No
70054740			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	25.00	697.20	Replace	Replace R	No
68014710A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	25.00	668.40	Replace	Replace R	No
61175010			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	2	27.90	25.00	41.85	Replace	Replace X	No
55714700			TAIL GATE MOULDING GLASS, BACK DOOR	1	29.70	25.00	22.27	Replace	Replace X	No
5575470051			TAIL GATE MOULDING LOWER GLASS , BACK DOOR	1	19.70	25.00	14.77	Replace	Replace X	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
75574470 10			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , LH	1	29.90	25.00	22.42	Replace	Replace X	No
75573471 10			TAIL GATE MOULDING LOWER GLASS , BACK DOOR , RH	1	29.90	25.00	22.42	Replace	Replace X	No
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace X	No
89430520 10			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	25.00	18.67	Replace	Replace X	No
89350470 10			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	10.00	406.89	Replace	Replace X	No
75441470 10			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
									✓ NEC	
75442471 10			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	25.00	39.22	Replace	Replace	No
									✓ NEC	
75403480 10			EMBLEM SUB-ASSY REAR	1	46.30	25.00	34.72	Replace	Replace	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
8307470 10			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	25.00	472.35	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No
2461470 0			PAD, RR BUMPER, CTR	3	2.20	25.00	4.95	Replace	Replace	No
TOTAL MATERIALS								4,921.81	4,921.73	
TOTAL MATERIALS(Discounted)								4,921.73	4,921.73	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									