

JIN AUTO SERVICES PTE LTD

Blk 14 #01-412 Defu Lane 10
Singapore 539195
Tel:62898126 Fax :62870590

Your ref :
Our Ref :

Date: 2/4/2018

DEAR SIR/MADAM

ESTIMATED REPAIR COST FOR SFL7715R HONDA STREAM

1	1 PC	GRILLE	SCR	\$	235.90	✓
2	1 PC	Front bumper	m/R	\$	635.60	✓
3	1 PC	Front bumper clip (1 set)	all	\$	30.00	✓
4	1 PC	Front bumper reinforcement	R	\$	222.40	X
5	2 PCS	Front Bumper Beam	n1	\$	89.80	X
6	2 PCS	Front bumper side retainer	n1	\$	38.40	X
7	1 PC	FRONT LH HEADLAMP	SCR	\$	774.50	✓
				\$	2,026.60	
				less 20%	\$	(405.32)
				\$	1,621.28	
8		SPRAY PAINTING FRONT PORTIONS		\$	280.00	200
10		LABOUR CHARGE TO REMOVE AND RENEW FRONT PARTS		\$	350.00	200
9		CHECK WIRING		\$	35.00	20
				\$	2,286.28	

not Allowed
2/5/18
23/4/18

P-1676
1340.00
1760.8
1408.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: