

ASS. REC. BY: PRS REF: CS/FWD17010765/0906/1 Special Instructions: _____

Surveyor: menmen ang ASSIGNMENT (Office)

From (Person): Clara Li of FWD Date/Time: 02042018

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJT9882M Insured: EW8229A

at Workshop m/s: N-51 Automotive Tel: 68420051

of: 2 Kaki Bukit Ave 2 #01-17/18

Policy No: PNDV2017-00002000 Claim No: 1201700003109

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 116/2017

(Client's Record)


CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement: _____

Date/Time: 26/2017 2:57PM Person Contacted: Hui Lin Vehicle: EX-OUT

Date/Time	Action/Instruction (A) Estimate
	SJT9882M - NA / 26/17 616694 / 13 RA: 116/2017
	EW8229A - 26/17 16069488 / Kyp 392 RA: 27/2/2016
	Survey: 26/2017, dismantle: 5/6/2017, after repair: 8/6/2017

\$4850 17 Days. (Red to 2750, 36%)

(or sum 17/5/18



Note: MV: \$12,500 (est)
 VIA: \$7341
 NV: \$5159.

REF: FWD

ASSIGNMENT

(2017)

From: Date: 26/2/17

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: ST 9882M

at Workshop m/s: K-51 Automotive

of:

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$11K - \$12.5K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up'

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

Veh No: ST 9882M Yr Regn: 27 Nov 2007

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vios cc 1497

Colour: Silver A.C: Insured / Std / NI / NA

Sp. Reading: 148144 T.Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053HY930.50 24804

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55 R15

R: 11

BS: ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal: 5 mm R/Bal: 5 mm

L/Bal: 5 mm L/Bal: 5 mm

D.O.A.

D.O.I. 02-06-17

Survey held at: W/S 4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The ☒ Chassis frame / Body Structure affected due to collision.

Date/Time. File Pass to?

1) 15/6-2017

Date/Time. File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

)

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: PPS

Lump Sum / I.B.I: (\$)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD17010765/Gqb-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 03-04-2018



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EW 8229A	Veh. Inspected	SJT 9882M
Policy No.		Coverage (\$)	0.00
Claim No.	1201700003109	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/06/2017	Inspection Date	03/04/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: clara.li@fwd.com
Sent: Monday, 2 April, 2018 7:11 PM
To: admin-d@lkkauto.com; assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com
Subject: [Paper Survey] SJT9882M & EW8229A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD CLAIM REF: 1201700003109)
Attachments: TP Survey Report & Photos.pdf
Importance: High

Hi LKK team,

Please refer to the attached survey report & photographs and conduct a paper resurvey on an urgent basis.

Kindly let us have the paper resurvey report soonest possible via email.

Thank you.

Kind Regards

Clara Li

Senior Executive, Claims

FWD Singapore Pte. Ltd.

6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986

T (65) 6727 5722

E clara.li@fwd.com

W fwd.com.sg



	Endowment Plan Get the biggest guaranteed return for a 3 year plan available online. Limited time offer!		2.02% p.a. fwd.com.sg save now
--	--	--	--

From: Ashley Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Friday, 2 June, 2017 4:25 PM

To: Belliana - SGUser; assignments@lkkauto.com; sur@lkkauto.com; admin-a@lkkauto.com

Subject: RE: SJT9882M & EW8229A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD CLAIM REF: 1201700003109)

Dear Belliana,

Received with thanks.

Best Regards,

Ashley Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: belliana@fwd.com [<mailto:belliana@fwd.com>]

Sent: Friday, 2 June, 2017 4:18 PM

To: assignments@lkkauto.com; sur@lkkauto.com; admin-d@lkkauto.com; admin-a@lkkauto.com

Subject: FW: SJT9882M & EW8229A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD CLAIM REF: 1201700003109)

Hi LKK Team

FYA as attached.

Thanks

Belliana

Assistant Manager, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01
Suntec Tower 4, Singapore 038986
E belliana@fwd.com

With FWD, you get to keep your
50% NCD for Life. No matter what.

get a quick quote now »



F
ins

From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Friday, June 02, 2017 4:00 PM

To: Belliana - SGUser <belliana@fwd.com>


Cc: CRM and all customer engagements - SG Common <service.sg@fwd.com>; SG Corporate Contact <contact.sg@fwd.com>

Subject: Re: SJT9882M & EW8229A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS (FWD CLAIM REF: 1201700003109)

Dear Sir/Madam,

Please see attached.

Regards,
Melody Chin
N-51 Automotive Pte Ltd
Office : 6842 0051
Fax : 6741 0510
www.n51.com.sg



On Fri, Jun 2, 2017 at 2:46 PM, <belliana@fwd.com> wrote:

WITHOUT PREJUDICE

Dear Sir/ Madam

We regret that we are objecting to your proposed list of surveyors.

We will be appointing, M/s **LKK AUTO CONSULTANTS PTE LTD**, to conduct the pre-repair survey (PRS) on your client's vehicle, SJT9882M. We seek your cooperation to inform your client's workshop to arrange the vehicle readily for dismantling with repair estimates during the pre-repair survey.

If there is a change in your client's workshop, please inform us soon. We reserve our rights for re-inspection.

Regards

Belliana

Assistant Manager, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01

Suntec Tower 4, Singapore 038986

E belliana@fwd.com

With FWD, you get to keep your
50% NCD for Life. No matter what.
get a quick quote now >



P
in

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Friday, June 02, 2017 12:08 PM

To: Belliana - SGUser <belliana@fwd.com>

Cc: CRM and all customer engagements - SG Common <service.sg@fwd.com>; SG Corporate Contact
<contact.sg@fwd.com>

Subject: Re: SJT9882M & EW8229A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3
WORKING DAYS (FWD CLAIM REF: 1201700003109)

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



On Fri, Jun 2, 2017 at 11:43 AM, <belliana@fwd.com> wrote:

Without Prejudice

Dear Sir/ Madam

We refer to your email dated 1 June 2017 of the PRI Notice of your client's vehicle SJT9882M.

Please find our panel surveyors as follows: -

1. LKK AUTO CONSULTANTS PTE LTD
2. INFINITI APPRAISAL SERVICE
3. AJAX INSPECTION SERVICES PTE LTD

If you are not agreeable to any of the above, we reserve our rights to request for pre-repair inspection of your client's vehicle.

We look forward to receiving your reply.

Thank you.

Regards

Belliana

Assistant Manager, Claims



FWD Singapore Pte Ltd

6 Temasek Boulevard, #18-01

Suntec Tower 4, Singapore 038986

E belliana@fwd.com

With FWD, you get to keep your
50% NCD for Life. No matter what.

get a quick quote now »



From: Chin Hui Xin [<mailto:huixin@n51.com.sg>]

Sent: Thursday, 1 June, 2017 5:53 PM

To: SG Corporate Contact

Subject: SJT9882M & EW8229A - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,


Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/06/2017 09:11
Date Of Accident	01/06/2017 11:30
Exact Location Of Accident	OUTRAM RD TWDS TIONG BAHRU OUTSIDE SGH BLK 9
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT9882M
Insured/Policyholder	
Name Of Registered Owner	TWINCAR RENTAL
Co Reg No	53092815M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-68420051
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS
Exact Purpose for which vehicle was being used at time of accident	ON JOB
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5074126734-01
Cover Note Number	
Driver	
Name of Driver	WONG FOOK LOY (HUANG FULAI)
NRIC No	S7502064C
Date Of Birth	11/01/1975
Occupation	INDOOR
Date Of Driving Pass	25/11/2011
Driving Experience	5 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90029659
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 425 FAJAR ROAD
#02-541
Postcode 670425
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION- CHANGE/CROSS LANE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: WITH WORKSHOP
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number EW8229A
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver TAY SENG HUAT
NRIC/Passport Number
Contact Number 96803163
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLE2173C
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number 97975570
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number PC2285B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number 82090712
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name WONG FOOK LOY(HUANG FULAI)
Approximate Age
Injuries Sustain SLIGHT
Injured person in which vehicle? SJT9882M
Were seat belts worn? YES
Was injured conveyed to hospital by ambulance? NO
Address
Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer, collectively the **Personal Information**, and disclose and transfer such Personal Information to all insurers (i) who have insured vehicles involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the **Insurers**, the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purposes (i) of:
(i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims, including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the **Purposes**);
(b) all insurers (i) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents including their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

[Signature] 02/06/17

Sketch Plan #2

Describe Circumstances of the Accident

Handwritten description of the accident circumstances, including details about the vehicles involved, the location, and the sequence of events. The text is written in cursive and spans multiple lines of the form.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Signature 02/06/17

Text size + -

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 2815M

Vehicle Details

Vehicle No.: SJT9882M

Vehicle to be Exported: No

Intended De-registration
Date: 05 Jul 2017

Vehicle Make: TOYOTA

Vehicle Model: VIOS E AUTO

Primary Colour: Silver

Manufacturing Year: 2007

Engine No.: 1NZX615202

Chassis No.: MR053HY9305024804

Maximum Power Output: 80.0 kW (107 bhp)

Open Market Value: \$12,466.00

Original Registration
Date: 27 Nov 2007

First Registration Date: 27 Nov 2007

Transfer Count: 3

Actual ARF Paid: \$13,713.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry
Date: 26 Nov 2017

PARF Rebate Amount: \$6,856.00

Intended COE Rebate Details

COE Expiry Date: 26 Nov 2017

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$12,401.00

COE Rebate Amount: \$485.00

Total Rebate Amount: \$7,341.00

The information contained herein is correct as at 05 Jun 2017

OK

Land Transport Authority

Please read through the Privacy Statement, Terms of Use and Disclaimer.
Please do not use the **Back** or **Forward** buttons on your browser as this may alter the results of the transactions.
Best viewed with IE 6.0 SP3 and above, 1024 X 768 resolution
Copyright © 2017 LTA | [Privacy Statement](#) | [Terms of Use](#) | [Disclaimer](#) | [Rate the Website](#) | [Rate this e-Service](#)
Last updated on 28 May 2017 at 12:58 AM

Report No: 0595-17-N51

02 January 2018

ACCIDENT VEHICLE SURVEY REPORT

Twincar Rental
Blk 2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

Vehicle Reg No.:	SJT9882M	Odometer:	148144km
Make & Model:	Toyota Vios E Auto	Colour:	Silver
Chassis number:	MR053HY9305024804	Date of accident:	01/06/2017
Year of Regn.:	27/11/2007	Date inspected:	02/06/2017
Repairer at:	N-51 Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-18 Kaki Bukit Auto Hub Singapore 417921	Date inspected (After Repair):	08/06/2017

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	6mm/Falken	6mm/Falken	195/55R15
Rear:	5mm/Dunlop	5mm/Dunlop	195/55R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear RH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment
REAR BOOTLID WEATHERSTRIP	1	deformed	106.70	X 106.70 NN
REAR BUMPER	1	squashed	451.90	451.90
REAR BUMPER CORNER RETAINER L/R	2	necessary	204.72	204.72
REAR BUMPER RH INNER SHIELD	1	warped	181.90	181.90
REAR BUMPER RH INNER SHIELD CLIPS	3	necessary	19.50	19.50
REAR BUMPER RH REFLECTOR	1	fractured	172.45	X 172.45 NN
REAR BUMPER SIDE RETAINER L/R	2	necessary	121.00	121.00
REAR RH FENDER	1	buckled	1,097.30	1,097.30
REAR RH FENDER INNER UPHOLSTERY TRIM	1	deformed	272.80	272.80
REAR RH SHOCK ABSORBER	1	bent	191.40	191.40
REAR RH TAILLAMP	1	fractured	291.90	291.90
REAR RH TAILLAMP BACK RUBBER GASKET	1	necessary	23.00	23.00
REAR RH TAILLAMP INNER PANEL	1	repair	124.35	0.00
REAR RH WHEEL HOUSE PANEL ASSY	1	repair	561.60	0.00
REAR RH WHEEL HUB BEARING	1	dislodged	581.25	581.25
REAR SUSPENSION AXLE	1	distorted	1,712.10	1,712.10
REAR WINDSCREEN MOULDING	1	necessary	171.20	171.20
SPARE TYRE PANEL RH TOP SPONGE	1	deformed	374.45	X 374.45 NN
Subtotal before discount			S\$ 6,659.52	S\$ 5,973.57 5319.97
Percentage discount 25% and 25%			S\$ 1,664.88	S\$ 1,493.39 3989.98
Sub-total 1			S\$ 4,994.64	S\$ 4,480.18
REAR BUMPER CLIPS - SET	1	necessary	30.00	30.00 -
REAR RH 15" SPORT RIM	1	abraded	500.00	500.00 250
REAR RH 195/55R15 85V TYRE	1	abraded	400.00	400.00 150
REAR RH FENDER INNER INSULATOR MAT	1	necessary	180.00	X 180.00 NN
REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS - SET	1	necessary	30.00	30.00 -
REAR WINDSCREEN SEALANT	1	necessary	100.00	100.00 50
SPARE TYRE PANEL INSULATOR MAT	1	necessary	350.00	X 350.00 NN
Subtotal before discount			S\$ 1,590.00	S\$ 1,590.00 510
Sub-total 2			S\$ 1,590.00	S\$ 1,590.00
Parts-total			S\$ 6,584.64	S\$ 6,070.18


LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	100.00	60.00 30
To remove and refit rear windscreen(to FR)	150.00	120.00 100
To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.	600.00	450.00 300
To road test driving, check and resetting wheel alignments system.	180.00	180.00 60
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00	120.00 60
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,000.00	800.00 400
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,600.00	1,100.00 600
To apply anti-rust chemical on repaired and replaced panel.	80.00	60.00 1
Labour Total	S\$ 3,850.00	S\$ 2,890.00 1610
Parts & Labour Total	S\$ 10,434.64	S\$ 8,960.18

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 7,600.00
and the recommended number of working days for the repairs is within 10 day(s).


B J Loi (I Eng., MIMI, AIRTE)
Automotive Appraiser

6109.97

20%: 4850



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD17010765/Gqbs2-1

6 TEMASEK BOULEVARD
#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 17-05-2018



Code : FWD

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	EW 8229A	Veh. Inspected	SJT 9882M
Policy No.	PNPV2017-00002000	Coverage (\$)	0.00
Claim No.	1201700003109	Excess (\$)	0.00
Assign From	CLARA LI	Assign Date	02/04/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	MR053HY9305024804	Colour	SILVER
Odometer	148144	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55R15	DUNLOP	5 mm
L/H Front Tyre	195/55R15	DUNLOP	5 mm
R/H Rear Tyre	195/55R15	DUNLOP	5 mm
L/H Rear Tyre	195/55R15	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	01/06/2017	Inspection Date	02/06/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 9882M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>					
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	106.70	-	-
1	REAR BUMPER	SQUASHED	451.90	-	451.90
2	REAR BUMPER CORNER RETAINER L/R	NECESSARY	204.72	-	204.72
1	REAR BUMPER RH INNER SHIELD	WARPED	181.90	-	181.90
3	REAR BUMPER RH INNER SHIELD CLIPS	NECESSARY	19.50	-	19.50
1	REAR BUMPER RH REFLECTOR	NOT NECESSARY	172.45	-	-
2	REAR BUMPER SIDE RETAINER L/R	NECESSARY	121.00	-	121.00
1	REAR RH FENDER	BUCKLED	1,097.30	-	1,097.30
1	REAR RH FENDER INNER UPHOLSTERY TRIM	DEFORMED	272.80	-	272.80
1	REAR RH SHOCK ABSORBER	BENT	191.40	-	191.40
1	REAR RH TAILLAMP	FRACTURED	291.90	-	291.90
1	REAR RH TAILLAMP BACK RUBBER GASKET	NECESSARY	23.00	-	23.00
1	REAR RH TAILLAMP INNER PANEL	TO REPAIR SEE LABOUR	124.35	-	-
1	REAR RH WHEEL HOUSE PANEL ASSY	TO REPAIR SEE LABOUR	561.60	-	-
1	REAR RH WHEEL HUB BEARING	DISLODGE	581.25	-	581.25
1	REAR SUSPENSION AXLE	DISTORTED	1,712.10	-	1,712.10
1	REAR WINDSCREEN MOULDING	NECESSARY	171.20	-	171.20
1	SPARE TYRE PANEL RH TOP SPONGE	NOT NECESSARY	374.45	-	-
	LESS 25% DISCOUNT		-1,664.88	-	-1,329.99
			4,994.64	-	3,989.98
<u>SPECIAL NETT ITEMS</u>					
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	-	30.00
1	REAR RH 15" SPORT RIM (SN)	ABRADED	500.00	-	250.00
1	REAR RH 195/55R15 85V TYRE (SN)	ABRADED	400.00	-	150.00
1	REAR RH FENDER INNER INSULATOR MAT (SN)	NOT NECESSARY	180.00	-	-
1	SET REAR RH FENDER INNER UPHOLSTERY TRIM CLIPS (SN)	NECESSARY	30.00	-	30.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	100.00	-	50.00

Report Ref No. CS3/FWD17010765/Gqbs2-1



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Cost Price (\$)	Our Adjusted (\$)
1	SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	350.00	-	-
			1,590.00	-	510.00
	LABOUR				
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.		100.00	-	30.00
	TO REMOVE AND REFIT REAR WINDSCREEN (TO FR).		150.00	-	100.00
	TO REMOVE, CHANGE REAR SUSPENSION PARTS, AXLE CARRIAGE, ABSORBER, LOWER ARM, TOP ARM, TRAILING ARM, KNUCKLE ARM, WHEEL BEARING BEARING HUB AND ETC.		600.00	-	300.00
	TO ROAD TEST DRIVING, CHECK AND RESETTING WHEEL ALIGNMENTS SYSTEM.		180.00	-	60.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		140.00	-	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	-	400.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT, INCLUSIVE OF THE REPAIR OF REAR RH TAILLAMP INNER PANEL AND REAR RH WHEEL HOUSE PANEL ASSY.		1,600.00	-	600.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		80.00	-	60.00
			3,850.00	-	1,610.00
GRAND TOTAL			10,434.64	-	6,109.98
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)					4,850.00

Report Ref No. CS3/FWD17010765/Gqbs2-1

Report Ref No. CS3/FWD17010765/Gqbs2-1



MARKET VALUE: \$12,500.00 (EST)
LTA: \$7,341.00
NETT VALUE; \$5,159.00

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.