

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: GW5250H		
TP Vehicle No	: SLB6916R	Accident Date	: 31/03/2018
Make	: BMW X5 XL	Assignment Date	: 03/04/2018
Date of Inspection	: 03/04/2018	Est. Duration of Repair	: 8 days
Inspection At	: Mova Automotive Pte Ltd (Bukit Merah) No. 22 Jalan Kilang, #07-01, Mova Building Singapore 159419		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,307.15
Revised Amount	:S\$	18,538.20
Check Items (Estimated)	:S\$	2,890.85
Total	:S\$	21,429.05

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.