

ISS. REC. BY:

REF: CS/MSG18006044 / Gvds (1/1) Instruction:

Surveyor:

Merimen

GQ

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time:

3/4/18 @ 8:13am

Estimated Cost:

Bill to:

OD / IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJR 3409Y

Insured:

SKG 8522R

at Workshop m/s

Torque 5

Tel:

6452 4457

of

8 Kaki BK Ave 4 #01-49

Policy No.:

27404648SMP

Claim No.:

554150

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

31/3/2018

CA / REV / REP. / REV 24 HRS

hp)

H.O.D. Endorsement

Date/Time:

9:32am @ 3/4/18

Person Contacted:

Lee Ying

Vehicle

 IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SJR 3409Y -x
	SKG 8522R -x.
4/4/18	Send preli revised by merimen, pending for parts prices
1/8/18	LS \$6050 confirmed by email (Recd 22,419.60, 78%)
1/8/18	Send preli revised via merimen

Xarl.

REF: MSIG

0259W

ASSIGNMENT

From: _____ Date: 03/04/2018

Estimated Cost: _____

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJR 3409Y
at Workshop mis Torque 5
of 8 kaki Bkt Ave 4 #01-19

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$17K.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (wp)

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SJR 3409Y Yr Regn: Jan 2011

Type: M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Cerato cc 1591

Colour: Maroon A/C Insured / Std / NI / NA

Sp Reading: 213146 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAPH 2213 950 85354

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / STD A/Rim or

Tyre Size: F: 215/45 R17

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FALKEN

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. _____

D.O.I. 03-04-18

Survey held at: w/s 3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 0-1 AUG 2018

[Signature]
11/8/18

Date/Time File Pass to? : Prel. Report

: Final Report

Date/Time File Return to?

1/2 - typst

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportance

1. S+P2. SI

3. Prices

4. Other

Add Fee: Site Insp \$

Interview \$

Tech Insp \$

Wheel and \$

Report Format: merimen

Lump Sum / I.B.I: 6050f





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006044/Gvd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 03-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKG 8522R	Veh. Inspected	SJR 3409Y
Policy No.	27404648SMP	Coverage (\$)	0.00
Claim No.	554150	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/03/2018	Inspection Date	03/04/2018
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Mar 2018		03 Apr 2018 08:13 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LEE MEI LOUN CARISSA, ID: 57120400F								
Main Claimant:	MAYANG SERVICES, Co. Reg. No.: 53340259W								
Vehicle Reg. No.:	SJR3409Y	Date of Loss:	31/03/2018 12:00 - :59 [105 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 554150	Policy/Cover Note No.:	27404648SMP Coverage: 15/10/2017 - 14/10/2018						
Vehicle Reg. No. (Insured):	SKG8522R	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/04/2018]								
Adj Asg. Remarks:	We are agreeable to your list of surveyor - Adrian Ling as the SJE for this matter. Kindly make the necessary arrangements.								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	
Date: 01 Aug 2018	
<h3 style="margin: 0;">Preliminary Advice</h3>	

Insured Vehicle No	: SKG8522R		
TP Vehicle No	: SJR3409Y	Accident Date	: 31/03/2018
Make	: KIA CERATO FORTE	Assignment Date	: 03/04/2018
Date of Inspection	: 03/04/2018	Est. Duration of Repair	: 6.00
Inspection At	: TORQUE 5 BODYWORKS PTE LTD (KAKI BUKIT) 8 KAKI BUKIT AVE 4., #01-49/50/51/52/53/54 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

	:S\$	28,469.60
Repairer's Estimate (Gross)		
Revised Amount (estimated)	:S\$	6,050.00 (LUMP SUM)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,050.00
Lump Sum Repair	:S\$	

Total Loss Consideration

	:S\$	
New for Old Value		
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
---	--

Attn: Irene Tan Gek Ing **Date:** 04 Apr 2018

Preliminary Advice

Insured Vehicle No	: SKG8522R		
TP Vehicle No	: SJR3409Y	Accident Date	: 31/03/2018
Make	: KIA CERATO FORTE	Assignment Date	: 03/04/2018
Date of Inspection	: 03/04/2018	Est. Duration of Repair	: 6.00
Inspection At	: TORQUE 5 BODYWORKS PTE LTD (KAKI BUKIT) 8 KAKI BUKIT AVE 4., #01-49/50/51/52/53/54 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,060.00	(LABOUR ONLY)
Revised Amount	:S\$	4,260.00	(LABOUR ONLY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	4,260.00	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$		
Pre-Accident Value	:S\$		
COE / PARF Rebate	:S\$		
Salvage Value	:S\$		
Margin for Repair	:S\$		

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.
 PENDING FOR PARTS PRICES FROM REPAIRER

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0259W
Vehicle Details	
Vehicle No.:	SJR3409Y
Vehicle to be Exported:	No
Intended De-registration Date:	04 Apr 2018
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6(A) SX ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2009
Engine No.:	G4FC9H262470
Chassis No.:	KNAFH221395085354
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$13,989.00
Original Registration Date:	19 Jun 2009
First Registration Date:	19 Jun 2009
Transfer Count:	2
Actual ARF Paid:	\$13,989.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jun 2019
PARF Rebate Amount:	\$7,693.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jun 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$10,046.00
COE Rebate Amount:	\$1,192.00
Total Rebate Amount:	\$8,885.00

The information contained herein is correct as at 04 Apr 2018

OK

Extended Warranty! Best Value For Money! Easy To Maintain! Great Fuel Economy! High Trade-In! Well Maintained Sporty Designed Sedan, Awaits You To View And Believe! Buy It From Us With A Peace Of Mind...

Office No. - 68447667

Jonathan Quah - 91901666 | Eric Lee - 91827304 | Ricky Eng - 91853390

Kia Cerato Forte 1.6M EX **\$13,300** \$6,140 /yr 30-Apr-2009 1,591 cc 148,112 km Village Credit **Available**

Fast And Easy Deal, Spacious Cabin/Boot Space, Perfect For Short Term Drive, Call Now To Find Out More.

Office No. - 67482227

Mr Lim - 90688985 | Jerral - 81388352

Kia Cerato Forte 1.6A SX **\$17,500** \$9,000 /yr 21-May-2009 1,591 cc - Esteem Performance Pte Ltd **Available**

Looking For A Short Term Drive? Look No Further! Low Depreciation! Easy To Maintain, Call Us To Find Out More.

Office No. - 64591221

Jef - 86896550 | Alicia - 96962226

Kia Cerato Forte 1.6A SX **\$16,151** \$9,040 /yr 27-May-2009 1,591 cc - Dosh Car **Available**

New Arrival, Car Is In Excellent Condition And Well Maintained. Buy With A Peace Of Mind. Accident Free Unit And Drive Away With No Repair Needed, High Loan And Trade In Available! Contact Us For View...

Office No. - 67779311

Zack - 92705705 | Jack Tan - 86566662 | Mr Sim - 87877719

Kia Cerato Forte 1.6M SX **\$14,800** \$7,180 /yr 28-May-2009 1,591 cc 115,358 km Autocar Pte Ltd **Available**

New Arrival Beautiful Paintwork! Original Condition And Low Depreciation! Car Is In Good Working Condition. Wait No More And Call Us To Make An Appointment Now!

Office No. - -

Martin - 90595173 | Mr Yeo - 97427882

Kia Cerato Forte 1.6A SX **\$17,800** \$9,090 /yr 29-May-2009 1,591 cc - Dickson Automobile **Available**

Special Interest At 1.99% Only! Just 1 Owner! Low Mileage! Extended Warranty Available! Value For Money! Well Taken Care By Previous Owner In Excellent Condition, View And Let The Car Speak For Itself...

Office No. - 68447667

Tank Ong - 85265670 | Ricky Eng - 91853390 | Jonathan Quah - 91901666

Kia Cerato Forte 2.0A SX **\$17,800** \$8,210 /yr 19-Jun-2009 1,998 cc 116,000 km House De Carz Trading Pte Ltd **Available**

Well Maintained, All Wear And Tear Replaced, Zero Repairs Required, Cheapest In Town, Reliable Mid Range Sedan For Your Daily Use, Call Us To View And Feel The Difference, Call Our Friendly Sales Team...

Office No. - -

Casper Lee - 93855920 | Damien Khoo - 98783300 | Adrian - 93888488

Kia Cerato Forte 2.0A SX **\$19,500** \$9,010 /yr 19-Jun-2009 1,998 cc - Trust Motor Trading **Available**

Regularly Serviced By Previous Owners. Very Good Condition. Sporty Silver Color With Black Interior, Hurry And Arrange An Appointment To View, Call Now.

Office No. - 63384472

Alvin Chea - 90295022 | Benson Tan - 84187320 | Mr Lim - 96263081

Kia Cerato Forte 1.6A SX **\$17,800** \$8,710 /yr 29-Jun-2009 1,591 cc 134,436 km Remy Motor Trading Company **Available**

Sporty Outlook! Ideal For Short Term Drive/COE Renewal In Future! Low Maintenance For Your Daily Usage!

Office No. - 64680082

David - 94551891 | Desmond - 97323670 | Mr Yeo - 97482688

Kia Cerato Forte 2.0A SX **\$20,800** \$10,400 /yr 29-Jun-2009 1,998 cc 118,000 km Dosh Car **Available**

Well Maintained By 1 Owner, All Wear And Tear Replaced, Zero Repairs Required, New Around The Same Depreciation As A 1.6, Reliable Mid Range Sedan For Your Daily Use, Call Us To View And Feel The Diff...

Office No. - 67413111

Stella - 91065005 | David - 96558965 | JJ - 91739381

Kia Cerato Forte 1.6A SX **\$17,800** \$8,690 /yr 30-Jun-2009 1,591 cc - Ka-Hup Vehicles Trading **Available**

Very Affordable Mid Sized Car, Down Payment With Low Interest Rate At 2.78%. Car Is In Superb Condition, Regular Maintaining Done By

Email: sm@idac.com.sg
Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 31 / 03 / 2019 (dd/mm/yy) Time of Accident: 12 : 00 (24-HR-FORMAT)

Vehicle No.: SJR3409Y Vehicle Make & Model: Kia Cerato Forte

Exact location of Accident: Bencoolen st

Policyholder's Name / IC No.: Mayang Services / 53340259W

Driver's Name / IC No.: Nazarudin Bin Idradi / 51790830H (As Above)

Driver's Contact No.: 97524331 Company Contact No: _____

Driver's Address: 367 WOODLANDS AVE 5 #03-464 S730367

Insurance Company: NTUC Email address (if any): _____

Relationship between Owner & Driver: (Please CIRCLE one only)

Owner / Spouse / Children / Friend / Parents / Sibling / Relative / Employee / Hirer or Others specify: _____

What do you wish to claim? (Please TICK one only)

Own Insurance / Other Vehicle (The one you want to claim against) / Reporting (For Record Purpose)

Exact purpose for which the vehicle was being used at time of accident?

Private use / Work purpose

Occupation (nature of job) Indoor / Outdoor

No. of Passengers (Including Driver): 02

Weather condition & Road conditions? (On the day of accident)

Clear & Dry / Raining & Wet / After-Rain & Wet / Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? Yes / No

Any Injuries: Yes / No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: Yes / No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No: _____ Vehicle No: SKG8522R ^(B)

Driver's Contact No: _____ Insurance Company (If any): _____

2. Driver's Name / IC No: _____ Vehicle No: SFZ2286X ^(C)

Driver's Contact No: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


X

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' was
 travelling on the stated venue. I was travelling
 straight in my lane and the front vehicle
 stop hence I stop. A few moment later
 stationary vehicle
 I felt an impact from my rear. The impact
 caused my vehicle to propel forward and hit
 onto vehicle 'C' rear portion. I got down &
 realise I was involved in a 3 car chain
 collision.

Passenger: Grab Passenger male

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x
 Policyholder's Signature
 Date & Time:

Jaily
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
4DR, KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Bonnet X	1.00	0.00	0.00
2	Bonnet lock assy X	1.00	0.00	0.00
3	Bonnet outer rubber X	1.00	0.00	0.00
4	Front grille assy ?	1.00	0.00	0.00
5	Front grille clip X	1.00	0.00	0.00
6	Front grille logo X	1.00	0.00	0.00
7	Front grille chrome piece X	1.00	0.00	0.00
8	Front bumper / BA de.	1.00	0.00	0.00
9	Front bumper clip - MGC	1.00	0.00	0.00
10	Front bumper retainer (LH) -	1.00	0.00	0.00
11	Front bumper retainer (RH) - {MGC	1.00	0.00	0.00
12	Front bumper bracket (LH) X	1.00	0.00	0.00
13	Front bumper bracket (RH) X ?	1.00	0.00	0.00
14	Front bumper reinforcement ?	1.00	0.00	0.00
15	Front bumper sponge ?	1.00	0.00	0.00
16	Front bumper fog lamp (LH) X	1.00	0.00	0.00
17	Front bumper fog lamp (RH) X	1.00	0.00	0.00
18	Front bumper fog lamp grille (LH) X	1.00	0.00	0.00
19	Front bumper fog lamp grille (RH) X	1.00	0.00	0.00
20	Front number plate garnish X	1.00	0.00	0.00
21	Front fender (LH) - repair	1.00	0.00	0.00
22	Front fender (RH) - repair	1.00	0.00	0.00
23	Head lamp (LH) ?	1.00	0.00	0.00
24	Head lamp (RH) ?	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR, KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt
25	Head lamp clip (LH) X	1.00	0.00	0.00
26	Head lamp clip (RH) X	1.00	0.00	0.00
27	Support panel X	1.00	0.00	0.00
28	Support panel garnish X	1.00	0.00	0.00
29	Condenser X	1.00	0.00	0.00
30	Radiator X	1.00	0.00	0.00
31	Rear bootlid / <i>Bruc</i>	1.00	0.00	0.00
32	Rear bootlid hinge (LH) X	1.00	0.00	0.00
33	Rear bootlid hinge (RH) X	1.00	0.00	0.00
34	Rear bootlid support garnish (LH) X	1.00	0.00	0.00
35	Rear bootlid support garnish (RH) X	1.00	0.00	0.00
36	Rear bootlid lock / <i>BT</i>	1.00	0.00	0.00
37	Rear bootlid weather strip / <i>Tuis</i>	1.00	0.00	0.00
38	Rear bootlid logo / <i>ABC</i>	1.00	0.00	0.00
39	Rear bootlid emblem - Cerato / <i>ABC</i>	1.00	0.00	0.00
40	Rear bootlid emblem - Forte / <i>ABC</i>	1.00	0.00	0.00
41	Rear bootlid emblem - Cycle & Carriage / <i>ABC</i>	1.00	0.00	0.00
42	Rear bootlid inner trim X	1.00	0.00	0.00
43	Rear bootlid inner trim clip X	1.00	0.00	0.00
44	Rear bootlid lamp (LH) X	1.00	0.00	0.00
45	Rear bootlid lamp (RH) X	1.00	0.00	0.00
46	Rear bumper plate garnish X	1.00	0.00	0.00
47	Rear bumper / <i>el</i>	1.00	0.00	0.00
48	Rear bumper clip / <i>ABC</i>	1.00	0.00	0.00
49	Rear bumper retainer (LH) / <i>ABC</i>	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
4DR, KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt
50	Rear bumper retainer (RH) / MC	1.00	0.00	0.00
51	Rear bumper bracket (LH) X	1.00	0.00	0.00
52	Rear bumper bracket (RH) X	1.00	0.00	0.00
53	Rear bumper reinforcement ?	1.00	0.00	0.00
54	Rear bumper sponge ?	1.00	0.00	0.00
55	Tail lamp (LH) X	1.00	0.00	0.00
56	Tail lamp (RH) X	1.00	0.00	0.00
57	Tail lamp clip (LH) X	1.00	0.00	0.00
58	Tail lamp clip (RH) X	1.00	0.00	0.00
59	Rear fender (LH) - repair	1.00	0.00	0.00
60	Rear fender (RH) - repair	1.00	0.00	0.00
61	Rear fender inner trim (LH) X	1.00	0.00	0.00
62	Rear fender inner trim (RH) X	1.00	0.00	0.00
63	Rear fender inner trim clip (LH) X	1.00	0.00	0.00
64	Rear fender inner trim clip (RH) X	1.00	0.00	0.00
65	Rear end panel ?	1.00	0.00	0.00
66	Rear end panel top garnish ?	1.00	0.00	0.00
67	Rear end panel top garnish clip X	1.00	0.00	0.00
68	Spare wheel panel X	1.00	0.00	0.00
69	Spare wheel panel top board X	1.00	0.00	0.00
70	Spare wheel panel sponge X	1.00	0.00	0.00
71	Exhaust pipe X	1.00	0.00	0.00
72	Exhaust pipe mounting X	1.00	0.00	0.00
73	Exhaust pipe gasket X	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR, KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt
			Amt	S\$ 0.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 0.00
Section: Special Nett Items				
74	Front bumper lower spoiler / CRA	1.00	1,200.00	1,200.00
75	Front number plate / CRA	1.00	50.00	50.00
76	Rear number plate X	1.00	50.00	50.00
77	Rear bumper reverse sensor ?	1.00	300.00	300.00
78	Rear bumper lower spoiler / el	1.00	1,200.00	1,200.00
79	Rear end panel sealant ?	1.00	80.00	80.00
			Amt	S\$ 2,880.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 2,880.00

No	Description	Qty	U/P	Amt
Section: Labour Items				
80	To R&R front accident affected areas	1.00	600.00	600.00
81	To putty & respray front accident affected areas	1.00	800.00	800.00
82	To rust proof front accident affected areas	1.00	60.00	60.00
83	To R&R aircon condensor & refill gas	1.00	200.00	200.00
84	To check wiring layout & head lamp focus	1.00	80.00	80.00
85	To R&R rear accident affected areas	1.00	1,250.00	1,250.00
86	To putty & respray rear accident affected areas	1.00	1,250.00	1,250.00
87	To rust proof rear accident affected areas	1.00	60.00	60.00
88	To R&R rear boot mechanism	1.00	80.00	80.00
89	To R&R rear luggage compartment	1.00	200.00	200.00
90	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA,CERATO FORTE 1.6(A) SX ABS D/AB 2WD
4DR,KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt	
91	To check wiring layout of tail lamp	1.00	80,00	80,00	30
92	To R&R exhaust pipe assy	1.00	180,00	180,00	X
93	To check for water seepage	1.00	80,00	80,00	X
94	To do wheel alignment	1.00	180,00	180,00	X

Amt S\$ 5,180.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 5,180.00

6 Days.

Lumpsum repair.

After paint photos.

Geo Giang - 82880282

03/4/18.

[Handwritten Signature]
Approval

• Repairer must notify
 • Repairer must notify
 • Insurance must be notified
 • Display must be during survey
 • Parts must be subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	2,880.00
Labour Items Subtotal	S\$
	5,180.00
Total	S\$
	8,060.00



Torque 5 Pte Ltd

No. 8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
 Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR, KNAFH221395085354
 Year of Manufacture : 2009

Estimation No. : E18040004
 DOA : 31/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Bonnet X	1.00	0.00	0.00
2	Bonnet lock assy X	1.00	0.00	0.00
3	Bonnet outer rubber X	1.00	0.00	0.00
4	Front grille assy X - BR	1.00	0.00	0.00
5	Front grille clip X	1.00	0.00	0.00
6	Front grille logo X	1.00	0.00	0.00
7	Front grille chrome piece X	1.00	0.00	0.00
8	Front bumper X - BR	1.00	0.00	0.00
9	Front bumper clip X - MBL	1.00	0.00	0.00
10	Front bumper retainer (LH) X - MBL	1.00	0.00	0.00
11	Front bumper retainer (RH) X - MBL	1.00	0.00	0.00
12	Front bumper bracket (LH) X	1.00	0.00	0.00
13	Front bumper bracket (RH) X	1.00	0.00	0.00
14	Front bumper reinforcement X	1.00	0.00	0.00
15	Front bumper sponge X - CEA	1.00	0.00	0.00
16	Front bumper fog lamp (LH) X	1.00	0.00	0.00
17	Front bumper fog lamp (RH) X	1.00	0.00	0.00
18	Front bumper fog lamp grille (LH) X	1.00	0.00	0.00
19	Front bumper fog lamp grille (RH) X	1.00	0.00	0.00
20	Front number plate garnish X	1.00	0.00	0.00
21	Front fender (LH) - repair	1.00	0.00	0.00
22	Front fender (RH) - repair	1.00	0.00	0.00
23	Head lamp (LH) X	1.00	0.00	0.00
24	Head lamp (RH) X	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA,CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR,KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt
25	Head lamp clip (LH) X	1.00	0.00	0.00
26	Head lamp clip (RH) X	1.00	0.00	0.00
27	Support panel X	1.00	0.00	0.00
28	Support panel garnish X	1.00	0.00	0.00
29	Condenser X	1.00	0.00	0.00
30	Radiator X	1.00	0.00	0.00
31	Rear bootlid / <i>Proc</i>	1.00	0.00	0.00
32	Rear bootlid hinge (LH) X	1.00	0.00	0.00
33	Rear bootlid hinge (RH) X	1.00	0.00	0.00
34	Rear bootlid support garnish (LH) X	1.00	0.00	0.00
35	Rear bootlid support garnish (RH) X	1.00	0.00	0.00
36	Rear bootlid lock / <i>BT</i>	1.00	0.00	0.00
37	Rear bootlid weather strip / <i>Tris</i>	1.00	0.00	0.00
38	Rear bootlid logo / <i>ABC</i>	1.00	0.00	0.00
39	Rear bootlid emblem - Cerato / <i>ABC</i>	1.00	0.00	0.00
40	Rear bootlid emblem - Forte / <i>ABC</i>	1.00	0.00	0.00
41	Rear bootlid emblem - Cycle & Carriage / <i>ABC</i>	1.00	0.00	0.00
42	Rear bootlid inner trim / <i>TN</i>	1.00	0.00	0.00
43	Rear bootlid inner trim clip / <i>ABC</i>	1.00	0.00	0.00
44	Rear bootlid lamp (LH) / <i>CRA</i>	1.00	0.00	0.00
45	Rear bootlid lamp (RH) / <i>CRA</i>	1.00	0.00	0.00
46	Rear bumper plate garnish / <i>CRA</i>	1.00	0.00	0.00
47	Rear bumper / <i>el</i>	1.00	0.00	0.00
48	Rear bumper clip / <i>ABC</i>	1.00	0.00	0.00
49	Rear bumper retainer (LH) / <i>ABC</i>	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA,CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR,KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt
50	Rear bumper retainer (RH) / <i>ACL</i>	1.00	0.00	0.00
51	Rear bumper bracket (LH) <i>X</i>	1.00	0.00	0.00
52	Rear bumper bracket (RH) <i>X</i>	1.00	0.00	0.00
53	Rear bumper reinforcement <i>? - CRA</i>	1.00	0.00	0.00
54	Rear bumper sponge <i>? - CRA</i>	1.00	0.00	0.00
55	Tail lamp (LH) <i>⊗ - CRA</i>	1.00	0.00	0.00
56	Tail lamp (RH) <i>⊗ - CRA</i>	1.00	0.00	0.00
57	Tail lamp clip (LH) <i>X ?</i>	1.00	0.00	0.00
58	Tail lamp clip (RH) <i>X ?</i>	1.00	0.00	0.00
59	Rear fender (LH) - repair	1.00	0.00	0.00
60	Rear fender (RH) - repair	1.00	0.00	0.00
61	Rear fender inner trim (LH) <i>⊗ - TN</i>	1.00	0.00	0.00
62	Rear fender inner trim (RH) <i>X</i>	1.00	0.00	0.00
63	Rear fender inner trim clip (LH) <i>⊗ -</i>	1.00	0.00	0.00
64	Rear fender inner trim clip (RH) <i>X</i>	1.00	0.00	0.00
65	Rear end panel <i>? - buc</i>	1.00	0.00	0.00
66	Rear end panel top garnish <i>? - ee</i>	1.00	0.00	0.00
67	Rear end panel top garnish clip <i>⊗ -</i>	1.00	0.00	0.00
68	Spare wheel panel <i>X Repairs</i>	1.00	0.00	0.00
69	Spare wheel panel top board <i>X</i>	1.00	0.00	0.00
70	Spare wheel panel sponge <i>X</i>	1.00	0.00	0.00
71	Exhaust pipe <i>X</i>	1.00	0.00	0.00
72	Exhaust pipe mounting <i>X</i>	1.00	0.00	0.00
73	Exhaust pipe gasket <i>X</i>	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
 Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR, KNAFH221395085354
 Year of Manufacture : 2009

Estimation No. : E18040004
 DOA : 31/03/2018

No	Description	Qty	U/P	Amt
				S\$ 0.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 0.00
Section: Special Nett Items				
74	Front bumper lower spoiler - CRA	1.00	1,200.00	1,200.00 450
75	Front number plate - CRA	1.00	50.00	50.00 40
76	Rear number plate X	1.00	50.00	50.00 X
77	Rear bumper reverse sensor P - NW	1.00	300.00	300.00 200
78	Rear bumper lower spoiler - ee	1.00	1,200.00	1,200.00 450
79	Rear end panel sealant P	1.00	80.00	80.00 40
			Amt	S\$ 2,880.00
			Discount (0.00%)	S\$ 0.00
			Subtotal	S\$ 2,880.00

No	Description	Qty	U/P	Amt
Section: Labour Items				
80	To R&R front accident affected areas	1.00	600.00	600.00 200
81	To putty & respray front accident affected areas	1.00	800.00	800.00 200
82	To rust proof front accident affected areas	1.00	60.00	60.00 X
83	To rust proof front accident affected areas	1.00	200.00	200.00 X
84	To R&R aircon condensor & refill gas	1.00	80.00	80.00 X
85	To check wiring layout & head lamp focus	1.00	1,250.00	1,250.00 600.00
86	To R&R rear accident affected areas	1.00	1,250.00	1,250.00 600.00
87	To putty & respray rear accident affected areas	1.00	60.00	60.00 40
88	To rust proof rear accident affected areas	1.00	80.00	80.00 40
89	To R&R rear boot mechanism	1.00	200.00	200.00 60
90	To R&R rear luggage compartment	1.00	80.00	80.00 40
	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00 40

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
4DR, KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt	
91	To check wiring layout of tail lamp	1.00	80.00	80.00	30
92	To R&R exhaust pipe assy	1.00	180.00	180.00	X
93	To check for water seepage	1.00	80.00	80.00	X
94	To do wheel alignment	1.00	180.00	180.00	X
				Amt S\$ 5,180.00	
				Discount (0.00%) S\$ 0.00	
				Subtotal S\$ 5,180.00	

6 Days.
Lumpsum repair.
After paint photos.
Gno Qiang - 82880282
03/4/18.

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 2,880.00
Labour Items Subtotal	S\$ 5,180.00
Total	S\$ 8,060.00



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
Make & Model : KIA,CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR,KNAFH221395085354
Year of Manufacture : 2009

Estimation No. : E18040004
DOA : 31/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Bonnet X R	1.00	0.00	X 0.00 873.00
2	Bonnet lock assy X nn	1.00	0.00	X 0.00 375.00
3	Bonnet outer rubber X nn	1.00	0.00	X 0.00 166.00
4	Front grille assy X BR 195	1.00	0.00	X 0.00 598.00 195
5	Front grille clip X nn	1.00	0.00	X 0.00 50.00
6	Front grille logo X nn	1.00	0.00	X 0.00 89.00
7	Front grille chrome piece X nn	1.00	0.00	X 0.00
8	Front bumper / BR DE.	1.00	0.00	X 0.00 690.00 530
9	Front bumper clip / MC	1.00	0.00	X 0.00 50.00
10	Front bumper retainer (LH) / MC	1.00	0.00	X 0.00 121.90 21
11	Front bumper retainer (RH) / MC	1.00	0.00	X 0.00 121.90 21
12	Front bumper bracket (LH) X nn	1.00	0.00	X 0.00 79.50
13	Front bumper bracket (RH) X nn	1.00	0.00	X 0.00 79.50
14	Front bumper reinforcement X nn	1.00	0.00	X 0.00 499.80
15	Front bumper sponge X CEA	1.00	0.00	X 0.00 315.40 120
16	Front bumper fog lamp (LH) X	1.00	0.00	X 0.00 287.50
17	Front bumper fog lamp (RH) X	1.00	0.00	X 0.00 287.50
18	Front bumper fog lamp grille (LH) X } nn	1.00	0.00	X 0.00 299.70
19	Front bumper fog lamp grille (RH) X }	1.00	0.00	X 0.00 299.70
20	Front number plate garnish X	1.00	0.00	X 0.00
21	Front fender (LH) - repair	1.00	0.00	X 0.00 699.20
22	Front fender (RH) - repair	1.00	0.00	X 0.00 699.20
23	Head lamp (LH) X nn	1.00	0.00	X 0.00 681.00
24	Head lamp (RH) X nn	1.00	0.00	X 0.00 681.00
				8033.80

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
 Make & Model : KIA,CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 Year of Manufacture : 2009
 4DR,KNAFH221395085354

Estimation No. : E18040004
 DOA : 31/03/2018

No	Description	Qty	U/P	Amt
25	Head lamp clip (LH) X nn	1.00	0.00	X 0.00 10.00
26	Head lamp clip (RH) X nn	1.00	0.00	X 0.00 10.00
27	Support panel X R	1.00	0.00	X 0.00 468.00
28	Support panel garnish X nn	1.00	0.00	X 0.00 317.00
29	Condenser X nn	1.00	0.00	X 0.00 754.00
30	Radiator X nn	1.00	0.00	X 0.00 566.00
31	Rear bootlid / <i>blue</i>	1.00	0.00	/ 0.00 1067.40 729
32	Rear bootlid hinge (LH) X nn	1.00	0.00	X 0.00 135.00
33	Rear bootlid hinge (RH) X nn	1.00	0.00	X 0.00 135.00
34	Rear bootlid support garnish (LH) X nn	1.00	0.00	X 0.00
35	Rear bootlid support garnish (RH) X nn	1.00	0.00	X 0.00
36	Rear bootlid lock / <i>BT</i>	1.00	0.00	/ 0.00 163.80
37	Rear bootlid weather strip / <i>Tru</i>	1.00	0.00	/ 0.00 158.00 119
38	Rear bootlid logo / <i>ABC</i>	1.00	0.00	/ 0.00 127.50 55
39	Rear bootlid emblem - Cerato / <i>SAC</i>	1.00	0.00	/ 0.00 124.70 43
40	Rear bootlid emblem - Forte / <i>SAC</i>	1.00	0.00	/ 0.00 101.70 47
41	Rear bootlid emblem - Cycle & Carriage / <i>REC</i>	1.00	0.00	/ 0.00 101.70 40
42	Rear bootlid inner trim / <i>IN</i>	1.00	0.00	/ 0.00 204.40 84
43	Rear bootlid inner trim clip / <i>REC</i>	1.00	0.00	/ 0.00 58.00 20
44	Rear bootlid lamp (LH) / <i>CRA</i>	1.00	0.00	/ 0.00 225.40 135
45	Rear bootlid lamp (RH) / <i>CRA</i>	1.00	0.00	/ 0.00 205.40 135
46	Rear bumper plate garnish / <i>CRA</i>	1.00	0.00	/ 0.00 184.20 121
47	Rear bumper / <i>ee</i>	1.00	0.00	/ 0.00 837.60 601
48	Rear bumper clip / <i>REC</i>	1.00	0.00	/ 0.00 50.00 30
49	Rear bumper retainer (LH) / <i>REC</i>	1.00	0.00	/ 0.00 65.00 28
				6015.80

Continue on next page...



No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

Torque 5 Pte Ltd

ESTIMATION REPORT

Vehicle No : SJR3409Y
 Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR, KNAFH221395085354
 Year of Manufacture : 2009

Estimation No. : E18040004
 DOA : 31/03/2018

No	Description	Qty	U/P	Amt
50	Rear bumper retainer (RH) / nec	1.00	0.00	0.00 65,00 28
51	Rear bumper bracket (LH) x nn	1.00	0.00	X 0.00 125,00
52	Rear bumper bracket (RH) x nn	1.00	0.00	X 0.00 125,00
53	Rear bumper reinforcement R / CPA	1.00	0.00	0.00 422,00 175
54	Rear bumper sponge R / CPA	1.00	0.00	0.00 175,00 75
55	Tail lamp (LH) R / CPA	1.00	0.00	0.00 323,40 229
56	Tail lamp (RH) R / CPA	1.00	0.00	0.00 323,40 229
57	Tail lamp clip (LH) x ? nn	1.00	0.00	X 0.00 10,00
58	Tail lamp clip (RH) x ? nn	1.00	0.00	X 0.00 10,00
59	Rear fender (LH) - repair	1.00	0.00	0.00
60	Rear fender (RH) - repair	1.00	0.00	0.00
61	Rear fender inner trim (LH) R - TN	1.00	0.00	0.00 480,00 247
62	Rear fender inner trim (RH) x nn	1.00	0.00	X 0.00 480,00
63	Rear fender inner trim clip (LH) R - nec	1.00	0.00	0.00 50,00
64	Rear fender inner trim clip (RH) x nn	X 1.00	0.00	X 0.00 50,00
65	Rear end panel R - Buc	1.00	0.00	0.00 377,00
66	Rear end panel top garnish R - R	1.00	0.00	0.00 145,00
67	Rear end panel top garnish clip R - nec	1.00	0.00	0.00 50,00
68	Spare wheel panel x Repair	1.00	0.00	X 0.00 1980,00
69	Spare wheel panel top board x	1.00	0.00	X 0.00 135,00
70	Spare wheel panel sponge x	1.00	0.00	X 0.00
71	Exhaust pipe x } nn	1.00	0.00	X 0.00 835,20
72	Exhaust pipe mounting x	1.00	0.00	X 0.00 156,50
73	Exhaust pipe gasket x	1.00	0.00	X 0.00 32,50

6360

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
 Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 Year of Manufacture : 2009
 4DR, KNAFH221395085354

Estimation No. : E18040004
 DOA : 31/03/2018

No	Description	Qty	U/P	Amt	
				Amt	S\$ 0.00
				Discount (0.00%)	S\$ 0.00
				Subtotal	S\$ 0.00
Section: Special Nett Items					
74	Front bumper lower spoiler — CRA	1.00	1,200.00	1,200.00	450
75	Front number plate — CRA	1.00	50.00	50.00	40
76	Rear number plate X nn	1.00	50.00	50.00	X
77	Rear bumper reverse sensor P — NW	1.00	300.00	300.00	200
78	Rear bumper lower spoiler — ee	1.00	1,200.00	1,200.00	450
79	Rear end panel sealant P — nec	1.00	80.00	80.00	40
				Amt	S\$ 2,880.00
				Discount (0.00%)	S\$ 0.00
				Subtotal	S\$ 2,880.00
Section: Labour Items					
80	To R&R front accident affected areas	1.00	600.00	600.00	200
81	To putty & respray front accident affected areas	1.00	800.00	800.00	200
82	To rust proof front accident affected areas	1.00	60.00	60.00	X
83	To rust proof front accident affected areas	1.00	200.00	200.00	X
84	To R&R aircon condensor & refill gas	1.00	80.00	80.00	X
85	To check wiring layout & head lamp focus	1.00	1,250.00	1,250.00	600 700
86	To R&R rear accident affected areas	1.00	1,250.00	1,250.00	600 700
87	To putty & respray rear accident affected areas	1.00	60.00	60.00	40
88	To rust proof rear accident affected areas	1.00	80.00	80.00	40
89	To R&R rear boot mechanism	1.00	200.00	200.00	60
90	To R&R rear luggage compartment	1.00	80.00	80.00	40
	To R&R rear bumper reverse sensor & check function				

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SJR3409Y
 Make & Model : KIA, CERATO FORTE 1.6(A) SX ABS D/AB 2WD
 4DR, KNAFH221395085354
 Year of Manufacture : 2009

Estimation No. : E18040004
 DOA : 31/03/2018

No	Description	Qty	U/P	Amt	
91	To check wiring layout of tail lamp	1.00	80.00	80.00	30
92	To R&R exhaust pipe assy	1.00	180.00	180.00	X
93	To check for water seepage	1.00	80.00	80.00	X
94	To do wheel alignment	1.00	180.00	180.00	X
				28,469.60	
				Amt S\$ 5,180.00	
				Discount (0.00%) S\$ 0.00	
				Subtotal S\$ 5,180.00	2010

6 Days.

Lumpsum repair.

After paint photos.

Gno Qiang - 82880282

03/4/18.

P: 7365-80 - 10%

= 6629.22

Q: 1180-00

L: 2010-00

9819.22

* HC @ 7860 @ 6
 repair days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal	S\$ 0.00
Special Nett Items	S\$
Subtotal	2,880.00
Labour Items Subtotal	S\$
	5,180.00
Total	S\$
	8,060.00

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 1 August 2018 1:43 PM
To: 'Torque 5 Assessment'; Guo Qiang (LKKAuto)
Cc: claims@torque5.com; sam.chang@torque5.com; SUR; Admin A
Subject: RE: *3RD REMINDER* FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

Dear Stephanie ,

Noted with thanks.

Kindly send Final invoice and all supporting documents to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Torque 5 Assessment <assessment@torque5.com>
Sent: Wednesday, 1 August 2018 10:15 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: claims@torque5.com; sam.chang@torque5.com; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; 'Torque 5 Assessment' <assessment@torque5.com>
Subject: RE: *3RD REMINDER* FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

Dear Veron,



We hereby confirm the final amount of L/S \$6,050 (before GST @ 6 repair days).
Thank you.

Warmest Regards,
Stephanie Teo

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



[REDACTED]

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Tuesday, 31 July, 2018 2:20 PM
To: Assessment; Guo Qiang (LKKAuto)
Cc: claims@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; SUR; Admin A
Subject: RE: *3RD REMINDER* FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

Dear Suanne,

WITHOUT PREJUDICE

Offer Lump Sum \$6050 @ 6 working days.

Kindly confirm.

Best Regards,

Veron Chen | Case Handler



LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email

sur@lkkauto.com | fax: 6256-

4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Wednesday, 27 June 2018 4:59 PM
To: Assessment <assessment@torque5.com>; Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: claims@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: *3RD REMINDER* FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

Dear Suanne,

Will get Guo Qiang to finalize.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Assessment [<mailto:assessment@torque5.com>]

Sent: Wednesday, 27 June 2018 12:21 PM

To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>

Cc: claims@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; SUR <sur@lkkauto.com>; 'Torque 5 Assessment' <assessment@torque5.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: *3RD REMINDER* FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

3RD REMINDER



Dear Guo Qiang,

Kindly revert.

Warmest Regards,

Suanne Tan

Claims Officer | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



From: Torque 5 Assessment [<mailto:assessment@torque5.com>]

Sent: Friday, June 08, 2018 6:02 PM

To: 'Guo Qiang (LKKAuto)' <GuoQiang@lkkauto.com>

Cc: claims@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; 'SUR' <sur@lkkauto.com>; 'Torque 5 Assessment' <assessment@torque5.com>

Subject: RE: *REMINDER* FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

Importance: High

Dear Guo Qiang,



Kindly revert your confirmation if we can close this case at L/S \$7,860 @ 6 repair days.
Thank you.

Warmest Regards,

Stephanie Teo

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



From: Assessment [<mailto:assessment@torque5.com>]

Sent: Wednesday, 16 May, 2018 3:56 PM

To: 'Guo Qiang (LKKAuto)'

Cc: claims@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com; 'Torque 5 Assessment'; 'SUR'

Subject: RE: *REMINDER* FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

REMINDER

Dear Guo Qiang,



Kindly check and confirm final amount.



Thank you.

*Warmest Regards,
Suanne Tan*

Claims Officer | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



From: Torque 5 Assessment [<mailto:assessment@torque5.com>]

Sent: Tuesday, April 17, 2018 7:11 PM

To: 'Guo Qiang (LKKAuto)' <GuoQiang@lkkauto.com>

Cc: 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com; sam.chang@torque5.com; eric.lee@torque5.com

Subject: FINALISATION FOR SJR 3409 Y (SURVEY DATE : 03/04/18)

Dear Guo Qiang,



Kindly check and confirm the final amount.



Thank you.

Warmest Regards,
Stephanie Teo
Assessor | Motor Claims

Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875

www.torque5.com



...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Mar 2018		03 Apr 2018 08:13 Edit Adj Rpt	S\$6,050.00 Edit Estimates	S\$6,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	LEE MEI LOUN CARISSA , ID: S7120400F								
Main Claimant:	MAYANG SERVICES , Co. Reg. No.: 53340259W								
Vehicle Reg. No.:	SJR3409Y	Date of Loss:	31/03/2018 12:00 - :59 [105 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 554150	Policy/Cover Note No.:	27404648SMP Coverage: 15/10/2017 - 14/10/2018						
Vehicle Reg. No. (Insured):	SKG8522R	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 03/05/2018]								
Adj Asg. Remarks:	We are agreeable to your list of surveyor – Adrian Ling as the SJE for this matter. Kindly make the necessary arrangements.								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJR3409Y (554150)
[SKG8522R]
TP
MAYANG SERVICES
Mar 31 2018 12:00PM
[LEE MEI LOUN CARISSA]
Torque 5 Bodyworks Pte Ltd

Upload Documents Upload Photos Compose New Letter			View	View in Browser
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 15:44	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
2	01/08/18 14:00	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
2	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
3	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
4	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
5	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
6	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
7	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
8	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
9	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
10	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
11	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
12	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
13	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
14	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
15	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
16	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
17	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
18	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
19	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
20	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
21	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
22	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
23	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
24	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
25	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
26	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
27	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
28	04/04/18 14:34	General View	Load JPG	<input checked="" type="checkbox"/>
29	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
30	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
31	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
32	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
33	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
34	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
35	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
36	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
37	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
38	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
39	04/04/18 14:35	General View	Load JPG	<input checked="" type="checkbox"/>
40	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	01/08/18 13:50	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/04/18 08:07	TPD SJR3409Y GIA REPORT.	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006044/GVD3Q2

Date: 14/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 27404648SMP
Claimant Vehicle No : SJR3409Y **Insured Vehicle No :** SKG8522R
 Date of Loss: 31/03/2018 Nature of Claim: TP Claim No: 554150

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR3409Y**
 Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H262470
 Reg. Date: 19/06/2009 (Man. Year: 2009) Chassis No: KNAFH221395085354
 Colour: Maroon Odometer: 213146 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
 Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
 Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,289.60	5,583.52	17,706.08	76.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,180.00	2,010.00	3,170.00	61.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,469.60	7,593.52	20,876.08	73.33
Approved Total (Overridden) (S\$)		6,050.00		
(S\$)	28,469.60	6,050.00	22,419.60	78.75
+ GST 7.00/7.00% (S\$)	1,992.87	423.50	1,569.37	78.75
Nett Amount (S\$)	30,462.47	6,473.50	23,988.97	78.75

INSPECTION

Date of Assignment: 03/04/2018
 Date Inspected: 03/04/2018 Inspected At: Torque 5 Bodyworks Pte Ltd (Kaki Bukit)
 8 Kaki Bukit Ave 4., #01-49/50/51/52/53/54
 Premier @ Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 6.0 days

Adjuster: XING GUO QIANG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Aug 2018)
Parts: 143	KIA CERATO FORTE 1.6 A/T ABS AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR3409Y)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	873.00 F	*- FL
2	1		*BONNET LOCK ASSY	Not Necessary	375.00 F	*- FL
3	1		*BONNET OUTER RUBBER	Not Necessary	166.00 F	*- FL
4	1		*FRONT GRILLE ASSY	Broken	598.00 F	*195.00 FL
5	1		*FRONT GRILLE CLIP	Not Necessary	50.00 F	*- FL
6	1		*FRONT GRILLE LOGO	Not Necessary	89.00 F	*- FL
7	1		*FRONT GRILLE CHROME PIECE (NPA)	Not Necessary	0.00 F	*- FL
8	1		*FRONT BUMPER	Deformed	690.00 F	*530.00 FL
9	1		*FRONT BUMPER CLIP	Necessary	50.00 F	*50.00 FL
10	1		*FRONT BUMPER RETAINER (LH)	Necessary	121.90 F	*21.00 FL
11	1		*FRONT BUMPER RETAINER (RH)	Necessary	121.90 F	*21.00 FL
12	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	79.50 F	*- FL
13	1		*FRONT BUMPER BRACKET (RH)	Not Necessary	79.50 F	*- FL
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	499.80 F	*- FL
15	1		*FRONT BUMPER SPONGE	Cracked	315.40 F	*120.00 FL
16	1		*FRONT BUMPER FOG LAMP (LH)	Not Necessary	282.50 F	*- FL
17	1		*FRONT BUMPER FOG LAMP (RH)	Not Necessary	282.50 F	*- FL
18	1		*FRONT BUMPER FOG LAMP GRILLE (LH)	Not Necessary	299.70 F	*- FL
19	1		*FRONT BUMPER FOG LAMP GRILLE (RH)	Not Necessary	299.70 F	*- FL
20	1		*FRONT BUMPER PLATE GARNISH (NPA)	Not Necessary	0.00 F	*- FL
21	1		*FRONT FENDE (LH)	Repair	699.20 F	*- FL
22	1		*FRONT FENDE (RH)	Repair	699.20 F	*- FL
23	1		*HEAD LAMP (LH)	Not Necessary	681.00 F	*- FL
24	1		*HEAD LAMP (RH)	Not Necessary	681.00 F	*- FL
25	1		*HEAD LAMP CLIP (LH)	Not Necessary	10.00 F	*- FL
26	1		*HEAD LAMP CLIP (RH)	Not Necessary	10.00 F	*- FL
27	1		*SUPPORT PANEL	Repair	468.00 F	*- FL
28	1		*SUPPORT PANEL GARNISH	Not Necessary	312.00 F	*- FL
29	1		*CONDENSER	Not Necessary	754.00 F	*- FL
30	1		*RADIATOR	Not Necessary	566.00 F	*- FL
31	1		*REAR BOOTLID	Buckled	1,067.40 F	*729.00 FL
32	1		*REAR BOOTLID HINGE (LH)	Not Necessary	135.00 F	*- FL
33	1		*REAR BOOTLID HINGE (RH)	Not Necessary	135.00 F	*- FL
34	1		*REAR BOOTLID SUPPORT GARNISH (LH) (NPA)	Not Necessary	0.00 F	*- FL
35	1		*REAR BOOTLID SUPPORT GARNISH (RH) (NPA)	Not Necessary	0.00 F	*- FL
36	1		*REAR BOOTLID LOCK	Bent	163.80 F	*163.80 FL
37	1		*REAR BOOTLID WEATHER STRIP	Twisted	150.00 F	*119.00 FL
38	1		*REAR BOOTLID LOGO	Necessary	137.50 F	*55.00 FL
39	1		*REAR BOOTLID EMBLEM -CERATO	Necessary	101.70 F	*43.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR BOOTLID EMBLEM -FORTE	Necessary	101.70 F	*47.00 FL
41	1		*REAR BOOTLID EMBLEM -CYCLE & CARRIAGE	Necessary	101.70 F	*40.00 FL
42	1		*REAR BOOTLID INNER TRIM	Torn	204.40 F	*84.00 FL
43	1		*REAR BOOTLID INNER TRIM CLIP	Necessary	50.00 F	*20.00 FL
44	1		*REAR BOOTLID LAMP (LH)	Cracked	205.40 F	*135.00 FL
45	1		*REAR BOOTLID LAMP (RH)	Cracked	205.40 F	*135.00 FL
46	1		*REAR BUMPER PLATE GARNISH	Cracked	184.20 F	*121.00 FL
47	1		*REAR BUMPER	Deformed	837.60 F	*601.00 FL
48	1		*REAR BUMPER CLIP	Necessary	50.00 F	*30.00 FL
49	1		*REAR BUMPER RETAINER (LH)	Necessary	65.00 F	*28.00 FL
50	1		*REAR BUMPER RETAINER (RH)	Necessary	65.00 F	*28.00 FL
51	1		*REAR BUMPER BRACKET (LH)	Not Necessary	125.00 F	*- FL
52	1		*REAR BUMPER BRACKET (RH)	Not Necessary	125.00 F	*- FL
53	1		*REAR BUMPER REINFORCEMENT	Cracked	432.00 F	*175.00 FL
54	1		*REAR BUMPER SPONGE	Cracked	175.00 F	*75.00 FL
55	1		*TAIL LAMP (LH)	Cracked	323.40 F	*229.00 FL
56	1		*TAIL LAMP (RH)	Cracked	323.40 F	*229.00 FL
57	1		*TAIL LAMP CLIP(LH)	Not Necessary	10.00 F	*- FL
58	1		*TAIL LAMP CLIP(RH)	Not Necessary	10.00 F	*- FL
59	1		*REAR FENDER (LH) (NPA)	Repair	0.00 F	*- FL
60	1		*REAR FENDER (RH) (NPA)	Repair	0.00 F	*- FL
61	1		*REAR FENDER INNER TRIM (LH)	Torn	480.00 F	*247.00 FL
62	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	480.00 F	*- FL
63	1		*REAR FENDER INNER TRIM CLIP (LH)	Necessary	50.00 F	*50.00 FL
64	1		*REAR FENDER INNER TRIM CLIP (RH)	Not Necessary	50.00 F	*- FL
65	1		*REAR END PANEL	Buckled	377.00 F	*377.00 FL
66	1		*REAR END PANEL TOP GARNISH	Deformed	145.00 F	*145.00 FL
67	1		*REAR END PANEL TOP GARNISH CLIP	Necessary	50.00 F	*50.00 FL
68	1		*SPARE WHEEL PANEL	Repair	1,980.00 F	*- FL
69	1		*SPARE WHEEL PANEL TOP BOARD	Not Necessary	135.00 F	*- FL
70	1		*SPARE WHEEL PANEL SPONGE (NPA)	Not Necessary	0.00 F	*- FL
71	1		*EXHAUST PIPE	Not Necessary	835.20 F	*- FL
72	1		*EXHAUST PIPE MOUNTING	Not Necessary	156.50 F	*- FL
73	1		*EXHAUST PIPE GASKET	Not Necessary	32.50 F	*- FL
74	1		*FRONT BUMPER LOWER SPOILER	Cracked	1,200.00 FS	*450.00 FS
75	1		*FRONT NUMBER PLATE	Cracked	50.00 FS	*40.00 FS
76	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
77	1		*REAR BUMPER REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
78	1		*REAR BUMPER LOWER SPOILER	Deformed	1,200.00 FS	*450.00 FS
79	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,289.60	6,072.80
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	489.28
Total Parts (\$\$)	23,289.60	5,583.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R FRONT ACCIDENT AFFECTED AREAS	New	600.00	200.00
2	TO PUTTY & RESPRAY FRONT ACCIDENT AFFECTED AREAS	New	800.00	200.00
3	TO RUST PROOF FRONT ACCIDENT AFFECTED AREAS	New	60.00	0.00
4	TO R&R AIRCON CONDENSOR & REFILL GAS	New	200.00	0.00
5	TO CHECK WIRING LAYOUT & HEAD LAMP FOCUS	New	80.00	0.00
6	TO R&R REAR ACCIDENT AFFECTED AREAS	New	1,250.00	700.00
7	TO PUTTY & RESPRAY REAR ACCIDENT AFFECTED AREAS	New	1,250.00	700.00
8	TO RUST PROOF REAR ACCIDENT AFFECTED AREAS	New	60.00	40.00
9	TO R&R REAR BOOT MECHANISM	New	80.00	40.00
10	TO R&R REAR LUGGAGE COMPARTMENT	New	200.00	60.00
11	TO R&R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION	New	80.00	40.00
12	TO CHECK WIRING LAYOUT OF TAIL LAMP	New	80.00	30.00
13	TO R&R EXHAUST PIPE ASSY	New	180.00	0.00
14	TO CHECK FOR WATER SEEPAGE	New	80.00	0.00
15	TO DO WHEEL ALIGNMENT	New	180.00	0.00
Gross Labour Cost (S\$)			5,180.00	2,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >