

ASS. REC. BY:

REF:

CS/ALG18006047/K7d3

Special Instruction:

Surveyor
Munim

Kamath

ASSIGNMENT (Office)

From (Person):

Dushere Supremeniam

of

ALG

Date/Time:

3/4/18 @ 8:27am.

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLH 1223H

Insured:

SLE 2496X

at Workshop m/s

C.S. Ong Auto

Tel:

6484 1933

of

10 AMK Ind. Park 2A #02-16

Policy No:

099999814

Claim No:

877134463756

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

06/03/2018

CA / REV / REP. / REV 24 HRS

1wp

04/04/18 @ after 2pm

H.O.D. Endorsement

Date/Time:

6:54am @ 3/4/18

Person Contacted:

Mrs. Ong

Vehicle IN / OUT

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLH 1223H - X

SLE 2496X - X.

24/4/18 11:57pm @ 1800 email & Confirm (Ref B 8024-57, 8210)

REF: ALH

ASSIGNMENT

From: Date: 04/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLH 1223H

at Workshop n/s:

of C-S Ong
Blk 10 Amk Tru Park 2A #02-16

Insured:

Policy No:

Claims No:


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLH 1223H Yr Regn: 10 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Sierr

Colour: Green

Sp. Reading: 35300

Eng/No:

C/No: NSP170

Gen. Cond: Good Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A: 6/13/18

D.O.I: 4/4/18

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

5/4 AM 11:15 to Catherine

RECEIVED 25 APR 2018

Date/Time. File Pass to?

☐

Prel. Report

☐

Final Report

11/28/4 to [Signature]

Date/Time. File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee

Transportation

1. 3 + 10 = 13

2. Photos

3. Other

TOTAL

Report Format: MER-TP

Lump Sum / I.B.F. (\$)

1800

24 x 72.0



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18006047/Kqd3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 03-04-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 2496X	Veh. Inspected	SLH 1223H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	DARSHENE SUPRAMANIAM	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/03/2018	Inspection Date	
Survey held at	C. S. ONG AUTO PTE LTD BLOCK 10 ANG MO KIO IND PK 2A #04-01/#03-11 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Nivitha (LKK Auto)

From: Supramaniam, Darshene <Darshene.Supramaniam@aig.com>
Sent: Tuesday, 3 April 2018 8:27 AM
To: 'admin-a@lkkauto.com'; assignments@lkkauto.com
Cc: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLE2496X & SLH1223H ON 06 MARCH 2018
Attachments: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLE24... (31.6 KB); 02042018092450.pdf

Hi,

Please refer to the enclosed request from **RIAZ LLC**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thank you.

Best Regards,

Darshene Supramaniam
AIG
Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

Level 12, Menara Worldwide, 198 Jalan Bukit Bintang. 55100 Kuala Lumpur, Malaysia
Tel +603 2719 6000 ext 100-2208 | Fax +603 2719 6150

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



RIAZ

L.L.C

ADVOCATES AND SOLICITORS
COMMISSIONER FOR OATHS

ACRA NUMBER : 200911678H

GST REGISTRATION NUMBER : 200911678H

02/04/2018

Our Ref: SLH 1223H (V) CS ONG

Your Ref: SLE 2496X

TO: AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
Tower 2 #07-16
Singapore 079120
Attn: Motor Claims Department

RIAZ QAYYUM (LLB HONS) NUS
(DIRECTOR)

TAN KOK SIANG (LLB HONS) LON
(ASSOCIATE)

ABDUL HALIM BIN ROSALAN (LLB HONS) UTAS
(ASSOCIATE)

BY FAX (6415-3727) ONLY
MUHD RIDHWAN ABDUL RAHIM (LLB HONS) LEEDS
(ASSOCIATE)

NOTICE OF ACCIDENT

Dear Sir

We are instructed by our client to *notify* you of a road traffic accident on 06.03.2018 at about 1510 hours along Sinaran Drive involving our client's vehicle registration number SLH 1223H and vehicle registration number SLE 2496X driven by you or your authorized driver at the material time. A copy of Singapore accident statement / traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : C.S ONG AUTO PTE LTD

Address : 10 ANG MO KIO AUTO POINT
IND PARK 2A, #02-16
SINGAPORE 568047

Telephone no. : 6484 1933

Fax no. : 6484 1922

Please let us hear from you by the stipulated time.

Yours faithfully

encs

cc Client

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor
(Name & signature)

Date & time of inspection

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/03/2018 15:51
Date Of Accident	06/03/2018 15:10
Exact Location Of Accident	SINARAN DRIVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH1223H
Insured/Policyholder	
Name Of Registered Owner	BOON YEN WEI
NRIC No	S7340539D
Email Address	DARRENBOON99@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94555125
Alternative Phone No	OTHERS-94555125

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA-1.5 G CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PTE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01014916
Cover Note Number	25/10/2017 - 24/10/2018


Driver

Name of Driver	BOON YEN WEI
NRIC No	S7340539D
Date Of Birth	01/11/1973
Occupation	INDOOR
Date Of Driving Pass	02/05/1997
Driving Experience	20 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94555125
Fax Number	
Contact Number	OTHERS-94555125
Email Address	DARRENBOON99@GMAIL.COM

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



A : SLH1223H
B : SLE2496X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 06/03/2018 at around 1510hrs, I WAS travelling along Sinaran Drive.

I came to a stop to give way to vehicles on the major road. After which, the vehicle SLE2496X collided onto the rear portion of my vehicle.

Claim 3rd Party : C-S-DNG AUTO PTE LTD

E-mail a copy : CSongauto@yahoo.com.sg

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (AMK)
NRIC/IN No:

☒ Claim Own Policy ☐ Claim Third Party ☐ Reporting Only
☒ Claim CDTP at other workshop

Not Authorised
 11 Amp @ \$800p
 Running After Repair
 6 days

C. S. ONG AUTO PTE. LTD.

Business Reg No.: 201408916W

GST Reg No.: 201408916W

10, Ang Mo Kio Ind. Park 2A, #02-16, AMK Autopoint, Singapore (568047).

Tel: 6484 1933 Fax: 6484 1922

E-Mail: csongauto@yahoo.com.sg

To: Motor Claims Department,
 AIG ASIA PACIFIC INSURANCE PTE LTD

Date: 22/03/2018

Accident Involving Vehicles SLH1223H & SLE2496X [Your Insured] on 06/03/2018 @
 1510Hrs along SINARAN DRIVE

Estimated Repair Costs For SLH1223H [Toyota Sienta]

<u>Qty</u>	<u>Parts</u>	<u>Amount</u>	
1Pc	Rear Tail Gate	\$ 1,076.00	✓
1Pc	Rear Tail Gate "Toyota" Logo	\$ 75.30	✓
1Pc	Rear Tail Gate "SIENTA" Plate With Mldg	\$ 256.80	X
1Pc	Rear Tail Gate "HYBRID" Emblem	\$ 70.50	✓
1Pc	Rear Tail Gate Rubber Stopper & Damper Assembly	\$ 230.80	X
2Pcs	Rear Tail Gate LH & RH Hinges @ \$59.73 Each	\$ 119.46	X
1Pc	Rear Tail Gate Inner Trim Board Cover Assembly	\$ 158.50	X
1Set	Rear Tail Gate Inner Trim Board Cover Clip	\$ 35.00	X
1Pc	Rear Tail Gate Inner Weatherstrip Rubber	\$ 368.20	X
1Pc	Rear Tail Gate Inner Lock Assembly	\$ 361.60	X
1Pc	Rear Tail Gate Striker Lock	\$ 24.60	X
1Pc	Rear Windscreen Mldg	\$ 75.20	✓
2Pcs	Rear RH & LH Tail Gate Lamp @ \$248.70 each	\$ 497.40	X
2Pcs	Rear RH & LH Tail Gate Outer Lamp @ \$347.00 each	\$ 694.00	X
1Pc	Rear Bumper	\$ 278.00	✓
1Pc	Rear Bumper LH Support Garnish	\$ 214.00	X
1Pc	Rear Bumper RH Support Garnish	\$ 214.00	X
1Pc	Rear Bumper Centre Garnish	\$ 235.40	X
1Pc	Rear Towing Cover	\$ 53.50	X
1Set	Rear Bumper Clips	\$ 35.00	✓
2Pcs	Rear Bumper Side Retainer @ \$92.33	\$ 184.66	X
2Pcs	Rear Bumper RH & LH Reflector @ \$70.05 each	\$ 140.10	X
1Pc	Rear End Panel	\$ 374.00	X
1Pc	Rear End Panel Inner Top Trim Garnish	\$ 232.00	X
1Set	Rear End Panel Inner Top Trim Garnish Clips	\$ 35.00	X

1Pc Rear Spare Tyre Panel
1Pc Rear Spare Tyre Panel Cover Board

R \$ 673.60 *X*
Sm \$ 550.80 *X*
Parts Sum: \$ 7,263.42
Parts Less 25%: \$ 1,815.86
Parts Total: \$ 5,447.57

Special Nett. Items

1Set Rear Camera
1Set Rear Number Plate with Holder
1Set Rear End Panel Sealants
2Set Rear RH & LH Tail Lamp Panel Sealants
1Set Rear WindScreen Glass Sealant
1Set Rear Spare Tyre Panel Sealants

Sm \$ 350.00 *X*
Sm \$ 80.00 *X*
nn \$ 100.00 *X*
nn \$ 100.00 *X*
nn \$ 100.00 *40sm*
nn \$ 100.00 *X*
Special Nett. Items Total: \$ 830.00

Labour & MISC Charges

Description	Amount
* To remove and replace rear windscreen to facilitate repair	\$ 200.00 <i>1201</i>
* To cut & remove all rear damaged panels, replace new parts, refit and to realign all of the above items	\$ 1,500.00 <i>4001</i>
* To putty & re-spray new paintwork on all rear affected areas.	\$ 1,500.00 <i>4401</i>
* To conduct a check on all wiring systems.	\$ 150.00 <i>201</i>
* To anti rust all affected areas.	\$ 200.00 <i>301</i>

Labour & Charges Total: \$ 3,550.00
Parts Total: \$ 5,447.57
Special Nett. Items Total: \$ 830.00
Labour & Charges Total: \$ 3,550.00
Total Cost of Repair: \$ 9,827.57
(Non inclusive of 7% GST)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Apr 2018 Edit Reg		03 Apr 2018 00:00 Edit Adj Rpt	S\$1,800.00 Edit Estimates	S\$1,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	LCRF Pte Ltd, Co. Reg. No.: -		
Main Claimant:	BOON YEN WEI, ID: S7340539D		
Vehicle Reg. No.:	SLH1223H	Date of Loss:	06/03/2018 15:00 - :59 [16 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8771394637SG	Policy/Cover Note No.:	0999994814
Vehicle Reg. No. (Insured):	SLE2496X	Policy No. (Claimant):	
		Excess:	
Repairer:	C. S. Ong Auto Pte Ltd (HQ) BLK 10 ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT, 568047 Ang Mo Kio - Tel: 64841933		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Wilson-KL]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 16/04/2018]		
Claimant's Solicitor:	RIAZ LLC - Tel: 65340110		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

















- AIG_SG (06/04/2018): NO OI GIA REPORT
- AIG_SG (06/04/2018): TP GIA REPORT

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH1223H (8771394637SG)
[SLE2496X]
TP
BOON YEN WEI
Mar 6 2018 3:00PM
[LCRF Pte Ltd]
C. S. Ong Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
2	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
3	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
4	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
5	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
6	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
7	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
8	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
9	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
10	25/04/18 15:09	General View	 Load JPG	<input checked="" type="checkbox"/>
11	25/04/18 15:09	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
12	25/04/18 15:09	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
13	25/04/18 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
14	25/04/18 15:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/04/18 14:51	TP GIA REPORT	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	12/04/18 15:15	E-filed GIA report OI GIA REPT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18006047/KQD3Q2

Date: 26/04/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994814
Claimant Vehicle No : SLH1223H **Insured Vehicle No :** SLE2496X
 Date of Loss: 06/03/2018 Nature of Claim: TP Claim No: 8771394637SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH1223H**
 Make & Model: TOYOTA SIENTA, 1.5 G CVT (A) Engine No: 2NR8677575
 Reg. Date: 25/10/2016 (Man. Year: 2016) Chassis No: NSP1707056016
 Colour: Green Odometer: 35300 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,277.56	1,247.50	5,030.06	80.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,550.00	1,010.00	2,540.00	71.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,827.56	2,257.50	7,570.06	77.03
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	9,827.56	1,800.00	8,027.56	81.68
+ GST 7.00/7.00% (S\$)	687.93	126.00	561.93	81.68
Nett Amount (S\$)	10,515.49	1,926.00	8,589.49	81.68

INSPECTION

Date of Assignment: 03/04/2018
 Date Inspected: 04/04/2018 Inspected At: C. S. Ong Auto Pte Ltd (HQ)
 BLK 10 ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT
 Singapore 568047
 Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAIL GATE	Bent	1,076.00 FL	*1,076.00 FL
2	1		*REAR TAIL GATE TOYOTA LOGO	Necessary	75.30 FL	*75.30 FL
3	1		*REAR TAIL GATE SIENTA PLATE WITH MLDG	Serviceable	256.80 FL	*- FL
4	1		*REAR TAIL GATE HYBRID EMBLEM	Necessary	70.50 FL	*70.50 FL
5	1		*REAR TAIL GATE RUBBER STOPPER & DAMPER ASSEMBLY	Serviceable	230.80 FL	*- FL
6	2		*REAR TAIL GATE LH & RH HINGES	Repair	119.46 FL	*- FL
7	1		*REAR TAIL GATE INNER TRIM BOARD COVER ASSEMBLY	Serviceable	158.50 FL	*- FL
8	1		*SET REAR TAIL GATE INNER TRIM BOARD COVER CLIP	Not Necessary	35.00 FL	*- FL
9	1		*REAR TAIL GATE INNER WEATHERSTRIP RUBBER	Serviceable	368.20 FL	*- FL
10	1		*REAR TAIL GATE INNER LOCK ASSEMBLY	Repair	361.60 FL	*- FL
11	1		*REAR TAIL GATE STRIKER LOCK	Repair	24.60 FL	*- FL
12	1		*REAR WINDSCREEN MLDG	Necessary	75.20 FL	*75.20 FL
13	2		*REAR RH & LH TAIL GATE LAMP	Serviceable	497.40 FL	*- FL
14	2		*REAR RH & LH TAIL GATE OUTER LAMP	Serviceable	694.00 FL	*- FL
15	1		*REAR BUMPER	Dented	278.00 FL	*278.00 FL
16	1		*REAR BUMPER LH SUPPORT GARNISH	Serviceable	214.00 FL	*- FL
17	1		*REAR BUMPER RH SUPPORT GARNISH	Serviceable	214.00 FL	*- FL
18	1		*REAR BUMPER CENTRE GARNISH	Serviceable	235.40 FL	*- FL
19	1		*REAR TOWING COVER	Serviceable	53.50 FL	*- FL
20	1		*SET REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
21	2		*REAR BUMPER SIDE RETAINER	Serviceable	184.66 FL	*- FL
22	2		*REAR BUMPER RH & LH REFLECTOR	Serviceable	140.10 FL	*- FL
23	1		*REAR END PANEL	Repair	374.00 FL	*- FL
24	1		*REAR END PANEL INNER TOP TRIM GARNISH	Serviceable	232.00 FL	*- FL
25	1		*SET REAR END PANEL INNER TOP TRIM GARNISH CLIPS	Not Necessary	35.00 FL	*- FL
26	1		*REAR SPARE TYRE PANEL	Repair	673.60 FL	*- FL
27	1		*REAR SPARE TYRE PANEL COVER BOARD	Serviceable	550.80 FL	*- FL
28	1		*SET REAR CAMERA	Serviceable	350.00 FS	*- FS
29	1		*SET REAR NUMBER PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
30	1		*SET REAR END PANEL SEALANTS	Not Necessary	100.00 FS	*- FS
31	2		*SET REAR RH & LH TAIL LAMP PANEL SEALANTS	Not Necessary	100.00 FS	*- FS
32	1		*SET REAR WINDSCREEN GLASS SEALANT	Necessary	100.00 FS	*40.00 FS
33	1		*SET REAR SPARE TYRE PANEL SEALANTS	Not Necessary	100.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	8,093.42	1,650.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,815.86	402.50
Total Parts (\$\$)	6,277.56	1,247.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE REAR WINDSCREEN TO FACILITATE REPAIR	New	200.00	120.00
2	TO CUT & REMOVE ALL REAR DAMAGED PANELS ,REPLACE NEW PARTS ,REFIT AND TO REALIGN ALL OF THE ABOVE ITEMS	New	1,500.00	400.00
3	TO PUTTY & RESPRAY NEW PAINTWORK ON ALL REAR AFFECTED AREAS	New	1,500.00	440.00
4	TO CONDUCT A CHECK ON ALL WIRING SYSTEMS	New	150.00	20.00
5	TO ANTI RUST ALL AFFECTED AREAS	New	200.00	30.00
Gross Labour Cost (\$\$)			3,550.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >