

10.04 @ 10.00 am

Survey & repair

a request LKK to survey
before 12pm

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

03 APR 2018

Estimate No.	: b1 46469	Page No. : 1 of 2
Date Estimated	: 03/04/2018	
Prepared By	: Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR -Angelvin Baby Lourdes Chee Parma
31 Tampines Street 34
#09-30

Singapore 529237

- ACCOUNT - 121AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE1616Y	V886024	30/05/2017	218iA/2	0

DESCRIPTIONVALUE

To replace front bumper and attachments.

850 ~~1,275.00~~

Painting front bumper.

934 ~~1,038.00~~

To check electrical wiring systems and lightings at the rear section for proper function.

150 ~~177.00~~

To replace tyre and wheel rim including balancing. (1x).

80 ~~94.00~~

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 ~~531.00~~

Sundries.

? 80.00

Total Labour 1: **3,195.00**DESCRIPTIONQTYPRICVALUE

Disc wheel I ✓ SCR

1 1,049.65 1,049.65

CLOSED GRID RH (SPORT) ✓ SCR ?

1 126.25 126.25

RH AIR INLET FINISHER BASIS ?

1 91.85 91.85

FRT BUMPER PANEL PRIMED SRA (SPORT) ✓ CUT

1 927.45 927.45

SET MOUNTING PDC/PMA SENSOR FRT ✓ NEC

1 30.35 30.35

DECOUPLING RING PDC TORQUE CONVERTE ✓ NEC

4 5.05 20.20

RR PDC SENSOR ALPINWEISS (300) ?

1 368.80 368.80

(DG/SL) ADHESIVE SET K6 ✓ NEC

1 53.05 53.05

Total Parts : **2,667.60**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46469
Date Estimated : 03/04/2018
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE1616Y	V886024	30/05/2017	218iA/2	0

Sebastian.
10/4/18.

- Part by part repair.
- Question Mark Item
Photo
- Photo Before Paint.

90036121

sebastianyeang@lkkauto.com

4 days.

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	3,195.00
Parts	:	2,667.60
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	410.38
Grand Total	:	6,272.98

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **