

22/09/2003

ASS. REC BY:

REF: CS3|SMO180D6050/R144d39

Special Instruction:

range 1 days

Surveyor:

ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMO

Date/Time: 3/4/18 @ 10:11am

Estimated Cost:

Bill to:

OD-TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 479S

Insured:

G8B4256T

at Workshop m/s:

Miracle Workz

Tel:

9647 2568

of

18 Toh Guan Rd East # 04-126

Policy No:

Claim No:

CMTD1801371 / GPL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:30am @ 3/4/18

Person Contacted:

Nicole

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

SLM 479S - X

G8B 4256T - X

Perman

ASSIGNMENT

From:

Date:

04/04/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No.

SLM 4795

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi

C.C

Colour

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading

85514

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAGU 2228V 7DA 057 083

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/35R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/03/18

D.O.I.

05/04/18

Survey held at

MIRACLE WORKS

1.28pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

* Repair Estimate : S\$ 14500 - 15500 -

* 4 days

27/4/18

Submit PRS Report

RECEIVED 30 APR 2018

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Photos:

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 3 April 2018 10:11 AM
To: Lheny; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Gnoh, Pau Loong
Subject: CMTD1801371/GPL - ACCIDENT INVOLVING GBB4256T & SLM479S ON 27.03.2018
Attachments: MW.pdf

Our Reference: CMTD1801371/GPL
Your Reference: CY. SLM479S.18.MW(HW).wp(Lh)

Without Prejudice

Date: 3rd April 2018

Attention:
M/S C YOGARAJAH LLC

Dear Lheny,

ACCIDENT INVOLVING GBB4256T & SLM479S ON 27.03.2018

We refer to your email reply dated 03/04/2018.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Lheny [<mailto:lheny@yoga-legal.com>]

Sent: Tuesday, April 03, 2018 9:53 AM

To: Teo, Grace

Cc: Gnoh, Pau Loong

Subject: RE: CMTD1801371/GPL - ACCIDENT INVOLVING GBB4256T & SLM479S ON 27.03.2018

WITHOUT PREJUDICE

Dear Grace Teo

We refer to your email on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Winson Goh
2. Amas Ong Poh Meng
3. Ong Ah Keng, Kent

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Best regards,

Lheny

M/s C YOGARAJAH LLC
883 North Bridge Road
#19-05 Southbank
Singapore 198785

Tel: 6292 5838

Fax: 6292 5938

Email: lheny@yoga-legal.com

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Tuesday, 3 April, 2018 9:50 AM

To: lheny@yoga-legal.com

Cc: Gnoh, Pau Loong

Subject: CMTD1801371/GPL - ACCIDENT INVOLVING GBB4256T & SLM479S ON 27.03.2018

Our Reference: CMTD1801371/GPL

Your Reference: CY. SLM479S.18.MW(HW).wp(Lh)

Date: 3rd April 2018

Without Prejudice
EMAIL ONLY

Attention:

M/S C YOGARAJAH LLC

Dear Lheny,

ACCIDENT INVOLVING GBB4256T & SLM479S ON 27.03.2018

We refer to your Notice of Accident dated 02/04/2018.

Please be informed that Gnoh Pau Loong the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

| | Motor Surveyor | Surveyor | Selection (Indicate as tick) |
|---|----------------------------------|---------------------------|------------------------------|
| 1 | Raleigh Services | Andrew Ow Yong | |
| | | Vincent Ng | |
| 2 | LKK Auto Consultants | Kenneth Kong (North area) | |
| | | Marcus Chua (East area) | |
| | | Mohd Rasul (West area) | |
| | | Mohd Taufikh (West area) | |
| 3 | Priority Services | Jimmy Lee | |
| | | Lawrence Ng | |
| | | Jeffery Ong | |
| 4 | JP Knights Adjusters & Surveyors | Jason Lek | |
| 5 | In House surveyor | Teo See Ling | |
| | | | |
| | | | |

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



CMTD1801371/GPL

883 North Bridge Road
#19-05 Southbank
Singapore 198785
T: 6292 5838
F: 6292 5938

(UEN No. 201333127N)
(GST Reg No. 201333127N)

Our Ref : CY.SLM479S.18.MW(HW).wp(Lh)

Your Ref : Your Insured vehicle **GBB 4256T**

02 April 2018

NEX GLOBAL ENGINEERING PTE LTD

c/o Motor Claims Department
Sompo Insurance Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

BY FAX (6221 3147) ONLY


Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLM 479S & GBB 4256T ON 27.03.2018 @ 18:40HRS ALONG JUNCTION OF YUAN CHING ROAD / BOON LAY WAY

We are instructed by MATCO ASIA SERVICES PTE LTD to notify you of a road traffic accident on 27.03.2018 @ 18:40hrs along junction of Yuan Ching Rd / Boon Lay Way involving our client's customer's vehicle registration number SLM 479S and vehicle registration number GBB 4256T driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


C. Yogarajah LLC
Enc

Cc: M/s. Miracle Works Pte Ltd
48 Toh Guan Road East
#04 - 126 Enterprise Hub
Singapore 608586
Nicole (82045858 / 96472568 / 64683096)
Fax no : 6515 5434

| | |
|---------------------------|--|
| SOMPO INSURANCE PTE. LTD. | |
| 02 APR 2018 | |
| | |
| | |
| | |



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | |
|---|--|-------------------------------|---|---|
| SOMPO INSURANCE SINGAPORE PL | | Ref: CS3/SMO18006050/R1z4d3s2 | | |
| 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623 | | Date: 04-05-2018 | |  |
| Code: SMO | | | | |
| 1. Policy Particulars :- (THIRD PARTY CLAIM) | | | | |
| Insured Veh. | GBB 4256T | Veh. Inspected | SLM 479S | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | CMTD1801371/GPL | Excess (\$) | 0.00 | |
| Assign From | GRACE TEO | Assign Date | 03/04/2018 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | AUDI | c.c | 0 | |
| Engine No. | HIDDEN | Year of Reg. | | |
| Chassis No. | WAUZZZ8V7DA057083 | Colour | WHITE | |
| Odometer | 85514 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/35R19 | GOODYEAR | 6 mm | |
| L/H Front Tyre | 225/35R19 | GOODYEAR | 6 mm | |
| R/H Rear Tyre | 225/35R19 | GOODYEAR | 6 mm | |
| L/H Rear Tyre | 225/35R19 | GOODYEAR | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. | | |  | |
| 5. General Information | | | | |
| Accident Date | 27/03/2018 | Inspect Date / Time | 05/04/2018 (01:28 PM) | |
| Survey held at | MIRACLE WORKZ PTE LTD 48 TOH GUAN ROAD EAST #04-126 ENTERPRISE HUB SINGAPORE 608586 | | | |
| 5a. Remarks | | | | |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$14,500-\$15,500 | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | | |

Report Ref No. CS3/SMO18006050/R1z4d3s2

Inspected By



MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.