

ASS. REC. BY:

REC: CS / FC18006059 / Gtd3 / 72

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Aung Yin Min

of

FCI

Date/Time: 02/04/2018 @ 5:45pm.

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLV 4080J

Insured:

SHD 8806Z

at Workshop m/s

S Three Automotive

Tel:

62841575

of

Blk 8, Sin Ming Ind. Est # 01-64/66

Policy No:

Claim No:

D18 002585MF5H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29/03/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

905am @ 3/4/18

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SLV 4080J - X
	SHD 8806Z - NSI INC 116/8825/H/g/k3
	D.O.A: 12/9/2011

Signature

REF:

Pci

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLV4080J

Yr Regn:

28 Dec 2017

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Grace 1.5 c.c. 1496

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

14694

T/Radio: Insured / Std / NI / NA

Eng/No:

G/No:

GM 41107.552

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60 R 15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

08-05-18

Survey held at

w/s

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/7

Finalized \$ 2050 with Jay. (Red. 4370.46.68%)

RECEIVED 12 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) b/A Typist

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

-

Survey Fee:

Transportation:

) S+RS. SI

) Photos

) Others

TOTAL

Add Fee:

☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)
☐ :

Report Format:

TP

Lump Sum / I.B.I. (\$ 2050) -

145

50

20

215

MOTOR SURVEY ASSIGNMENT

Date	02-04-2018	Our Ref No. D18002585MFSH
Accident Date	29-03-2018	Claim Type. Third Party
Insured Vehicle	SHD8806Z	Third Party Vehicle. SLV4080J
Survey Location	BLK 8 SIN MING INDUSTRIAL ESTATE #01-64/66	
Contact Person.	MS JOEY	
Contact No.	62841575/ 96620282	Fax No. 64875315
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	S THREE AUTOMOTIVE RECOVERY PTE LTD	Attention. NIL
Cc : TP Solicitor	LIBERTY LAW PRACTICE LLP	TP Solicitor Fax No. NA
Officer Incharge	AUNGYM	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236536)



PRI Documents



Close



PRI Header Details

Claim No	D18002585MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & LIBERTY L
Workshop Name	S THREE AUTOMOTIVE RECOVERY PTE LTD (Contact Person : MS JOEY)	Survey Location & Contact Details	BLK 8 SIN MING INDUSTRIAL ESTATE #01-64/66 Mobile: 96620282 , Phone: 62841575 , Fax: 6487531! EmailId: SERENE@LIBERTYLAW.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHD8806Z	TP Vehicle No	SLV4080J
PRI Recieved Date	02-04-2018 04:22:44 PM	Surveyor Appointed Date	02-04-2018 05:44:16 PM	Surveyor Accept Date	03-04-2018 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	03-04-2018	Upload Survey Report *:	Choose File
-----------------------------	----------------------	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Identification Card

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8321489I



Name
KWOK ZHEN WANG
(GUO ZHENWANG)
郭 振 旺

Race
CHINESE

Date of birth
17-06-1963

Sex
M

Country/Place of birth
SINGAPORE



Card No. S8321489I



Date of issue
01-07-2016

Address
APT BLA 201 JUNONG EAST STREET 21
#01-103
SINGAPORE 605201

Driving License

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8740120J



Name

SHARON LEONG HUI SHAN
(LIANG HUI SHAN)

梁慧珊

CHINESE

Date of Birth

15-12-1987

Country of Birth

SINGAPORE

Sex

F

S8740120J

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number S8740120J

Name

SHARON LEONG HUI SHAN
(LIANG HUI SHAN)

Valid From 15 Dec 1987

Valid Until 18 Oct 2011



4811177

NPIC No. S8740120J



Date of Issue

02-06-2010


Address

23 TENG TONG ROAD
SINGAPORE 428514

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

EFFECTIVE DATE

Class 3A Motor cars without clutch pedals (Auto) <= 2000cc 21 Dec 2009
with <= 7 passenger seats, excluding of the driver; and
other motor vehicles without clutch pedals <= 2500kg



NP 425A

STHREE AUTOMOTIVE RECOVERY PTE LTD

Blk B Sin Ming Industrial Estate
#01-64/66 Singapore 575643
Tel : 6284 1542 / 6284 1575
Fax : 6487 5315
sthreeautomotive@gmail.com

TO :
ATTN : **MOTOR CLAIM DEPT.**

T/P VEH. NO. : **SHD8806Z**

ESTIMATE REPOJ 1st QUOTATION
OWNER'S PARTICULAR

JOB NO. : _____

NAME : **KWOK ZHEN WANG**
ADDRESS : _____

CONTACT : **9776 8357**

LICENSE NO. : **SLV4080J** TRANS.
MAKE / MODEL : **HONDA GRACE**
OWNER'S INSUR : **NTUC**
JOB-CODE **TP** S/A : **JOEY**

CHASSIS NO : **GM41107552**
ENGINE NO : _____

ACCIDENT DATE : **31-Mar-18**

CLAIM DETAIL

MATERIALS

	QTY	QUO-PRICE	DISC. %	DISC- PRICE	SUR. DISP	REV. PRICE
1 FRT BUMPER / <i>Cut</i>	1.00	810.80	/ 20.00	648.64	Y	_____
2 FRT BUMPER BRACKET LH X <i>NN</i>	1.00	35.00	20.00	28.00	Y	_____
3 FRT BUMPER BRACKET RH X <i>NN</i>	1.00	35.00	20.00	28.00	Y	_____
4 FRT BUMPER SIDE RETAINER LH X <i>NN</i>	1.00	25.00	20.00	20.00	Y	_____
5 FRT BUMPER SIDE RETAINER RH X <i>NN</i>	1.00	25.00	/ 20.00	20.00	Y	_____
6 FRT BUMPER REINFORCEMENT X <i>NN</i>	1.00	237.60	20.00	190.08	Y	_____
7 FRT GRILLE X <i>NN</i>	1.00	250.55	20.00	200.44	Y	_____
8 FRT GRILLE CHROME MLDG X <i>NN</i>	1.00	268.50	20.00	214.80	Y	_____
9 FRT GRILLE LOGO X	1.00	30.00	20.00	24.00	Y	_____
10 HEADLAMP RH HID / <i>Scr</i>	1.00	1383.20	/ 20.00	1106.56	Y	_____
11 FRT FENDER RH X <i>Repair</i>	1.00	374.22	20.00	299.38	Y	_____
12 FRT SUPPORT PANEL ASSY X <i>NN</i>	1.00	455.00	20.00	364.00	Y	_____
13 FRONT FENDER INNER SHIELD RH X <i>NN</i>	1.00	78.20	20.00	62.56	Y	_____
14 FRONT WHEEL COVER RH X <i>NN</i>	1.00	280.00	20.00	224.00	Y	_____

TOTAL (PARTS) :

2219

4288.07

175.2

3430.46

SPECIAL NETT ITEM

1 FRT BUMPER CLIPS (1 SET) / <i>McL.</i>	1.00	50.00	/ 0.00	50.00	Y	_____
2 FRT FENDER INNER SHIELD CLIPS (1 SET) X <i>NN</i>	1.00	X 50.00	0.00	50.00	Y	_____
3 FRT NUMBER PLATE X <i>NN</i>	1.00	X 50.00	0.00	50.00	Y	_____

TOTAL (PARTS) :

150.00

150.00

LABOUR

1 STRENGTHEN & PANEL BEAT ACCIDENT AREA	1.00	1200.00	0.00	1200.00	Y	<i>200</i>
2 SPRAY PAINTING ON ACCIDENT AREA	1.00	1100.00	0.00	1100.00	Y	<i>500</i>
3 R&R AC CONDENSOR & CHARGE UP GAS	1.00	150.00	0.00	150.00	Y	<i>X NN</i>
4 RESPRAY TUFF KOTE ON ACC AREAS	1.00	150.00	0.00	150.00	Y	<i>X NN</i>
5 CHECK & REPAIR WIRING SYSTEM	1.00	120.00	0.00	120.00	Y	<i>30</i>
6 COMPUTERISED WHEEL ALIGNMENT	1.00	120.00	0.00	120.00	Y	<i>X NN</i>

TOTAL (LABOUR) :

2840.00

2840.00

730

TOTAL PARTS & LABOUR

7278.07

6420.46

2555.2
20%: 2050

EXCESS : S\$ _____

NO. OF DAY : 3

RE-SURVEY : BEFORE / AFTER PAINTING 0

PART-BY-PART OR LUMP-SUM : S\$ _____

DATE OF SURVEY : 8 / 5 / 2018

SURVEY BY : Guo Qifeng

CONTACT : _____

FAX NO : _____

NOTE : LUMP-SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006059/Gtd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 12-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 8806Z	Veh. Inspected	SLV 4080J	
Policy No.	D-18088937MFSH	Coverage (\$)	0.00	
Claim No.	D18002585MFSH	Excess (\$)	0.00	
Assign From	AUNGYM	Assign Date	02/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA GRACE 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	GM41107552	Colour	WHITE	
Odometer	14694	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/03/2018	Inspection Date	08/05/2018	
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 4080J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER	CUT	810.80	810.80
1	FRT BUMPER BRACKET LH	NOT NECESSARY	35.00	-
1	FRT BUMPER BRACKET RH	NOT NECESSARY	35.00	-
1	FRT BUMPER SIDE RETAINER LH	NOT NECESSARY	25.00	-
1	FRT BUMPER SIDE RETAINER RH	NECESSARY	25.00	25.00
1	FRT BUMPER REINFORCEMENT	NOT NECESSARY	237.60	-
1	FRT GRILLE	NOT NECESSARY	250.55	-
1	FRT GRILLE CHROME MLDG	NOT NECESSARY	268.50	-
1	FRT GRILLE LOGO	NOT NECESSARY	30.00	-
1	HEADLAMP RH HID	SCRATCHED	1,383.20	1,383.20
1	FRT FENDER RH	TO REPAIR SEE LABOUR	374.22	-
1	FRT SUPPORT PANEL ASSY	NOT NECESSARY	455.00	-
1	FRONT FENDER INNER SHIELD RH	NOT NECESSARY	78.20	-
1	FRONT WHEEL COVER RH	NOT NECESSARY	280.00	-
	LESS 20% DISCOUNT		-857.61	-443.80
			3,430.46	1,775.20
SPECIAL NETT ITEMS				
1	SET FRT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	SET FRT FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRT NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
			150.00	50.00
LABOUR				
	STRENGTHEN & PANEL BEAT ACCIDENT AREA.INCLUSIVE OF THE REPAIR OF FRT FENDER RH.		1,200.00	200.00
	SPRAY PAINTING ON ACCIDENT AREA.		1,100.00	500.00
	R&R AC CONDENSOR & CHARGE UP GAS.	NOT NECESSARY	150.00	-
	RESPRAY TUFF KOTE ON ACC AREAS.	NOT NECESSARY	150.00	-
	CHECK & REPAIR WIRING SYSTEM.		120.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	COMPUTERISED WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
			2,840.00	730.00
GRAND TOTAL			6,420.46	2,555.20
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,050.00

Report Ref No. CS/FC118006059/Gtd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.