

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890354/AMK

Date: 06 Apr 2018

Policy No: DMPCSN3008751800

Veh Reg No: SLV6435G

Make/Model: SUBARU FORESTER
 2.0V AWD A

Chassis No: JF1SH5KS59G020629

Engine No: EJ20D714953

Reg. Date: 26/10/2009

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 30/03/2018

TP Veh Reg No: SGL72X

Not Authorised

11 Lyr B?

Re-spray After Paint

9 days

Estimate Repair Cost to Vehicle No :SLV6435G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	620.30	1 PC	<i>CM</i> 620.30	<i>✓</i>
2 REAR BUMPER REINFORCEMENT	232.30	1 PC	<i>B</i> 232.30	<i>✓</i>
3 REAR BUMPER LH SIDE RETAINER	19.10	1 PC	<i>Dir</i> 19.10	<i>✓</i>
4 REAR BUMPER TOW HOOK COVER	17.20	1 PC	<i>mis</i> 17.20	<i>✓</i>
5 REAR BUMPER CLIP	3.90	5 PC	<i>me</i> 19.50	<i>✓</i>
6 REAR TAILGATE	1,192.30	1 PC	<i>B</i> 1,192.30	<i>✓</i>
7 TAILGATE INNER LOCK	200.30	1 PC	<i>me</i> 200.30	<i>✓</i>
8 TAILGATE INNER RUBBER	136.50	1 PC	<i>cut</i> 136.50	<i>50 & 20</i>
9 TAILGATE LOGO	62.90	1 PC	<i>me</i> 62.90	<i>✓</i>
10 TAILGATE EMBLEM 'SUBARU'	65.80	1 PC	<i>me</i> 65.80	<i>✓</i>
11 TAILGATE EMBLEM 'FORESTER'	64.20	1 PC	<i>me</i> 64.20	<i>✓</i>
12 TAILGATE WINDSCREEN GLASS MOULDING	86.00	1 SET	<i>me</i> 86.00	<i>✓</i>
13 REAR END PANEL	332.00	1 PC	<i>B</i> 332.00	<i>✓</i>
14 REAR END PANEL INNER TOP GARNISH	72.60	1 PC	<i>me</i> 72.60	<i>✓</i>
15 REAR FENDER LH INNER SHIELD	304.00	1 PC	<i>Dir/4mm</i> 304.00	<i>✓</i>
16 REAR LH FENDER INNER SHIELD CLIP	4.30	6 PC	<i>me</i> 25.80	<i>✓</i>
17 REAR LH EXHAUST PIPE	688.35	1 PC	<i>R</i> 688.35	<i>?</i>
18 REAR SPARE TYRE COMPARTMENT	492.80	1 PC	<i>R</i> 492.80	<i>?</i>
19 REAR LH FENDER INNER GARNISH	304.00	1 PC	<i>CM</i> 304.00	<i>✓</i>
			4,935.95	
		Less 20%	987.19	3,948.76
Special Net				
20 REVERSE SENSOR	200.00	1 SET	<i>Tu</i> 200.00	<i>✓</i>
21 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	<i>me</i> 40.00	<i>✓</i>
			240.00	240.00
Labour				
22 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	<i>✓</i>
23 REMOVE & REFIX REAR EXHAUST & ETC	60.00	1 LA	60.00	<i>✓</i>
24 REMOVE & REFIX REAR BUMPER, TAILGATE & ATTACHMENTS, TAILLAMPS; TO CUT, WELD & RENEW REAR END PANEL, REAR SPARE TYRE PANEL, KNOCKING & REPAIR REAR FENDERS & REALIGN THE SAME	1,400.00	1 LA	1,400.00	<i>1200</i>
25 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR FENDERS, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AREAS	1,100.00	1 LA	1,100.00	<i>1000</i>
26 RUSTPROOFING	90.00	1 LA	90.00	<i>60</i>

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 30/03/2018
TP Veh Reg No: SGL72X

Estimate No: ES1890354/AMK
Date: 06 Apr 2018
Policy No: DMPCSN3008751800
Veh Reg No: SLV6435G
Make/Model: SUBARU FORESTER
2.0V AWD A
Chassis No: JF1SH5KS59G020629
Engine No: EJ20D714953
Reg. Date: 26/10/2009

Estimate Repair Cost to Vehicle No :SLV6435G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
27 REMOVE & REFIX REAR SEAT,CARPET TO FACILITATE REPAIR	120.00	1 LA	120.00	100
			2,890.00	2,890.00
			Total	S\$ 7,078.76
			Add GST @ 7%	495.51
			Total Amount Payable	<u><u>S\$ 7,574.27</u></u>

VEHICLE LYING AT :
NO.10 ANG MO KIO INDUSTRIAL PARK 2A
#01-04 AMK AUTOPOINT
SINGAPORE 568047
TEL : 64812001

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

DORLYN LI

AUTHORISED SIGNATURE