

SMRT Accident Vehicle Repair Estimates

TH

Cell 17

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB509U
 Ref. No : TAX/04/18/2007
 Reg. Date : 07/10/2014
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : RYAN FOO CHEE BOON
 Type of Accident : HEAD TO SIDE
 Date / Time of Accident : 02/04/2018 11:00:00 AM
 Accident Reported Date / Time : 02/04/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 02/04/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024095326
 Special Instruction to ARC,if any :
 TOWED \$40/ SHB4335C(COMFORT)
 Prepared Date : 02/04/2018 02:33:58 PM



*Sebastian.
 3/4/18.
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Paint.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U505752141

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,674.00	0.00
Total Material Charges	: 10,549.90	10,549.90
Other Charges	: 1,528.44	0.00
TOTAL	: 14,766.34	0.00
Lum Sum Total	: 14,750.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sing Off Date	: 02/04/2018 05:17:31 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/04/2018 05:16:07 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH FRONT PORTION	1,014.00	0.00 500
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
TO REPSRAY FRONT HOOD	378.00	0.00 X
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 50
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 X
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	80.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO TOP UP A/C GAS	120.00	0.00 X
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO CHECK & RESET SYSTEM FUNCTION	350.00	0.00 X
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	148.44	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,528.44	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
2119-17930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace ✓ CRK	No
2127-17903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.87	Replace	Replace R	No
2115-17040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace ?	No
2611-17080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ✓ CRK	No
2021-17023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ✓ DT	No
17013-17030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace ?	No
2114-17140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace ?	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace X	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace ✓ CRK	No
3102-17020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace ✓ CRK	No
1210-2230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace ✓ CRK	No
1519-17050			BRACKET, FR TURN LOWER RH	1	26.00	25.00	19.50	Replace	Replace ?	No
1519-17060			BRACKET, FR TURN UPPER RH	1	24.40	25.00	18.30	Replace	Replace ?	No
1511-17050			LENS & BODY, FR TURN RH	1	511.80	10.00	460.62	Replace	Replace ✓ CRK	No
2618-17050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace ?	No
2113-17180			WIRE, ENGINE ROOM, NO.3	1	242.00	10.00	217.80	Replace	Replace ?	No
3301-17060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace X	No
3395-17020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace X	No
3201-17902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace R	No
1130-17500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace ✓ SCR	No
2111-1772			WIRE, ENGINE ROOM	1	5,567.10	10.00	5,010.39	Replace	Replace ?	No
5315-17140			WIPER WASHER JAR	1	180.10	25.00	135.07	Replace	Replace ✓ De fou	No
5330-17010			MOTOR NO:1, WIPER WASHER JAR	1	239.00	10.00	215.10	Replace	Replace ?	No
5330-170180			MOTOR NO:2, WIPER WASHER JAR	1	240.00	10.00	216.00	Replace	Replace ?	No
5371 / 10099-2091			HOSE, WINDSHIELD WASHER (FROM MOTOR TO JOINT)	1	17.60	25.00	13.20	Replace	Replace X	No
3710-17150			TUBE & ACCESSORY	1	631.90	25.00	473.92	Replace	Replace X	No
3876-17030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace X	No
3801-17050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace R	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
75374-17051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓	No <i>NE</i>
53875-17030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace ✓	No <i>707</i>
53852-17020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace X	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
12611--17140 Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace X	No
TOTAL MATERIALS								13,187.44	13,187.38	
TOTAL MATERIALS(Discounted)								10,549.90	10,549.90	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									