

REPA-IRESTIMATE*

VEHICLE NO : SHC 1923U

DATE 2/4/2018 11:37

MAKE :

MODE L : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Panel			\$ 391.80
	Rear Panel Garnish			\$ 95.80
	SUB TOTAL			\$ 1,894.50
	LESS 20%			\$ 378.90
	DISCOUNTED TOTAL			\$ 1,515.60
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Bumper Rubber Mat			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
				\$ 435.70
	Labour Charge			
	Panel Beating			\$ 250.00
	Spray Painting Charge-Bumper/Rear Panel			\$ 500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 970.00
	ESTIMATE TOTAL			\$ 2,921.30
	Kalvin (KCK)			
	M 2/4/18 1245hrs			
	2 Pys			
	U/S			
	After Repair p 4			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.