

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

QBE

VEHICLE NO : SHA 4335H

DATE 2/4/2018 16:01

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Radiator Grille X <i>repair</i>			\$ 282.10	
	Radiator Grille U Moulding X <i>repair</i>			\$ 108.90	
	Headlamp (RH) X <i>repair</i>			\$ 797.90	
	Front Door Glass (LH/RH) X <i>repair</i>		\$ 363.70	\$ 727.40	
	SUB TOTAL			\$ 1,916.30	
	LESS 20%			\$ 383.26	
	DISCOUNTED TOTAL			\$ 1,533.04	
	Front Fender Advertisement Logo (LH/RH) X		\$ 100.00	\$ 200.00	Nett
	Front Door Comfort Logo (LH/RH) X		\$ 75.00	\$ 150.00	Nett
				\$ 350.00	
	Labour Charge				
	Panel Beating			\$ 750.00	X
	Spray Painting Charge-Roof Top Panel/Doorx2/Bonnet/Bumper/Fenderx2			\$ 750.00	X
	Wiring Charge			\$ 50.00	X
	Tuff Kote			\$ 50.00	X
	Remove/Refix Roof Top Taxi Digital Sign			\$ 250.00	X
	TOTAL LABOUR			\$ 1,850.00	
	ESTIMATE TOTAL			\$ 3,733.04	
	<i>can be wash away.</i>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

COMFORTDELGRO ENGINEERING PTE LTD

VEHICLE NO : SHA 4335H

DATE 2/4/2018 15:35

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid <i>x rep</i>			\$ 1,349.50	
	Boot Lid Sonata Plate			\$ 43.60	
	Boot Lid Hyundai Plate			\$ 24.20	
	Boot Lid 'H' Emblem			\$ 26.10	
	Boot Lid CRDI Plate			\$ 22.70	
	Boot Lid Lamp (LH/RH) <i>x</i>		\$ 230.20	\$ 460.40	
	Licence Lamp (LH/RH) <i>x</i>		\$ 32.50	\$ 65.00	
	Rear Bumper			\$ 578.40	
	Rear Bumper Clip			\$ 22.00	
	Tail Lamp (LH/RH) <i>LH x RHV</i>		\$ 344.00	\$ 688.00	
	Rear Fender (RH)			\$ 1,935.90	
	Rear Fender Inner Lining (RH) <i>x</i>			\$ 74.10	
	Rear Windscreen Moulding			\$ 60.00	
	Rear Door Glass (LH/RH) <i>x wash</i>		\$ 241.60	\$ 483.20	
	SUB TOTAL			\$ 5,833.10	
	LESS 20%			\$ 1,166.62	
	DISCOUNTED TOTAL			\$ 4,666.48	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett
	Rear No. Plate <i>x</i>			\$ 25.00	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Bumper Rubber Mat			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
	Rear Windscreen Sealant			\$ 46.00	Nett
	Rear Door Tel No. Sticker (LH/RH) <i>x</i>		\$ 10.00	\$ 30.00	Nett
				\$ 431.00	
	Labour Charge				
	Panel Beating			\$ 750.00 ⁶⁰⁰	
	Spray Painting Charge-Bootlid/Bumper/Fenderx2/Doorx2 <i>x</i>			\$ 1,500.00 ⁶⁰⁰	
	Wiring Charge			\$ 50.00 ²⁰	
	Tuff Kote			\$ 50.00 ²⁰	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 ⁵⁰	
	Remove/Refix Rear Windscreen Glass			\$ 120.00 ¹⁰⁰	
	Remove/Refix Reverse Sensor			\$ 120.00 ²⁰	
	TOTAL LABOUR			\$ 2,740.00	
	ESTIMATE TOTAL			\$ 7,837.48	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Kalvin (LKK)
2/4/18 16:15h
3 Days
L/S After Repair p/l

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.