

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ernest Tay

Date: 19 Apr 2018

## **Preliminary Advice**

Insured Vehicle No : SHD340C

TP Vehicle No : SKT620M

Make : BMW 230I

Date of Inspection : 18/04/2018

Inspection At : PERFORMANCE MOTORS LTD

Accident Date : 27/03/2018

Assignment Date : 02/04/2018

Est. Duration of Repair : 3/Days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 6,108.70 |
| Revised Amount              | :S\$ | 3,519.50 |
| Check Items (Estimated)     | :S\$ | 1,923.20 |
| Total                       | :S\$ | 5,442.70 |

Lump Sum Repair :S\$

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :We have not authorized repairs.