

Wed 18/04 @ 10am
P & R

SLT620M

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

27 MAR 2018

Estimate No.	: b1 46401	Page No. : 1 of 2
Date Estimated	: 27/03/2018	
Prepared By	: Han Kwan Yong	

- ESTIMATE REPAIR FOR - Lee Kok Leong (Li Guoliang) 65 Chestnut Avenue #24-21 Singapore 679524	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT620M	VB27316	27/10/2017	230iA/2	0

DESCRIPTION	VALUE
To replace rear bumper & attachments including to knock out dented area caused by the accident	850 1,275.00
To respray rear bumper and lower apron cover	1337.45 1,486.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150 177.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Cust comments: After accident 'Drive Train' warning light 'on'. - To diagnose 'Drive Train' warning light 'on' including to reset and check for proper function	? 177.00
Sundries.	? 80.00
Total Labour 1:	3,372.00

DESCRIPTION	QTY	PRIC	VALUE
# SET MOUNTS PDC SENSOR REAR (	1	62.95	? 62.95
REAR BUMPER CARRIER	1	385.25	? 385.25
# REAR GUIDE CENTRE	1	41.45	? 41.45
# REAR BUMPER INSERT (M)	1	283.10	? 283.10
# FLAP TOWING EYE PRIMED (M)	1	38.00	Rx 38.00
# REAR BUMPER PANEL PRIMED (M)	1	956.35	des 956.35
# HEAT INSULATION REAR SILENCE CLIP	1	58.30	? 58.30
# EXTENSION FLOORPAN COVER SID	10	1.30	net 13.00
# RH REFLECTOR	1	62.35	? 62.35
DECOUPLING RING PDC TORQUE CONVERTE	1	35.20	? 35.20
PDC SENSOR MINERALWEISS (A96)	2	5.05	net 10.10
(DG/SL) ADHESIVE SET K6	2	368.80	? 737.60
	1	53.05	net 53.05

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T EEstimate No. : b1 46401
Date Estimated : 27/03/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLT620M	VB27316	27/10/2017	230iA/2	0

Total Parts : 2,736.70

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. <u>18/4/18</u>	Claim No. _____
Date&Time <u>18/4/18</u>	Excess S\$ _____
Surveyor's Name <u>Han Kwan Yong</u>	Sign <u>[Signature]</u>
Surveyor's Tel <u>97415749</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR ☒ / No ☐ PML Yes / No _____	
Surveyor's E-mail <u>han.kwan.yong@lkkauto.com</u>	
No. of Working Days Recommend <u>03 days</u>	

Labour 1	:	3,372.00
Parts	:	2,736.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	427.61
Grand Total	:	6,536.31

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **