

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9880B**AAD1803-248***Not Notarized
61 Sep 831001*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHD 9880B
VF1ABL15AUC277534
RENAULT
LATITUDE
27.3.2018
AXA

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68
1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 151.41
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21
1	BUMPER BEAM FRT	\$	<i>Sn</i> 914.08
1	HEADLAMP RH <i>LH</i>	\$	<i>Wt / my car</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT <i>BH</i>	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT <i>BH</i>	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT <i>BH</i>	\$	<i>Sn</i> 278.84 X
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>Sn</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46

TOTAL	\$	16,191.51
10%	\$	1,619.15
	\$	14,572.36

Trans-cab Auto Services Pte Ltd

AAD1803-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9880B

Specical Nett

1SET	BUMPER CLIP FRT	\$	net 66.00	✓
1	BUMPER BRACKET CLIP FRT RH	\$	nn 12.00	}
1	BUMPER SUPPORT CLIP FRT RH	\$	nn 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	nn 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	nn 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	nn 30.00	} X
1SET	WHEELARCH CLIP FRT RH	\$	nn 30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn 80.00	
1	FRONT DOOR STICKER 'Chassis'	\$	nn 50.00	

TOTAL \$ 438.00**TOTAL PARTS \$ 15,010.36****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,500.00	400
Putty and spray painting of the affected portion.	\$	3,000.00	400
To rust-proofing of the affected areas.	\$	170.00	30
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	* 20

Trans-cab Auto Services Pte Ltd

AAD1803-248

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9880B

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>nn</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00 X

TOTAL	\$	8,710.00
--------------	-----------	-----------------

Over All Total	\$	23,720.36
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)

~~10 DAYS~~

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: