



LIM YEW BOO SPRAY PAINT CO.

Blk 10, Sector C, #01-10, Sin Ming Ind. Est. Singapore 575645
No. 176, Sin Ming Drive, #03-05, Sin Ming AutoCare, Singapore 575721
Tel: 6453 4177 Fax: 6459 3724
Email: limyewboo@singnet.com.sg
Company Reg. No. : 200514/00L

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01
AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
Contact : 63387288 Fax No. : 68804838

Estimate : TP18/018

Date : 03/04/2018

Vehicle Num. : SKE 506B

Make/Model : TOYOTA PRIUS AUTO-2011

Chassis/Eng# : JTDKN36U401427231/2ZR516311

Accident Date : 26/03/2018

Claim No. :

Reference : LYB/SKE506/AXA/tp/sy

Policy No. :

*Not Authorized
Resurvey By repair
2 days*

S/N	Quantity	Particular	Unit Price	Amount S\$
1.	1	LIST ITEMS :		
2.	1	REAR BUMPER		463.60
		REAR BUMPER RETAINER		96.10
		List TotalS\$:		559.70
		25.00% Discount S\$:		139.93
				419.77
1.	1SET	SPECIAL NETT ITEMS :		
		REAR REVERSE SENSOR		250.00
		Special Nett Total S\$:		250.00
		LABOUR :		
		LABOUR TO REPLACE THE SENSOR & CHECK SENSOR FUNCTIONS		80.00
		TO REPAIR,PANEL BEAT ON REAR AFFECTED AREA.		300.00
		LABOUR CHARGE FOR REPLACE THE ABOVE-MENTIONED PARTS		
		TO PUTTY,PRIMER TO SPRAY ON REAR BUMPER,SENSOR USING		
		2K PAINT.		400.00
		Labour Total S\$:		780.00
		E. & O.E.	Total S\$:	1,449.77

for LIM YEW BOO SPRAY PAINT CO.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

All cheques should be crossed and made payable to
Lim Yew Boo Spray Paint Co.

Customer

E. & O. E.