



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HWEE HUAT
BLK 197 RIVERVALE DRIVE #17-703
SINGAPORE 540197

Attention : THE OWNER
Contact : 92364316

Estimate : ES006300

Date : 31/03/2018
Vehicle Num. : SLH6013P
Make/Model : HONDA VEZEL 1.5X A-2016
Chassis/Eng# : RU11203110/L15B4402884
Accident Date : 30/03/2018
Claim No. :
Reference :
Policy No. :

Not Authorized
Call Log 8, 1.B.1
8-10 day,

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	TAIL GATE		1,280.00 ✓
2.	2	TAIL GATE HINGE	185.00	370.00 X
3.	1	TAIL GATE W/SCREEN GLASS MOULDING		125.00 ✓
4.	2	TAIL GATE REFLECTOR	240.00	480.00
5.	1	TAIL GATE INNER TRIM		285.00 ?
6.	6	TAIL GATE INNER TRIM CLIP	4.50	27.00 ?
7.	1	TAIL GATE INNER LOCK		189.00 ✓
8.	1	TAIL GATE LOCK CATCH		25.00 X
9.	1	TAIL GATE RUBBER SEAL		166.80 ?
10.	2	TAIL GATE SHOCK ABSORBER	110.00	220.00 X
11.	1	VEZEL EMBLEM		68.00 ✓
12.	1	REAR BUMPER		883.00 ✓
13.	2	REAR BUMPER BRACKET	48.00	96.00 ?
14.	2	REAR BUMPER REFLECTOR	131.50	263.00 ✓
15.	1	REAR BUMPER SIDE PAD R/H		215.00 ✓
16.	2	REAR BUMPER SIDE RETAINER	35.00	70.00 ✓
17.	6	REAR BUMPER CLIP	4.50	27.00 ✓
18.	1	REAR FENDER R/H		1,152.00 ✓
19.	1	REAR FENDER OUTER GARNISH R/H		185.00 ✓
20.	1	REAR FENDER 1/4 GARNISH R/H		169.00 ?
21.	1	REAR FENDER MUDFLAP R/H		152.00 X
22.	1	REAR FENDER SPLASH SHIELD R/H		160.00 X
23.	4	REAR FENDER SPLASH SHIELD CLIP	4.50	18.00 X
24.	1	REAR END PANEL		688.30 ✓
25.	1	REAR END PANEL TOP GARNISH		182.30 ?
26.	4	REAR END PANEL TOP GARNISH CLIP	4.50	18.00 ?
27.	1	REAR FLOOR CORNER PANEL R/H		363.00 ?
28.	1	REAR CHASSIS FRAME R/H		896.20 ?
29.	1	SPARE TIRE PANEL		1,130.60 ?

CONTINUE / ...

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HWEE HUAT
BLK 197 RIVERVALE DRIVE #17-703
SINGAPORE 540197

Attention : THE OWNER
Contact : 92364316

Estimate : ES006300

Date : 31/03/2018
Vehicle Num. : SLH6013P
Make/Model : HONDA VEZEL 1.5X A-2016
Chassis/Eng# : RU11203110/L15B4402884
Accident Date : 30/03/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

30.	1	SPARE TIRE PANEL TOP BOARD		452.00	✓
31.	1	EXHAUST SILENCER BOX		588.00	✓
32.	1	EXHAUST CHROME PIPE		188.00	✓
33.	1	EXHAUST MOUNTING		20.50	✓
34.	1	TAIL LAMP R/H		650.00	✓
35.	1	SPARE TIRE PANEL UNDER COVER GARNISH		326.00	✓
36.	6	SPARE TIRE PANEL UNDER COVER GARNISH CLIP	4.50	27.00	✓
37.	1	REAR END PANEL ANTENNA KEY SENSOR		182.00	✓
38.	1	TAIL LAMP PANEL R/H		363.00	✓
39.	1	REAR PANEL BUZZER		169.00	✓

List TotalS\$:	12,869.70
20.00% Discount S\$:	2,573.94
	10,295.76

1.	1	TAIL GATE W/SCREEN GLASS SEALANT		65.00	✓
2.	1	REVERSE SENSOR SET		280.00	✓
3.	1	REAR NUMBER PLATE HOLDER		33.00	✓
4.	1	REAR NUMBER PLATE		25.00	✓

Special Nett Total S\$:	403.00
--------------------------	--------

LABOUR :	
REMOVE & REINSTALL TAIL GATE W/SCREEN GLASS	120.00
TRANSFER TAILGATE COMPONENT TO NEW GATE	60.00
REMOVE & REINSTALL R/H UPHOSTERY, REAR SEAT AND BELT	100.00
REMOVE & REINSTALL ROOF LINING SIDE GARNISH	120.00
REMOVE & REINSTALL EXHAUST SILENCER BOX	60.00
CHANGE TAIL LAMP AND CHECK LIGHTING	20.00

CONTINUE / ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

LEE HWEE HUAT
BLK 197 RIVERVALE DRIVE #17-703
SINGAPORE 540197

Attention : THE OWNER
Contact : 92364316

Estimate : ES006300

Date : 31/03/2018
Vehicle Num. : SLH6013P
Make/Model : HONDA VEZEL 1.5X A-2016
Chassis/Eng# : RU11203110/L15B4402884
Accident Date : 30/03/2018
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO CUT OFF REAR END PANEL, TAIL LAMP PANEL R/H, REAR R/H FENDER, REAR R/H CHASSIS FRAME, REAR R/H CORNER FLOOR PANEL, SPARE TIRE PANEL, AND CHANGE ALL NECESSARY PARTS		
		RUST PROOFING TREATMENT		1,600.00
		SPRAY PAINT DAMAGED AREA AFFECTED		100.00
				1,100.00
		Labour Total S\$:		3,595.00

SingDollars : Fourteen Thousand Two Hundred Ninety-Three & Cents Seventy-Six Only

Total S\$: 14,293.76
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun