

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

2-Apr-18

REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8838 S

1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
1 pc	Rear bumper inner sponge ?	\$	114.00
1 pc	Rear bumper o/s reflector ✕	\$	46.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✕	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✕	\$	36.00
		\$	1,134.00
		Less 10%	\$ 113.40
		\$	1,020.60

S/NETT

1 set	Rear bumper clips ✓	\$	48.00
	Sundry	\$	50.00 ✕
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	80.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 ✕
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same	\$	500.00 200
	To putty and spray painting on rear bumper	\$	250.00 180
		\$	2,128.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin (LKK)

3/4/18 1320 hrs

2 pgs

L/S

After Repair photo