



QUOTATION

KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: MSIG INSURANCE (SINGAPORE) PTE 16 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	Document No.	: SQT18001358	Page	2
Registration No	: SKU3258M	Date	: 2. Apr 2018	Customer No.	: WM003
Chassis No	: MRHRU1810FP000024	Svc Advisor	: ARY CHUA WAI NGEE	Engine No	: L15Z71000240
Model	: HRV DX-SIN CVT YM 2015	Date Time	: 2. Apr 2018 11:07:19 PM	Surveyor Name	:
Owner's Name	: MYLENE PHUA SWEE MAY	Survey Date	: DID : +65 6845 5673 HP : +65 8100 6306	Authorisation Date	: Email : arychna@honda.com.sg
Ins Policy No.	: EXTERNAL LABOUR SALE				
Date of Accident	: 26/4/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Survey By	<u>Marcus Loh</u>						
Date & Time	<u>4/4/18</u>				Total Amount	6,227.08	435.89
Excess	<u>8500</u>				Total (Inclusive of GST)		6,662.97
Status	<u>not submit</u>						
Signature	<u>before photo before repair, 4 days.</u>						



before photo before repair,
4 days.

for o/s.

Fax 62564315

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/4/2018 3:23:59 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from Individual line(s)