

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Ong Chin Kiat

Date: 04 Apr 2018

**Preliminary Advice**

Vehicle No	: SKU3258M	Accident Date	: 26/03/2018
Make	: HONDA HR-V	Policy No.	: 71544206QMY
Assignment Date	: 03/04/2018	Excess	: S\$500.00
Date of Inspection	: 04/04/2018	Est. Duration of Repair	: 4.00
Inspection At	: KAH MOTOR CO SDN BHD (UBI) 15 UBI ROAD 4 SINGAPORE 408610		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,227.08
Revised Amount	:S\$	3,494.84
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,494.84

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	73,000.00
COE / PARF Rebate	:S\$	58,085.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,915.00

**Remarks**

( X ) The vehicle is economical for repair.

( ) The above survey was conducted on a 'without prejudice' basis.