

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

AXA Insurance (S) Pte Ltd

To: _____

Accident Date : 17.02.2018

Not Authorized

61 Days 8 ?

Resurvey After Paint

4 days

Third Party

Policy No: _____

Date: 02.04.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Chevrolet Cruze" Reg. No. SKK7060S Claiming Against Your Insured Veh. No. SJS24375		
1pc	Rear Taillamp RH		<i>Sm</i> 585.00 <i>X</i>
1pc	Rear Bumper		<i>ad / m / sm</i> 1,152.00 <i>—</i>
12pcs	Rear Bumper Clips	3.00	<i>sm</i> 36.00 <i>—</i>
1pc	Rear Bumper Side Holder RH		<i>sm</i> 20.70 <i>—</i>
1pc	Rear Bumper Side Retainer		<i>sm</i> 20.70 <i>—</i>
1pc	Rear Wheel Rim RH		<i>ad</i> 756.00 <i>—</i>
1pc	Rear Shock Absorber RH		<i>sm</i> 247.00 <i>X</i>
1pc	Rear Wheel Bearing		505.00 <i>?</i>
1pc	Rear Wheel Axle		<i>sm</i> 2,784.00 <i>X</i>
			6,106.40
	Less 10%		610.64
			5,495.76
	To Dismantle / Replace Rear Under Carriage to Facilitate Repair		280.00 <i>?</i>
	To Conduct Computerize Wheel Alignment Test		80.00 <i>600</i>
	Labour Charge - Panel Beating, Repairing Of Rear O/S Door, Rear Fender and Parts Replacement		550.00 <i>400</i>
	To Respray Affected Areas		700.00 <i>600</i>
	Total :		<u><u>7,105.76</u></u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: