

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Christina Wong

Date: 19 Apr 2018

Preliminary Advice

Insured Vehicle No : SKL3497L

TP Vehicle No : SGH2888S

Accident Date : 29/03/2018

Make : BMW 523I

Assignment Date : 03/04/2018

Date of Inspection : 18/04/2018

Est. Duration of Repair : 7.00

Inspection At : PERFORMANCE MOTORS LIMITED (ALEXANDRA)
303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE
SINGAPORE 159941

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,767.95
Revised Amount	:S\$	11,387.50
Check Items (Estimated)	:S\$	10,720.55
Total	:S\$	22,108.05

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.