

ASS. REC. BY:

REF CS/MSG18006103/Tlvd3er

Initial Instruction:

Surveyor
Merimen

Taught

ASSIGNMENT (Office)

From (Person):

christina Wong

of

MSG

Date/Time

03/04/18 @ 1:52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGH 2888S

Insured:

SKL 3497L

at Workshop m/s:

Performance Motor

Tel:

63190174

of

303 Alexandra Road

Policy No:

27786474 QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/03/2018

CA / REV / REP. / REV 24 HRS

lwp

18-04-2018

H.O.D. Endorsement:

Date/Time:

2:16pm @ 3/4/18

Person Contacted:

Caroline

Vehicle IN/OUT

(Circled)

Date/Time	Action/Instruction (✓) Estimate	Hum.
	SGH 2888S - CC4 / AIG 17022231 / pm 3	D.O.A: 18/11/17
	SKL 3497L - CC6 / CTT 15018041 / Upb3s2	D.O.A: 22/10/15
19/4/18	Send preli revised by merimen	
19/6/18	Final fig \$13,265 confirmed by email (Red 10,633.50, 4445)	

Enquiry

Taylor

REF: MS16

Meriden

ASSIGNMENT

From: _____ Date: 18/04/2018

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGH 28885

at Workshop m/s Performance

of 303 Alexandra Rd

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: Han

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Han. Vehicle: IN / OUT

Veh No: SGH 28885 Yr Regn: 2010 May

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 523I C.C 2497

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 122802 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WB4FP32090C2.5 7724

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 285 / 3020

R: n n

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

Survey held at PMH

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 18/4/18 @ 1420

Date / Time Action / Instruction

E-mail Han repair limit \$18K.

RECEIVED 19 JUN 2018

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

2) 19/6 - typist

Report Format : Meriden

Lump Sum / I.B.I.: (\$ 13,265 / 2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee: 200

Transportation: _____

\$ + RS \$

Photos

Others 10

TOTAL

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006103/T1vd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 03-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 3497L	Veh. Inspected	SGH 2888S
Policy No.	27786474QMY	Coverage (\$)	0.00
Claim No.	554234	Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/03/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018		03 Apr 2018 13:52 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	NORENDRAWATI BTE SUSENO, ID: S1412713E		
Main Claimant:	MUI CHEE YEONG ANDREW, ID: S1772074J		
Vehicle Reg. No.:	SGH2888S	Date of Loss:	29/03/2018 00:00 - :59 [94 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	27786474QMY Coverage: 30/10/2017 - 29/10/2018
Vehicle Reg. No. (Insured):	SKL3497L	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/04/2018]		
Driver/Custodian (Insured):	SOH LI YING SABRIYA BINTE JOHAN SOH (), NRIC: S9103192B		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 19 April 2018 12:22 PM
To: 'Christina Wong'
Cc: SUR
Subject: RE: Our Ref:M554234 TP SGH2888S

Dear Christina,

IA amount submitted in merimen.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Christina Wong [mailto:Christina_Wong@sg.msig-asia.com]
Sent: Thursday, 19 April 2018 11:53 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: Our Ref:M554234 TP SGH2888S

Hi Veron

We refer to our email below.





What is the adjusted amount, I have checked Merimen so far nothing any idea roughly how much did our surveyor adjusted TP repair cost.

Thanks

Best Regards

Christina Wong
Senior Executive, Claims Services (Motor)
Direct line +65 6643 1311 | Direct fax +65 6225 7402 | christina_wong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

From: Christina Wong
Sent: Wednesday, 4 April, 2018 11:35 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Our Ref:M554234 TP SGH2888S

Hi Veron

Please inform the surveyor we noted that we have received the TP estimate of \$25,431.71 from Performance Motor is very high our insured's estimate repairs are only \$5,126.00.





Please ask surveyor to try and press down the repair cost, check market value and check consistency of TP damages. You should have also access to our insured's report there are scene photos taken by our insured, please have a look to check consistency. We will be doing direct settlement with Performance Motors.

Thanks

Best Regards

Christina Wong
Senior Executive, Claims Services (Motor)
Direct line +65 6643 1311 | Direct fax +65 6225 7402 | christina_wong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msig.com.sg/> | Follow us on    

A member of  INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 4 April 2018 11:43 AM
To: 'Christina Wong'; assignments
Cc: SUR
Subject: RE: Our Ref:M554234 TP SGH2888S

Dear Christina,

Thank you for the email.

Dear Assignment Team,

Please refer below email.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Christina Wong [mailto:Christina_Wong@sg.msig-asia.com]
Sent: Wednesday, 4 April 2018 11:35 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: Our Ref:M554234 TP SGH2888S

Hi Veron

Please inform the surveyor we noted that we have received the TP estimate of \$25,431.71 from Performance Motor. The estimate is very high our insured's estimate repairs are only \$5,126.00.





Please ask surveyor to try and press down the repair cost, check market value and check consistency of TP damages. You should have also access to our insured's report there are scene photos taken by our insured, please have a look to check consistency. We will be doing direct settlement with Performance Motors.

Thanks

Best Regards

Christina Wong
Senior Executive, Claims Services (Motor)
Direct line +65 6643 1311 | Direct fax +65 6225 7402 | christina_wong@sg.msig-asia.com



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msg.com.sg/> | Follow us on    

A member of **MS&AD** INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Christina Wong	Date: 19 Apr 2018

Preliminary Advice

Insured Vehicle No	: SKL3497L		
TP Vehicle No	: SGH2888S	Accident Date	: 29/03/2018
Make	: BMW 523i	Assignment Date	: 03/04/2018
Date of Inspection	: 18/04/2018	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,767.95
Revised Amount	:S\$	11,387.50
Check Items (Estimated)	:S\$	10,720.55
Total	:S\$	22,108.05
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2074J
Vehicle Details	
Vehicle No.:	SGH28885
Vehicle to be Exported:	No
Intended De-registration Date:	19 Apr 2018
Vehicle Make:	B.M.W.
Vehicle Model:	523I 2.5 AT ABS D/AB 2WD 4DR GAS/D
Primary Colour:	Silver
Manufacturing Year:	2010
Engine No.:	05447377N52B25AF
Chassis No.:	WBAFP32090C257724
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$41,108.00
Original Registration Date:	26 May 2010
First Registration Date:	26 May 2010
Transfer Count:	3
Actual ARF Paid:	\$41,108.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 May 2020
PARF Rebate Amount:	\$24,664.00
Intended COE Rebate Details	
COE Expiry Date:	25 May 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$45,501.00
COE Rebate Amount:	\$9,552.00
Total Rebate Amount:	\$34,216.00

The information contained herein is correct as at 19 Apr 2018

OK

- Thinking of selling my 4 years old Audi Q3 but....
- KIA K3 Owners check-in!
- Reckless Cyclists

bmw 523

Price Range

Depreciation

2010

Vehicle Type

Search

Advanced Search

Home » Used Cars » Car Search » BMW 5 Series 523i

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Car Rental

For Private & Commercial Vehicles
Rental From **\$50/Day**

Rent



CHANGI KIDS

DISCOVER THE FUN SIDE OF CHANGI

SESAME STREET HAS ARRIVED!
5 MARCH - 1 MAY 2018

Redeem an exclusive Sesame Street Mahler notebook at \$6.90 and look out for the first-in-Asia Sesame Street Airport Takeover Pop-up Exhibition, Inflatable Fun and giant Gachapon Machines filled with exciting treats!

www.changiairport.com/sesamestreet



Compare

BMW 5 Series 523i

Overview Financial Accessories Similar Research Photos Map

CONSIGNMENT



Car Search

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$53,800	
Depreciation	\$16,270 /yr View models with similar depreciation	?
Reg Date	20-May-2010 (2yrs 1mth COE left)	
Manufactured	2010	?
Mileage	-	
Transmission	Auto	
Engine Cap	2,497 cc	
Road Tax	\$1,796 /yr	?
Power	150.0 kW (201 bhp) View specs of the BMW 5 Series Sedan	
Curb Weight	1,650 kg	?
Features	Powerful BMW 2.5L 6 Inline Engine Mated To Smooth 8-Speed Steptronic Transmission, Cruise Control, Auto Hold, Electric Park Brake, SRS, ABS, DTC.	
Accessories	-	
Description	Hottest Selling Executive Sedan In The Market! Price Negotiable. Regularly Serviced. Pristine Condition. For That Responsive, Smooth And Quiet Drive, Don't Miss, View By Appointment!	
COE	\$42,001	?
OMV	\$39,776	?
ARF	\$39,776	?
Dereg Value	\$32,623 as of today (change)	?
No. of Owners	3	?
Type of Veh	Luxury Sedan	
Category	PARF Car, Consignment Car	
Availability	Available	CONSIGNMENT

Add to Shortlist Add to Compare Add a Note

Owner Consignment Car

This car is for sale by direct owner via a consignment agent. Consignment agents help to market, sell and handle all documentation on the car seller's behalf.

- List of owner consignment cars
- List of consignment agents



Seller Information

Company	Car Search <ul style="list-style-type: none">dealer's pricelist30 vehs sold 65 vehs available
Address	18 Sin Ming Lane #04-02 Search cars nearby this location
Location	Midview City
Office No	62620728

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	31/03/2018 11:34
Date Of Accident	29/03/2018 18:45
Exact Location Of Accident	OUTSIDE ORCHARD CENTRAL(ORCHARD RD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH2888S
Insured/Policyholder	
Name Of Registered Owner	MUI CHEE YEONG ANDREW
NRIC No	S1772074J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98000367
Alternative Phone No	OFFICE-98000367

Vehicle Particulars

Manufacturer	BMW
Model	523IA
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	MUI KA-HO KEITH
NRIC No	S9202039H
Date Of Birth	15/01/1992
Occupation	INDOOR
Date Of Driving Pass	15/09/2014
Driving Experience	3 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81619092
Fax Number	
Contact Number	
Email Address	KEITH.INKED@GMAIL.COM

Address	1 SUNSHINE TERRACE #13-01
Postcode	535689
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKL3497L
Vehicle Make/Model/Colour	TOYOTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SOH YI LING SABRIYA
NRIC/Passport Number	S9103192B
Contact Number	82227952
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X 
Policyholder's Signature
Date & Time:

31/03/18
(10.53am)

X 
Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

A full-page view of a blank sheet of white graph paper. The grid consists of small squares formed by thin black lines. There are approximately 20 columns and 25 rows of squares. A vertical margin line is present on the left side, creating a narrow column of about 2 squares wide.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving the vehicle SGH2888S ~~at~~ along Orchard Road at roughly 1842hrs on 29/03/18 when my vehicle slowly came to a ^{complete} stop as the vehicle in front had done the same. Shortly after I felt a huge knock from the back. I exited the vehicle to find a Toyota, vehicle no. SKL3497L had collided into my vehicle from the back. The back of veh no. SGH2888S was damaged, including the rear ~~bumper~~ bumper among other areas. The 3rd party's vehicle was damaged at the front as well. There were no injuries.

DECLARATION

I/We declare the foregoing particulars are true in every respect

Policyholder's Signature _____

Date & Time:

31/03/18

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Wed 18/04 @ 10am
S&R

SGH2888S

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

02 APR 2018

Estimate No. : b1 46440
Date Estimated : 31/03/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 3

- ESTIMATE REPAIR FOR -

Mui Chee Yeong Andrew
1 Sunshine Terrace
#13-01

Singapore 535689

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGH2888S	C257724	26/05/2010	523iA	0

DESCRIPTION

VALUE

To replace rear bumper & attachments, boot lid including to knock out tail panel and dented area caused by the accident

✓ 2550 2,975.00

To respray rear bumper, boot lid and tail panel

2537 1868 2,819.00

To carry out body cavity preservation.
(Per panel).

✓ 100 118.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

✓ 230 271.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

X 561ⁿⁿ 661.00

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

X 451ⁿⁿ 531.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

✓ 451 531.00

To replace exhaust manifold with catalyst including conduct checks for leak.

X 952ⁿⁿ 1,121.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

✓ 150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

✓ 150 177.00

Sundries.

✓ ? 150.00

Total Labour 1: 9,531.00

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190886 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46440
Date Estimated : 31/03/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGH2888S	C257724	26/05/2010	523iA	0

DESCRIPTION	QTY	PRIC	VALUE
FLAT GASKET	2	34.05	? 68.10
# CONNECTION PLATE	1	20.00	? 20.00
EXHAUST RUBBER RING	2	19.25	? 38.50
SILENCER CLAMPING BUSH	1	60.60	de ? 60.60
# EXHAUST PIPES W/PRIMARY SILE	1	1,739.40	? 1,739.40
# REAR SILENCER	1	1,526.10	bt ✓ 1,526.10
EXHAUST TRIM CHROME	2	130.55	mis ✓ 261.10
MANIFOLD GASKET	6	8.70	? 52.20
RMFD EXHAUST MANIFOLD ZYL 1-3 EU5	1	1,881.35	? 1,881.35
# RMFD EXHAUST MANIFOLD ZYL 4-	1	1,881.35	? 1,881.35
BOOTLID	1	1,602.40	bt ✓ 1,602.40
Set of mount	1	62.60	? 62.60
RR BUMPER LH MOUNT	1	142.55	? 142.55
RR BUMPER RH MOUNT	1	142.55	? 142.55
RR BUMPER CARRIER	1	714.25	? 714.25
RR BUMPER ADAPTER	1	48.00	? 48.00
COVER BUMPER REAR (M)	1	174.70	? 174.70
# GUIDE CENTRE REAR (M)	1	75.05	? 75.05
# GUIDE BOTTOM CENTRE (M)	1	46.85	? 46.85
# COVERING TOWING RR PRIMED (M)	1	55.70	x 55.70
REAR BUMPER PANEL PRIMED (M PDC)	1	1,650.65	de ✓ 1,650.65
# ADAPTER (M)	1	64.70	? 64.70
EMBLEM GROMMET	2	0.80	na ✓ 1.60
BMW EMBLEM	1	69.50	na ✓ 69.50
PLUG	10	1.05	na ✓ 10.50
REAR LH BUMPER HEAT INSULATOR	1	32.10	? 32.10
LH GUTTER STRIP	1	16.80	? 16.80
RH GUTTER STRIP	1	16.80	? 16.80
REAR M SPOILER PRIMED	1	573.75	de ✓ 573.75
# COVER BOTTOM RH (M)	1	123.70	? 123.70
BOOTLID SEALING	1	115.25	na ✓ 115.25
PLUG BLACK D=5MM	10	0.90	na ✓ 9.00
SENSOR WIRE FOR SMART OPENER TOP	1	42.10	? 42.10
SENSOR WIRE FOR SMART OPENER BOTTOM	1	40.50	? 40.50
EXPANDING NUT	10	0.55	na ✓ 5.50
# REAR LH REFLECTOR (M)	1	35.20	? 35.20
# REAR RH REFLECTOR (M)	1	35.20	x 35.20
DECOUPLING RING PDC TORQUE CONVERTE	2	5.05	na ✓ 10.10
BUMPER PDC SENSOR (354 TITANSILBER)	2	368.80	? 737.60
(DG/SL) ADHESIVE SET K6	1	53.05	na ✓ 53.05

Total Parts : 14,236.95

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180

Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944

Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 46440
Date Estimated : 31/03/2018
Prepared By : Han Kwan Yong

Page No. : 3 of 3

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGH2888S	C257724	26/05/2010	523iA	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, during resurvey
- Parts prices are subject to confirmation
- Third party surveys on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 18/4/18 Claim No. 18/4/18

Date/Time 18/4/18 Excess \$S 97495744

Surveyor's Name Tan Kah Sign Tan Kah

Surveyor's Tel. 97495744 Authorised Yes / No

Authorised Date 31/5/18 Time 3/5/18

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No P.M. Yes / No

Surveyor's E-mail tan.kah@lkkauto.com

No. of Working Days Recommend 7 days

23,898.50

Labour 1	:	9,531.00
Parts	:	14,236.95
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,663.76
Grand Total	:	25,431.71

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 19 June 2018 11:21 AM
To: 'PBSP'; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SGH28885

Dear Caroline,

WITHOUT PREJUDICE

Confirmed amount \$13,265.00 before GST

Repair days: 7 days

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Tuesday, 19 June 2018 10:49 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: FINAL REPORT / SGH28885

Dear Veron

2 of 2.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP

Sent: Tuesday, 19 June 2018 10:22:13 AM

To: Veron Chen (LKKAUTO); Taufikh (LKKAUTO); SUR

Subject: Re: FINAL REPORT / SGH2888S

Dear Veron

Part 1 of 2 pics.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

From: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Sent: Tuesday, 19 June 2018 10:12:16 AM

To: PBSP; Taufikh (LKKAUTO); SUR

Subject: RE: FINAL REPORT / SGH2888S

Dear Caroline,

Please forward us check items and before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)

Sent: Thursday, 14 June 2018 8:50 AM

To: 'PBSP' <pml-pbsp@simedarby.com.sg>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: FINAL REPORT / SGH2888S

Dear Caroline,

Please forward us check items and before paint photos.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]

Sent: Wednesday, 13 June 2018 5:44 PM

To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FINAL REPORT / SGH2888S

Dear Sirs

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,318.00

Total Parts : 6,947.00

Total Labour & Parts : 13,265.00

Repair days: 7

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 46440
Date Estimated : 31/03/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Mui Chee Yeong Andrew
1 Sunshine Terrace
#13-01

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 535689

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SGH2888S	C257724	26/05/2010	523iA	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments, boot lid and attachments, rear M spoiler include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To respray rear bumper, boot lid and tail end panel	2537.00		2,537.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00	
To replace rear exhaust silencer including alignment system and conducting checks for leak	451.00		451.00	
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00	
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
SILENCER CLAMPING BUSH	60.60	1.00		60.60
REAR SILENCER	1,526.10	1.00		1,526.10
# EXHAUST TRIM CHROME*	130.55	1.00		130.55
EXHAUST TRIM CHROME	130.55	1.00		130.55
BOOTLID	1,602.40	1.00		1,602.40
RR BUMPER CARRIER	714.25	1.00		714.25
COVER BUMPER REAR (M)	174.70	1.00		174.70
GUIDE CENTRE REAR (M)	75.05	1.00		75.05
GUIDE BOTTOM CENTRE (M)	46.85	1.00		46.85
REAR BUMPER PANEL PRIMED (M PDC)	1,650.65	1.00		1,650.65
ADAPTER (M)	64.70	1.00		64.70
EMBLEM GROMMET	0.80	2.00		1.60
BMW EMBLEM	69.50	1.00		69.50
PLUG	1.05	10.00		10.50
REAR M SPOILER PRIMED	573.75	1.00		573.75
BOOTLID SEALING	115.25	1.00		115.25

SUPPLEMENTARY ITEMS

Total Labour :	6,318.00
Total Parts :	6,947.00
Total Labour & Parts :	13,265.00
Deduction for Excess :	
Total Repair Costs less Excess:	13,265.00
GST @7%:	928.55
Grand Total :	14,193.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 46440
Date Estimated : 31/03/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Mui Chee Yeong Andrew
1 Sunshine Terrace
#13-01

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 535689

REGN NO	CHASSI S NO	REGN DATE	MODEL	M LEAGE
SGH2888S	C257724	26/05/2010	523iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXHAUST TRIM CHROME*	130.55	1.00		130.55

Rept

Total Labour :	
Total Parts :	130.55
Total Labour & Parts :	130.55

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 Apr 2018		03 Apr 2018 13:52 Edit Adj Rpt	S\$13,265.00 Edit Estimates	S\$13,265.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	NORENDRAWATI BTE SUSENO , ID: S1412713E		
Main Claimant:	MUI CHEE YEONG ANDREW , ID: S1772074J		
Vehicle Reg. No.:	SGH2888S	Date of Loss:	29/03/2018 18:00 - :59 [94 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554234	Policy/Cover Note No.:	27786474QMY (Comprehensive) Coverage: 30/10/2017 - 29/10/2018
Vehicle Reg. No. (Insured):	SKL3497L	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/05/2018]		
Driver/Custodian (Insured):	SOH LI YING SABRIYA BINTE JOHAN SOH (), NRIC: S9103192B		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.











































ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGH2888S (554234)**
[SKL3497L]
TP
MUI CHEE YEONG ANDREW
Mar 29 2018 6:00PM
[NORENDRAWATI BTE SUSENO]
Performance Motors Limited

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Video								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	03/04/18 15:15	Video from TP (Rear) From:OD - Reg. No: SKL3497L, Claimant: NORENDRAWATI BTE SUSENO						Load MOV		
Assessment Reports								1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/04/18 12:16	Adjuster Immediate Advice						Load HTM		
Photos/Images								3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
2	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
3	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
4	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
5	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
6	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
7	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
8	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
9	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
10	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
11	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
12	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
13	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
14	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
15	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
16	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
17	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
18	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
19	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
20	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
21	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
22	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
23	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
24	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
25	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
26	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
27	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
28	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
29	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	
30	19/04/18 11:05	General View						Load JPG	<input checked="" type="checkbox"/>	

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
34	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
38	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/04/18 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	19/06/18 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	19/06/18 11:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	03/04/18 13:53	Email frm TP - PRI	 Load PDF	
2	03/04/18 13:53	SGH2888S GIA Rpt	 Load PDF	
3	03/04/18 13:56	SKL3497L GIA Rpt	 Load PDF	
4	03/04/18 14:32	Estimate	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note:

Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006103/T1VD3E2

Date: 20/06/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 27786474QMY

Claimant Vehicle No : SGH2888S

Insured Vehicle No : SKL3497L

Date of Loss: 29/03/2018

Nature of Claim: TP

Claim No: 554234

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGH2888S

Make & Model: BMW 523i, 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A)

Engine No: 05447377N52B25AF

Reg. Date: 26/05/2010 (Man. Year: 2010)

Chassis No: WBAFP32090C257724

Colour: Silver

Odometer: 122802 km

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 285/30 R20

Rear Tyre Size: 285/30 R20

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,517.50	7,097.00	7,420.50	51.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,381.00	6,168.00	3,213.00	34.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,898.50	13,265.00	10,633.50	44.49
+ GST 7.00/7.00% (S\$)	1,672.90	928.55	744.35	44.49
Nett Amount (S\$)	25,571.40	14,193.55	11,377.85	44.49

INSPECTION

Date of Assignment: 03/04/2018

Date Inspected: 18/04/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2018)
Parts:	143	BMW 523i 2.5 AT ABS D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH2888S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	2		*FLAT GASKET	Not Necessary	68.10 FS	*- FS
3	1		*CONNECTION PLATE	Not Necessary	20.00 FS	*- FS
4	2		*EXHAUST RUBBER RING	Not Necessary	38.50 FS	*- FS
5	1		*SILENCER CLAMPING BUSH	Deformed	60.60 FS	*60.60 FS
6	1		*EXHAUST PIPES W/PRIMARY SILE	Not Necessary	1,739.40 FS	*- FS
7	1		*REAR SILENCER	Bent	1,526.10 FS	*1,526.10 FS
8	2		*EXHAUST TRIM CHROME	Missing	261.10 FS	*261.10 FS
9	6		*MANIFOLD GASKET	Not Necessary	52.20 FS	*- FS
10	1		*RMFD EXHAUST MANIFOLD ZYL 1-3 EU5	Not Necessary	1,881.35 FS	*- FS
11	1		*RMFD EXHAUST MANIFOLD ZYL 4-	Not Necessary	1,881.35 FS	*- FS
12	1		*BOOTLID	Bent	1,602.40 FS	*1,602.40 FS
13	1		*SET OF MOUNT	Not Necessary	62.60 FS	*- FS
14	1		*RR BUMPER LH MOUNT	Not Necessary	142.55 FS	*- FS
15	1		*RR BUMPER RH MOUNT	Not Necessary	142.55 FS	*- FS
16	1		*RR BUMPER CARRIER	Bent	714.25 FS	*714.25 FS
17	1		*RR BUMPER ADAPTER	Not Necessary	48.00 FS	*- FS
18	1		*COVER BUMPER REAR (M)	Deformed	174.70 FS	*174.70 FS
19	1		*GUIDE CENTRE REAR (M)	Deformed	75.05 FS	*75.05 FS
20	1		*GUIDE BOTTOM CENTRE (M)	Deformed	46.85 FS	*46.85 FS
21	1		*COVERING TOWING RR PRIMED (M)	Not Necessary	55.70 FS	*- FS
22	1		*REAR BUMPER PANEL PRIMED (M PDC)	Deformed	1,650.65 FS	*1,650.65 FS
23	1		*ADAPTER (M)	Deformed	64.70 FS	*64.70 FS
24	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
25	1		*BMW EMBLEM	Necessary	69.50 FS	*69.50 FS
26	10		*PLUG	Necessary	10.50 FS	*10.50 FS
27	1		*REAR LH BUMPER HEAT INSULATOR	Not Necessary	32.10 FS	*- FS
28	1		*LH GUTTER STRIP	Not Necessary	16.80 FS	*- FS
29	1		*RH GUTTER STRIP	Not Necessary	16.80 FS	*- FS
30	1		*REAR M SPOILER PRIMED	Deformed	573.75 FS	*573.75 FS
31	1		*COVER BOTTOM RH (M)	Not Necessary	123.70 FS	*- FS
32	1		*BOOTLID SEALING	Necessary	115.25 FS	*115.25 FS
33	10		*PLUG BLACK D=5MM	Not Necessary	9.00 FS	*- FS
34	1		*SENSOR WIRE FOR SMART OPENER TOP	Not Necessary	42.10 FS	*- FS
35	1		*SENSOR WIRE FOR SMART OPENER BOTTOM	Not Necessary	40.50 FS	*- FS
36	10		*EXPANDING NUT	Not Necessary	5.50 FS	*- FS
37	1		*REAR LH REFLECTOR (M)	Not Necessary	35.20 FS	*- FS
38	1		*REAR RH REFLECTOR (M)	Not Necessary	35.20 FS	*- FS
39	2		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	10.10 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	2		*BUMPER PDC SENSOR (354 TITANSILBER)	Not Necessary	737.60 FS	*- FS
41	1		*(DG/SL) ADHESIVE SET K6	Not Necessary	53.05 FS	*- FS
42	1		*EXHAUST TRIM CHROME	Repeated	130.55 FS	*- FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					14,517.50	7,097.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER & ATTACHMENTS, BOOT LID INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	2,975.00	2,550.00
2	TO RESPRAY REAR BUMPER, BOOT LID AND TAIL PANEL	New	2,819.00	2,537.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH FACILITATE REPAIRS	New	271.00	230.00
5	TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION	New	661.00	0.00
6	TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	0.00
7	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
8	TO REPLACE EXHAUST MANIFOLD WITH CATALYT INCLUDING CONDUCT CHECKS FOR LEAK	New	1,121.00	0.00
9	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
10	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			9,381.00	6,168.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >