



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 5649 E

Parts	(a) Cost / List Price Items	\$	7,341.82
	Plus/Less 25%	\$	1,835.46
	Total of Cost / List	\$	5,506.37
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	45.00
Total Parts Cost		\$	5,551.37
Labour		\$	2,500.00
Total		\$	8,051.37

*Not Authorized
 Resurvey before painting*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 31/4/18 at 12pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03-5 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Ke Date: 31/4/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
 Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SLN 5649 E
 Make & Model : TOYOTA PRIUS
 Chassis No : JTDKB3FU903557891

Submit By : Carmen Lim
 Year Manufacture : 2017
 Engine No. : _____

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>B₂</i>	1	\$45.00	S.N	✓
2	Front number plate garnish <i>CRA</i>	1	\$45.00		✓
3	Front support panel centre <i>R</i>	1	\$338.50		?
4	Front support panel RH <i>R</i>	1	\$213.50		X
5	Headlamp panel RH <i>R</i>	1	\$89.20		X
6	Headlamp RH <i>CRA</i>	1	\$2,531.60		✓
7	Front bumper <i>B₂</i>	1	\$450.80		✓
8	Front bumper clip <i>M₂</i>	10	\$40.00		✓
9	Front bumper reinforcement - upper	1	\$711.50		?
10	Front bumper side retainer RH <i>D₁</i>	1	\$107.20		✓
11	Front bumper side retainer LH <i>S₂</i>	1	\$107.20		X
12	Front bumper upper grille <i>D₁</i>	1	\$321.90		✓
13	Front bumper lower grille <i>P₁</i>	1	\$148.60		✓
14	Front bumper emblem <i>M₂</i>	1	\$87.10		✓
15	Front bumper tow cover RH <i>D₁</i>	1	\$25.70		✓
16	Front bumper sponge - upper	1	\$89.81		?
17	Fog lamp RH	1	\$910.70		?
18	RH front fender <i>R</i>	1	\$868.70		X
19	RH front fender undershield <i>S₂</i>	1	\$185.64		X
20	RH front fender undershield clip <i>22</i>	10	\$25.00		X
21	RHF fender wording "HYBRID" <i>M₂</i>	1	\$44.17		✓
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

