

22/03/2002

ASS. REC. BY:

REF: CS/MSG18006106/Grd302 Special Instruction:

Surveyor:

Menimen

G.O.

ASSIGNMENT (Office)

From (Person):

Catherine Thia

of

MSG

Date/Time:

3/4/18 @ 11:21 am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGP 5554T

Insured:

SLV 4136 H

at Workshop m/s

Torque 5

Tel:

64524457

of

8 Kaki Blc Ave 4 # 01-49 / 50

Policy No:

1000-680353

Claim No:

91478841

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/03/2018

CA / REV / REP. / REV 24 HRS 'wpi

DS 04/2018

H.O.D. Endorsement:

Date/Time:

2:22pm @ 3/4/18

Person Contacted:

Michelle

Vehicle IN

OUT

Date/Time	Action/Instruction (✓) Estimate
	SGP 5554T - NA / AIG / 18005909 / h4
	SLV 4136 H - NA / AIG / 18005909 / h4
	D.O.A. 29/3/18
	D.O.A. 29/3/18
	Sent prot the menimen

ASSIGNMENT

From:

Date:

5/4/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGP 5554T

at Workshop m/s

Torque 5

of

8/kaki Bkt Ave 4 #01-49/50

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20. % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGP 5554T

Yr Regn:

27 Nov 2017

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Merce E250 c.c. 1991

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

13508

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD 2130452-A 333440

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 245/45ZR18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

05-04-18

Survey held at

w/s

5pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/6/18

Confirm L/S \$2450 @ 3 day
Pd: \$750, 23/7.

Date/Time: File Pass to?



Preli. Report

1) tripist



Final Report

Date/Time: File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + RS \$

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

1P

Lump Sum / +B.I: (\$

2450.00

200

10

210

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Mar 2018		03 Apr 2018 11:21 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD., Co. Reg. No.: 197901535G		
Main Claimant:	BLUE MOON ENGINEERING PTE LTD, Co. Reg. No.: 199102516K		
Vehicle Reg. No.:	SGP5554T	Date of Loss:	29/03/2018 19:00 - :59 [4 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	1000680353 (Comprehensive) Coverage: 19/03/2018 - 18/03/2019
Vehicle Reg. No. (Insured):	SLV4136H	Policy No. (Claimant):	MSD/VPCP/13-009073
		Excess:	
Reparer:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/04/2018]		
Driver/Custodian (Insured):	CAMPION THIBAUT (), NRIC: G3248376W		
Adj Asg. Remarks:	please appoint mr adrian ling to survey. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [+]

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18006106/Grd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 03-04-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLV 4136H	Veh. Inspected	SGP 5554T
Policy No.	1000680353	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	29/03/2018	Inspection Date
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

ACCIDENT STATEMENT

ACCIDENT DATE: (29 / 03 / 18) (DD/MM/YYYY), TIME: (19 : 25) (HH:MM)

LOCATION: CTE TWDS CITY

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SG P5554T
 b) INSURANCE COMPANY: AIC
 c) POLICY NUMBER: 17 00079713
 d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
 e) MAKE & MODEL: merc E250
 f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
 g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
 h) PURPOSE OF USING AT ACCIDENT TIME: Private
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- a) NAME: Blue Moon Engineering Pte Ltd (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: 199102516K CONTACT:
 c) ADDRESS: 3 WOODLANDS INDUSTRIAL PARK E1
 #06-02 NORTHLAND INDUSTRIAL BUILDING 2 S'PORE 757726

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: Weng Xian Feng (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S92047594 CONTACT:
 c) ADDRESS: 30B GOODLINK PARK
 S'PORE 759511

*d) DATE OF BIRTH: (09 / 02 / 1992) (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) YEARS OF DRIVING EXPERIENCE: 8 year

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
 IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: son

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: SLV4136H MODEL:
 b) DRIVER'S NAME:
 c) NRIC/FIN/PASSPORT: CONTACT:

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: SLV493C MODEL:
 e) DRIVER'S NAME:
 f) NRIC/FIN/PASSPORT: CONTACT:

*No of passenger
 (including driver)
 (01)

*No of passenger
 (including driver)
 (01)

*No of passenger
 (including driver)
 ()

Email = REPORTING@
 TOPQUE5.com
 Fax = 6452 4584

KK
 596 061 Industrial Park 2
 01-25, 51 Ubi Ave
 S(408933)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

A handwritten signature in black ink, appearing to be 'J. K. S.', is written over a horizontal line.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' was travelling on the stated venue I was travelling straight in my lane, as the front vehicle stop, I applied my brake and came to a stop. A few moments later, I felt an impact from my vehicle rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2516K
Vehicle Details	
Vehicle No.:	SGP5554T
Vehicle to be Exported:	No
Intended De-registration Date:	05 Apr 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E250 EXCLUSIVE (R18 LED)
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	27492031217571
Chassis No.:	WDD2130452A333440
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$59,733.00
Original Registration Date:	27 Nov 2017
First Registration Date:	27 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$79,520.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Nov 2027
PARF Rebate Amount:	\$59,640.00
Intended COE Rebate Details	
COE Expiry Date:	26 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$55,356.00
Total Rebate Amount:	\$114,996.00

The information contained herein is correct as at 05 Apr 2018

OK

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGP5554T
Make & Model : MERCEDES BENZ, E250 EXCLUSIVE (R18 LED), WDD2130452A333440
Year of Manufacture : 2017

Estimation No. : E18040003
DOA : 29/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bootlid X	1.00	0.00	0.00 2560.00
2	Rear bootlid chrome piece X	1.00	0.00	0.00 184.60
3	Rear bootlid logo X	1.00	0.00	0.00 65.00
4	Rear bootlid emblem - E250 X	1.00	0.00	0.00 115.00
5	Rear bootlid emblem - Cycle & carriage X	1.00	0.00	0.00 115.00
6	Rear bootlid emblem - 9G-Tronic X	1.00	0.00	0.00 115.00
7	Rear bumper - Re	1.00	0.00	0.00 1660.00
8	Rear bumper clip - MBL	1.00 10	0.00 10.00	0.00 100.00
9	Rear bumper retainer (LH) - 4 MBL	1.00	0.00	0.00 79.00
10	Rear bumper retainer (RH)	1.00	0.00	0.00 79.00
11	Rear bumper reinforcement X	1.00	0.00	0.00 975.00
12	Rear bumper sponge X	1.00	0.00	0.00
13	Rear bumper sensor X	1.00	0.00	0.00 237.90
14	Rear bumper reflector (LH) X	1.00	0.00	0.00 37.00
15	Rear bumper reflector (RH) X	1.00	0.00	0.00 37.00
16	Rear bumper lower garnish - Cent	1.00	0.00	0.00 350.00
17	Rear bumper lower garnish chrome piece - art	1.00	0.00	0.00 400.00
18	Tail lamp (LH) X	1.00	0.00	0.00 827.20
19	Tail lamp (RH) X	1.00	0.00	0.00 827.20
20	Tail lamp clip (LH) X	1.00 2	0.00 10.00	0.00 20.00
21	Tail lamp clip (RH) X	1.00 2	0.00 10.00	0.00 20.00
22	Rear fender inner trim (LH) X	1.00	0.00	0.00 393.80
23	Rear fender inner trim (RH) X	1.00	0.00	0.00 393.80
24	Rear fender inner trim clip (LH) X	1.00 10	0.00 10.00	0.00 100.00

Supp:
* inner centre garnish / BR.

Continue on next page...

4691.50



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGP5554T
Make & Model : MERCEDES BENZ,E250 EXCLUSIVE (R18 LED),WDD2130452A333440
Year of Manufacture : 2017

Estimation No. : E18040003
DOA : 29/03/2018

No	Description	Qty	U/P	Amt
25	Rear fender inner trim clip (RH) X	1.00	0.00	0.00
26	Rear end panel X	1.00	0.00	0.00
27	Rear end panel top garnish X	1.00	0.00	0.00
28	Rear end panel top garnish clip X	1.00	0.00	0.00
29	Exhaust pipe X	2.00	0.00	0.00
30	Exhaust pipe mounting X	1.00	0.00	0.00
31	Exhaust pipe gasket X	1.00	0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items

32	Rear end panel sealant X	1.00	80.00	80.00
				Amt S\$ 80.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 80.00

Section: Labour Items

33	To R&R accident affected areas	1.00	1,000.00	1,000.00
34	To putty & respray accident affected areas	1.00	1,000.00	1,000.00
35	To rust proof accident affected areas	1.00	60.00	60.00
36	To R&R rear boot mechanism	1.00	80.00	80.00
37	To R&R rear luggage compartment	1.00	200.00	200.00
38	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00
39	To check wiring layout of tail lamp	1.00	80.00	80.00
40	To R&R exhaust pipe assy	1.00	180.00	180.00
41	To check for water seepage	1.00	80.00	80.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGP5554T
Make & Model : MERCEDES BENZ, E250 EXCLUSIVE (R18
LED), WDD2130452A333440
Year of Manufacture : 2017

Estimation No. : E18040003
DOA : 29/03/2018

No	Description	Qty	U/P	Amt
42	To do wheel alignment	1.00	180.00	180.00

Amt S\$ 2,940.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,940.00

3 Days.
Unpsum Repair.
After repair photos.
Gmo Qiy.
05/4/18

18838-50

List Items Subtotal S\$ 0.00
Special Nett Items Subtotal S\$ 80.00
Labour Items Subtotal S\$ 2,940.00
Total S\$ 3,020.00 3200

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SGP5554T
Make & Model : MERCEDES BENZ,E250 EXCLUSIVE (R18
LED),WDD2130452A333440
Year of Manufacture : 2017

Estimation No. : E18040035
DOA : 29/03/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Inner centre garnish <i>BR</i>	1.00	180.00	180.00
				Amt S\$ 180.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 180.00

P: 2848-107-
2563-20

SN: 0

L: 590-00

2153-20

2749.99
10% : 2474.99

3064.99

2% : 2450.

4/5 42500 @ 3
repair days

List Items Subtotal S\$ 180.00
Total S\$ 180.00

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGP5554T
Make & Model : MERCEDES BENZ,E250 EXCLUSIVE (R18 LED),WDD2130452A333440
Year of Manufacture : 2017

Estimation No. : E18040003
DOA : 29/03/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	Rear bootlid X	1.00	0.00	0.00 2560
2	Rear bootlid chrome piece X	1.00	0.00	0.00 184.60
3	Rear bootlid logo X	1.00	0.00	0.00 65.00
4	Rear bootlid emblem - E250 X	1.00	0.00	0.00
5	Rear bootlid emblem - Cycle & carriage A	1.00	0.00	0.00
6	Rear bootlid emblem - 9G-Tronic X	1.00	0.00	0.00
7	Rear bumper / Re	1.00	0.00	0.00
8	Rear bumper clip / MC	1.00	0.00	0.00
9	Rear bumper retainer (LH) /	1.00	0.00	0.00
10	Rear bumper retainer (RH) /	1.00	0.00	0.00
11	Rear bumper reinforcement ?	1.00	0.00	0.00
12	Rear bumper sponge ?	1.00	0.00	0.00
13	Rear bumper sensor X	1.00	0.00	0.00
14	Rear bumper reflector (LH) X	1.00	0.00	0.00
15	Rear bumper reflector (RH) X	1.00	0.00	0.00
16	Rear bumper lower garnish /	1.00	0.00	0.00
17	Rear bumper lower garnish chrome piece /	1.00	0.00	0.00
18	Tail lamp (LH) X	1.00	0.00	0.00
19	Tail lamp (RH) X	1.00	0.00	0.00
20	Tail lamp clip (LH) X	1.00	0.00	0.00
21	Tail lamp clip (RH) X	1.00	0.00	0.00
22	Rear fender inner trim (LH) X	1.00	0.00	0.00
23	Rear fender inner trim (RH) X	1.00	0.00	0.00
24	Rear fender inner trim clip (LH) X	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGP5554T
Make & Model : MERCEDES BENZ,E250 EXCLUSIVE (R18 LED),WDD2130452A333440
Year of Manufacture : 2017

Estimation No. : E18040003
DOA : 29/03/2018

No	Description	Qty	U/P	Amt
25	Rear fender inner trim clip (RH) X	1.00	0.00	0.00
26	Rear end panel X	1.00	0.00	0.00
27	Rear end panel top garnish X	1.00	0.00	0.00
28	Rear end panel top garnish clip X	1.00	0.00	0.00
29	Exhaust pipe X	2.00	0.00	0.00
30	Exhaust pipe mounting X	1.00	0.00	0.00
31	Exhaust pipe gasket X	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

32	Rear end panel sealant X	1.00	80.00	80.00
----	--------------------------	------	-------	-------

Amt S\$ 80.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 80.00

Section: Labour Items

33	To R&R accident affected areas	1.00	1,000.00	1,000.00	300
34	To putty & respray accident affected areas	1.00	1,000.00	1,000.00	250
35	To rust proof accident affected areas	1.00	60.00	60.00	X
36	To R&R rear boot mechanism	1.00	80.00	80.00	X
37	To R&R rear luggage compartment	1.00	200.00	200.00	X
38	To R&R rear bumper reverse sensor & check function	1.00	80.00	80.00	40
39	To check wiring layout of tail lamp	1.00	80.00	80.00	X
40	To R&R exhaust pipe assy	1.00	180.00	180.00	X
41	To check for water seepage	1.00	80.00	80.00	X

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SGP5554T
Make & Model : MERCEDES BENZ,E250 EXCLUSIVE (R18 LED),WDD2130452A333440
Year of Manufacture : 2017

Estimation No. : E18040003
DOA : 29/03/2018

No	Description	Qty	U/P	Amt
42	To do wheel alignment	1.00	180.00	180.00

Amt S\$ 2,940.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,940.00

3 Days.

Lumpsum Repair.

After repair photos.

Eno Qiang.

05/4/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 80.00
Labour Items Subtotal	S\$ 2,940.00
Total	S\$ 3,020.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Mar 2018		05 Apr 2018 17:01 Edit Adj Rpt	S\$2,450.00 Edit Estimates	S\$2,450.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	TOKYO CENTURY LEASING (SINGAPORE) PTE LTD., Co. Reg. No.: 197901535G								
Main Claimant:	BLUE MOON ENGINEERING PTE LTD, Co. Reg. No.: 199102516K								
Vehicle Reg. No.:	SGP5554T	Date of Loss:	29/03/2018 19:00 - :59 [4 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 216686	Policy/Cover Note No.:	1000680353 (Comprehensive) Coverage: 19/03/2018 - 18/03/2019						
Vehicle Reg. No. (Insured):	SLV4136H	Policy No. (Claimant):							
		Excess:							
Repairer:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/05/2018]								
Driver/Custodian (Insured):	CAMPION THIBAUT (), NRIC: G3248376W								
Adj Asg. Remarks:	please appoint mr adrian ling to survey. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (05/04/2018): Cancellation of Assignment: SGP5554T									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGP5554T (216686)

[SLV4136H]

TP

BLUE MOON ENGINEERING PTE LTD

Mar 29 2018 7:00PM

[TOKYO CENTURY LEASING (SINGAPORE) PTE LTD.]

Torque 5 Bodyworks Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)							Thumbnail	Print	
1	30/03/18 19:12	Accident Statement							Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	10/04/18 16:21	Adjuster Immediate Advice							Load HTM		
Photos/Images									3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	16/08/18 11:59	General View							Load JPG		
2	16/08/18 11:59	General View							Load JPG		
3	16/08/18 11:59	General View							Load JPG		
4	16/08/18 11:59	General View							Load JPG		
5	16/08/18 11:59	General View							Load JPG		
6	16/08/18 11:59	General View							Load JPG		
7	16/08/18 11:59	General View							Load JPG		
8	16/08/18 11:59	General View							Load JPG		
9	16/08/18 11:59	General View							Load JPG		
10	16/08/18 11:59	General View							Load JPG		
11	16/08/18 11:59	General View							Load JPG		
12	16/08/18 11:59	General View							Load JPG		
13	16/08/18 11:59	General View							Load JPG		
14	16/08/18 11:59	General View							Load JPG		
15	16/08/18 11:59	General View							Load JPG		
16	16/08/18 11:59	General View							Load JPG		
17	16/08/18 11:59	General View							Load JPG		
18	16/08/18 11:59	General View							Load JPG		
19	16/08/18 12:02	Reinspection Photo							Load JPG		
20	16/08/18 12:02	Reinspection Photo							Load JPG		
21	16/08/18 12:02	Reinspection Photo							Load JPG		
22	16/08/18 12:02	Reinspection Photo							Load JPG		
23	16/08/18 12:02	Reinspection Photo							Load JPG		
24	16/08/18 12:02	Reinspection Photo							Load JPG		
25	16/08/18 12:02	Reinspection Photo							Load JPG		
26	16/08/18 12:02	Reinspection Photo							Load JPG		
27	16/08/18 12:02	Reinspection Photo							Load JPG		
28	16/08/18 12:02	Reinspection Photo							Load JPG		
Documentation									1 per page		
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)							Thumbnail	Print	
1	03/04/18 11:14	SGP5554T E FILE REPORT (1st)							Load PDF		
2	03/04/18 11:17	TP PRI Request							Load PDF		

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
3	03/04/18 11:22	tp agreed common surveyor - assign LKK	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/08/18 12:11	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	30/03/18 19:12	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	30/03/18 19:09	Accident Photo	 Load JPG	☒
2	30/03/18 19:09	Accident Photo	 Load JPG	☒
3	30/03/18 19:09	Accident Photo	 Load JPG	☒
4	30/03/18 19:09	Accident Photo	 Load JPG	☒
5	30/03/18 19:09	Accident Photo	 Load JPG	☒
6	30/03/18 19:09	Accident Photo	 Load JPG	☒
7	30/03/18 19:09	Accident Photo	 Load JPG	☒
8	30/03/18 19:09	Accident Photo	 Load JPG	☒
9	30/03/18 19:09	Accident Photo	 Load JPG	☒
10	30/03/18 19:09	Identification Card	 Load JPG	☒
11	30/03/18 19:11	Identification Card	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	30/03/18 19:09	Sketch Plan	 Load JPG	☒
2	30/03/18 19:10	POLICE REPORT	 Load JPG	☒
3	30/03/18 19:10	POLICE REPORT	 Load JPG	☒
4	30/03/18 19:10	POLICE REPORT	 Load JPG	☒
5	30/03/18 19:10	POLICE REPORT	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006106/GRD3E2

Date: 17/08/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000680353

Claimant Vehicle No : SGP5554T

Insured Vehicle No : SLV4136H

Date of Loss: 29/03/2018

Nature of Claim: TP

Claim No: 216686

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGP5554T**

Make & Model: MERCEDES-BENZ E250, 2.0 SEDAN EDITION E (R18 LED SR) (A)

Engine No: 27492031217571

Reg. Date: 27/11/2017 (Man. Year: 2017)

Chassis No: WDD2130452A333440

Colour: Silver

Odometer: 13508 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45Z R18

Rear Tyre Size: 245/45Z R18

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,898.50	2,474.99	13,423.51	84.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,940.00	590.00	2,350.00	79.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,838.50	3,064.99	15,773.51	83.73
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	18,838.50	2,450.00	16,388.50	86.99
+ GST 7.00/7.00% (S\$)	1,318.70	171.50	1,147.20	86.99
Nett Amount (S\$)	20,157.20	2,621.50	17,535.70	86.99

INSPECTION

Date of Assignment: 05/04/2018

Date Inspected: 05/04/2018 Inspected At:

Torque 5 Bodyworks Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54
Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2018)
Parts:	143	MERCEDES-BENZ E250 2.0 SEDAN EDITION E (R18 LED SR) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGP5554T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Not Necessary	2,560.00 F	*- FL
2	1		*REAR BOOTLID CHROME PIECE	Not Necessary	184.60 F	*- FL
3	1		*REAR BOOTLID LOGO	Not Necessary	65.00 F	*- FL
4	1		*REAR BOOTLID EMBLEM - E250	Not Necessary	115.00 F	*- FL
5	1		*REAR BOOTLID EMBLEM - CYCLE & CARRIAGE	Not Necessary	115.00 F	*- FL
6	1		*REAR BOOTLID EMBLEM - 9G-TRONIC	Not Necessary	115.00 F	*- FL
7	1		*REAR BUMPER	Deformed	1,660.00 F	*1,660.00 FL
8	10		*REAR BUMPER CLIP	Necessary	100.00 F	*100.00 FL
9	1		*REAR BUMPER RETAINER (LH)	Necessary	79.00 F	*79.00 FL
10	1		*REAR BUMPER RETAINER (RH)	Necessary	79.00 F	*79.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Not Necessary	975.00 F	*- FL
12	1		*REAR BUMPER SPONGE (NPA)	Not Necessary	0.00 F	*- FL
13	1		*REAR BUMPER SENSOR	Not Necessary	237.90 F	*- FL
14	1		*REAR BUMPER REFLECTOR (LH)	Not Necessary	37.00 F	*- FL
15	1		*REAR BUMPER REFLECTOR (RH)	Not Necessary	37.00 F	*- FL
16	1		*REAR BUMPER LOWER GARNISH	Cut	350.00 F	*350.00 FL
17	1		*REAR BUMPER LOWER GARNISH CHROME PIECE	Cut	400.00 F	*301.99 FL
18	1		*TAIL LAMP (LH)	Not Necessary	827.20 F	*- FL
19	1		*TAIL LAMP (RH)	Not Necessary	827.20 F	*- FL
20	2		*TAIL LAMP CLIP (LH)	Not Necessary	20.00 F	*- FL
21	2		*TAIL LAMP CLIP (RH)	Not Necessary	20.00 F	*- FL
22	1		*REAR FENDER INNER TRIM (LH)	Not Necessary	393.80 F	*- FL
23	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	393.80 F	*- FL
24	10		*REAR FENDER INNER TRIM CLIP (LH)	Not Necessary	100.00 F	*- FL
25	2		*REAR FENDER INNER TRIM CLIP (RH)	Not Necessary	20.00 F	*- FL
26	1		*REAR END PANEL	Not Necessary	1,587.00 F	*- FL
27	1		*REAR END PANEL TOP GARNISH	Not Necessary	208.00 F	*- FL
28	10		*REAR END PANEL TOP GARNISH CLIP	Not Necessary	100.00 F	*- FL
29	2		*EXHAUST PIPE	Not Necessary	3,920.00 F	*- FL
30	1		*EXHAUST PIPE MOUNTING	Not Necessary	52.00 F	*- FL
31	1		*EXHAUST PIPE GASKET	Not Necessary	60.00 F	*- FL
32	1		*INNER CENTRE GARNISH	Broken	180.00 F	*180.00 FL
33	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,898.50	2,749.99
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	275.00
Total Parts (\$\$)	15,898.50	2,474.99

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R ACCIDENT AFFECTED AREAS	New	1,000.00	300.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	1,000.00	250.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	60.00	0.00
4	TO R & R REAR BOOT MECHANISM	New	80.00	0.00
5	TO R & R REAR LUGGAGE COMPARTMENT	New	200.00	0.00
6	TO R & R REAR BUMPER REVERSE SENSOR & CHECK FUNCTION	New	80.00	40.00
7	TO CHECK WIRING LAYOUT OF TAIL LAMP	New	80.00	0.00
8	TO R & R EXHAUST PIPE ASSY	New	180.00	0.00
9	TO CHECK FOR WATER SEEPAGE	New	80.00	0.00
10	TO DO WHEEL ALIGNMENT	New	180.00	0.00
Gross Labour Cost (S\$)			2,940.00	590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >