

ASS. REC. BY:

REF:

es/EGI18006109/RHd3ⁿ²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

3/4/18 @ 2.41pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SIN 4710S

Insured:

SKW 90M

at Workshop m/z:

Borneo Motors (Inchcape)

Tel:

6631 1863

of

2 Pandan Crescent (Level 4)

Policy No.:

Claim No.:

SKW 90M / RH / pl

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/04/2018

CA / REV / REP. / REV 24 HRS 'w/p'

H.O.D. Endorsement:

Date/Time:

2.50pm @ 3/4/18

Person Contacted:

Francis

Vehicle IN/OUT

(OUT)

Date/Time

Action/Instruction

(✓)

Estimate

SIN 4710S - x

SKW 90M - x

10/4/18 @ 10.11am

- Revert via email ergo

Part by Part \$8027.22 (Red: 1603.60 / 16%)

ASSIGNMENT

From: Date: 06/04/2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLN 4710S
at Workshop m/s: Borneo Motor
of: 2 Pandan Garden.

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Francis

(Policy Condition)

12pm

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLN 4710S Yr Regn: 2017 / MY

Type: ☒ M.Cp / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA SILHURA 1.5 C.C. 1496

Colour: ORANGE A/C: Insured / Std / NI / NA

Sp. Reading: 16533 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MHF 22843700027182

Gen. Cond: Good / ☒ Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/50R16

R:

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 01/04/18 D.O.I. 06/04/18

Survey held at: BORNEO MOTOR

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/5/2018

RECEIVED 24 MAY 2018

Date/Time, File Pass to?

1) 23/5/2018

Date/Time, File Return to?

2)

☐ : Prel. Report☒ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) \$ = RS. \$1

) Photos

) Others

)

TOTAL

Report Format: TP

Lump Sum / I.B.O. \$ 8022.22

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18006109/R1td3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 03-04-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 90M	Veh. Inspected	SLN 4710S
Policy No.		Coverage (\$)	0.00
Claim No.	SKW90M/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	01/04/2018	Inspection Date
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462	

5a. Remarks
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 3 April 2018 2:41 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SKW90M / TP : SLN4710S/LKK / DOA : 01/04/2018
Attachments: SLN4710S - SAS.pdf; SLN4710S - ESTIMATE.pdf; SLN4710S - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **INCHCAPE - BORNEO MOTORS (S) PTE LTD**,

ADDRESS : 2 PANDAN CRESCENT
INCHCAPE CENTRE LEVEL 4
SINGAPORE 128462

PERSON TO CONTACT : FRANCIS CHER @ 9847 6149 / 6631 1863

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on without prejudice basis. Please note that our insured/insured driver has yet to e-file their SAS for this accident. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate and Third Parties SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 03.04.2018
Our Reference: SKW 90M/RH/pl
Your Reference: SLN 4710S

Sent via Fax

or

Email

Siti.Nabilah@inchcape.com.sg

To: **INCHCAPE - BORNEO MOTORS (SINGAPORE) P/L**

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLN 4710S
Insured's Vehicle: SKW 90M
Date Of Accident: 01.04.2018

We acknowledge receipt of your request for PRS on: 03.04.2018


In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK AUTO

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
- ☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.
- ☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
- ☒ Our Insured's driver has not reported the accident to us todate.
- ☒ Others: **We are therefore not in a position to discuss on liability at this juncture.**

OFFICER-IN-CHARGE - ROHAINI

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S02127701**

Name: **HARRY GAY POH SIAN**

Birth Date: **07 Jul 1949**
Issue Date: **06 Oct 2003**

000900940E

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S02127701**

Name: **HARRY GAY POH SIAN**

Race: **CHINESE**
Date of Birth: **07-07-1949** Sex: **M**
Country of Birth: **SINGAPORE**

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S1124066F**

Name: **ELIZABETH TAY POH SUAN**
鄭寶鑽

Race: **CHINESE**
Date of Birth: **20-05-1955** Sex: **F**
Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS:

Class 2B Motorcycles <= 200 CC
Class 3 Motor cars <= 2000 kg with <= 7 passengers, exclusive of the driver; and motor tractors/vehicles <= 2500 kg

PASS DATE: **21 Feb 2005**
09 Oct 1973

S / No. **9000007420**

Licence No: **S02127701**

NP 428A

1618149

NRIC No: **S02127701**

Blood Group: **O+** Date of issue: **25-01-1994**

Address: **5 JALAN KEMAMAN #18-01 SINGAPORE 329325**

NRIC No: **S02127701** Date: **11-10-2004** No: **4935268**

A0118749

NRIC No: **S1124066F**

Blood Group: **A+** Date of issue: **02-04-2002**

Address: **5 JALAN KEMAMAN #18-01 SINGAPORE 329325**

NRIC No: **S1124066F** Date: **13-10-2004** No: **4935286**



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE NO. : VPA/P1932566 Account No. : 14885
Coverage : Comprehensive (SmartDrive Toyota Prestige)
Sum Insured : Market Value At The Time Of Loss
Name of Policy Holder : ELIZABETH TAY POH SUAN
Vehicle Registration No. : SLN4710S
Period of Insurance : From 04/05/2017 To 03/05/2018 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
(b) Any other person who is driving on the Policyholder's order or with his permission
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess : SGD 500.00

An Additional Excess is applicable as follows:

S\$2,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.


(Please refer to your policy on the terms & conditions)* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Issued by - SGOAGPH on 19/05/2017

IMPORTANT :


Authorized Signature

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation) Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.



3/4 12pm

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 124462
Tel no.: 6631 1188

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM <i>LKK</i> <i>Mr Nivita</i> <i>68411972</i>	S1000020 / TPCLAIM	
	Document No 0	
	Document Date 02/04/2018	Mrs Elizabeth Tay Poh Suan 5 Jalan Kemaman #18-01 Singapore 329325 Mobile: 96360723

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	MWYQKT E1	NSP170R	04/05/2017	SLN4710S	0	30236	5DS/SLN4710S/01041
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MHFZ28H3700027182	2NRX128126	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY T/P INS. T/P VEH. ACC DATE BY				100.00
		SUNDRIES : <i>500 lvs.</i> : SKW90M : 01.04.18 :				
2	Z	BP-SLANT				<i>net</i>
3	B	BP-LAB CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.				100.00 154.00
4	B	BP-LAB DRILL HOLE TO INSTALL REVERSE SENSOR.				154.00
5	B	BP-LAB REMOVE BOOT INTERIOR TO ASSIST REPAIR.				308.00
6	B	BP-LAB REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.				385.00
7	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.				400.00
8	B	BP-LAB REMOVE ATIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.				308.00
9	B	BP-LAB REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.			1848	2464.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3623150

TO SECURITY GUARD

3623150

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME 02/04/2018
16:14

VEHICLE NO
SLN4710S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mrs Elizabeth Tay Poh Suan 5 Jalan Kemaman #18-01 Singapore 329325 Mobile: 96360723
	Document No	
	Document Date	
	0	
	02/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	MWYQKT	E1	NSP170R	04/05/2017	SLN4710S	0	30236 5DS/SLN4710S/01041:
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MHFZ28H3700027182	2NRX128126	60	Francis Cher T S	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1518 2024.00
11	1	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1097.60		1097.60
12	2	S68105-0D260 GLASS SUB-ASSY, BACK	1.00	973.80		973.80
13	3	S64813-0D330 DAM, BACK WINDOW GLA	2.00	12.00		24.00
14	4	T04562-12010 W/SCREEN GLS DAM KIT,	1.00	101.00		101.00
15	5	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		173.44
16	6	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
17	7	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		72.20
18	8	S75441-0D070 PLATE, BACK DOOR NAM	1.00	51.50		51.50
19	9	S75442-0D290 PLATE, BACK DOOR NAM	1.00	34.40		34.40
20	0	S52161-0D070 EXTENSION, RR BUMPER	1.00	125.20		125.20
21	1	S52151-0D010 EXTENSION, RR BUMPER	1.00	184.20		184.20
22	2	S52159-0U919 COVER, RR BUMPER, L	1.00	306.40		306.40

Rasul

Hp 90010018

6 days

06/04/18

1210

Respray

1518 2024.00

1097.60

973.80

24.00

101.00

173.44

90.08

72.20

51.50

34.40

125.20

184.20

306.40

intermediate

125.20

184.20

306.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- For 3 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.
- Third party survey is on a "Without Prejudice" basis

For 3 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

Customer's Signature

Signature

Date:

Change Summary	
Parts	3,233.82
Labour	5,997.00
Materials	400.00
Lubrication/Fluid	0.00
Others	0.00

Total	9,630.82
GST 7.00%	674.16
Less	0.00
Amount Due	10,304.98

PLEASE TEAR ALONG PERFORATED LINE

3623151

TO SECURITY GUARD

3623151

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 02/04/2018
TIME 16:14

VEHICLE NO SLN4710S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Attn: Rasul
6 days. Final Bill

TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010/ICNI3 Document No 38023784 Document Date 16/05/2018	Mrs Elizabeth Tay Poh Suan 5 Jalan Kemaman #18-01 Singapore 329325 Mobile: 96360723

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	MWYQKT	E1	NSP170R	04/05/2017	SLN4710S	17519	30236 5DS/SLN4710S/010411
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MHFZ28H3700027182	2NRX128126	60	Francis Cher T S	16/05/2018 18.20	16/05/2018 18.20		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS. : ERGO INSURANCE T/P VEH. : SKW90M ACC DATE : 01.04.18 BY : RASUL (LKK)	*			50.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)	*			100.00
3	B	BP-LAB CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.	*			154.00
4	B	BP-LAB DRILL HOLE TO INSTALL REVERSE SENSOR.	*			154.00
5	B	BP-LAB REMOVE BOOT INTERIOR TO ASSIST REPAIR.	*			308.00
6	B	BP-LAB REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.	*			385.00
7	S	BP-SUBLET SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM. PO 16868	M30			400.00
8	B	BP-LAB REMOVE ATIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.	*			308.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3670024

3670024

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLN4710S

CUSTOMER

DATE 16/05/2018
TIME 19:29

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no. 6631-1188


TAX INVOICE

Account Detail	Account No	Customer Detail
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept	S1000010 / ICN13 Document No 38023784 Document Date 16/05/2018	Mrs Elizabeth Tay Poh Suan 5 Jalan Kemaman #18-01 Singapore 329325 Mobile: 96360723

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	MWYQKT	E1	NSP170R	04/05/2017	SLN4710S	17519	30236 5DS/SLN4710S/010411
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MHFZ28H3700027182	2NRX128126	60	Francis Cher T S	16/05/2018 18.20	16/05/2018 18.20		

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	B	BP-LAB REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.	*			1848.00
10	B	BP-RES SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			1518.00
11	1	S67005-0D360 PANEL SUB-ASSY, BACK	1.00	1097.60		1097.60
12	2	S68105-0D260 GLASS SUB-ASSY, BACK	1.00	973.80		973.80
13	3	S64813-0D330 DAM, BACK WINDOW GLA	2.00	12.00		24.00
14	4	T04562-12010 DAM KIT, WINDOW GLASS	1.00	101.00		101.00
15	5	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		173.44
16	6	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
17	7	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		72.20
18	8	S75441-0D070 PLATE, BACK DOOR NAM	1.00	51.50		51.50
19	9	S75442-0D290 PLATE, BACK DOOR NAM	1.00	34.40		34.40
20	0	S52151-0D010 EXTENSION, RR BUMPER	1.00	184.20		184.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	8,027.22
	Please acknowledge receipt of vehicle	Parts	2,802.22	
		Labour	4,825.00	GST 7.00% 561.91
		Materials	400.00	Less 0.00
		Lubrication/Fluid	0.00	
		Others	0.00	
				Amount Due 8,589.13

PLEASE MAIL YOUR CHEQUE TO 33 LENGKAP ROAD, SINGAPORE 159102

3670025

3670025

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 16/05/2018
TIME 19:29

VEHICLE NO SLN4710S

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD		Ref : CS/EG18006109/R1td3n2		
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 30-05-2018		
		Code : EGI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKW 90M	Veh. Inspected	SLN 4710S	
Policy No.		Coverage (\$)	0.00	
Claim No.	SKW90M/RH/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MHFZ28H3700027182	Colour	ORANGE	
Odometer	16533	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	195/50 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	195/50 R16	BRIDGESTONE	5 mm	
L/H Rear Tyre	195/50 R16	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/04/2018	Inspection Date	06/04/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 4710S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	PANEL SUB-ASSY, BACK (SN)	BUCKLED	1,097.60	1,097.60
1	GLASS SUB-ASSY, BACK (SN)	NECESSARY	973.80	973.80
2	DAM, BACK WINDOW GLA (SN)	NECESSARY	24.00	24.00
1	W/SCREEN GLS DAM KIT (SN)	NECESSARY	101.00	101.00
1	SINGLE STEP PRIMER (SN)	NECESSARY	173.44	173.44
1	SUPER FAST URETHANE BLACK (SN)	NECESSARY	90.08	90.08
1	TOYOTA SYMBOL EMBLEM (SN)	NECESSARY	72.20	72.20
1	PLATE, BACK DOOR NAM (SN)	NECESSARY	51.50	51.50
1	PLATE, BACK DOOR NAM (SN)	NECESSARY	34.40	34.40
1	EXTENSION, RR BUMPER (SN)	NOT NECESSARY	125.20	-
1	EXTENSION, RR BUMPER (SN)	DEFORMED	184.20	184.20
1	COVER, RR BUMPER, L (SN)	SERVICEABLE	306.40	-
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NECESSARY	100.00	100.00
			3,433.82	2,952.22
LABOUR				
	CHK REAR WIRING SYSTEM AND CONDUCT WATER TEST.		154.00	154.00
	DRILL HOLE TO INSTALL REVERSE SENSOR.		154.00	154.00
	REMOVE BOOT INTERIOR TO ASSIST REPAIR.		308.00	308.00
	REPLACE REAR W/SCREEN GLASS TO ASSIST REPAIR.		385.00	385.00
	SUPPLY AND INSTALL REAR W/SCREEN SOLAR FILM.		400.00	400.00
	REMOVE ATIL-GATE COMPONENTS TO TRANSFER ONTO NEW DOOR.		308.00	308.00
	REMOVE ALL NECESSARY DAMAGED PARTS TO REPLACE, REPAIR, STRAIGHTEN REAR BUMPER, TAIL-GATE, TAIL-LAMP PANEL AND AFFECTED PORTION OF CAR.		2,464.00	1,848.00
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		2,024.00	1,518.00
			6,197.00	5,075.00
GRAND TOTAL			9,630.82	8,027.22



RECOMMENDED COST OF REPAIRS			8,027.22
-----------------------------	--	--	----------

Report Ref No. CS/EGI18006109/R1td3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.