COMFORTDELGRO ENGINEERING PTE LTD **REPAIR ESTIMATE***

VEHICLE NO: SHD 6918Y

MAKE

MODEL : HYUNDAI i40

CHWA LKK Jh DATE 29/3/2018 16:42

Qty	Parts Description/ Labour P//P		Unit Price		Amount		
	Rear Bumper				\$	603.60	1
	Rear Bumper Reinforcement .7				\$	504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$	180.00	\$	360.00	
	Rear Bumper Side Bracket ?				\$	49.00	
	Rear Bumper Clips				\$	22.00	
	Rear Bumper Sponge ?				\$	143.40	1
	Rear Bumper Under Cover				\$	225.00	
	Per Boot / (RH) laup - SUB TOTAL				\$	1,907.35	1
	LESS 20%				\$	381.47	
	DISCOUNTED TOTAL				\$	1,525.88	-
	DISCOUNTED TOTAL				J.	1,525.00	
						125.50	
	Rear Bumper Reverse Sensor				\$	135.70	N
					_		4
					\$	135.70	4
	Labour Charge					200	-
	Panel Beating				\$	250.00	-
	Spray Painting Charge				\$	2 50. 00	2
	Wiring Charge				\$	50.00	T
	R/Refix Reverse Sensor				\$	120.00	12
	TOTAL LABOUR				\$	670.00	
	ESTIMATE TOTAL				\$	2,331.58	-
	ESTIMATE TOTAL [Ca/m / (//// // 2/4/8 11454 2 Days				•	2,331.30	╡
	1/ 1/1/1/1/						
	Cala	LKK	Auto Consu	ıltants hence n	otify		
	11 1,101,00	• To re	epairer of t	he following: lafter spray painti		- 1	
	1/ 2/4/18 11 412	• To di	splay damage	d part(s) during re	SULVA	,	
		• Parts	prices are su	bject to confirmati	bn.		
	2 Vy 1	• No ill	egal modificat	is on a "Without P	ejudio	e" basis	
	0/0	• Supp	ementary iter	SI MUS DA FORUE	veyed	and	
	E/P	IS SU	ect to final ar	proval from Insur	ance (Company	
	Before Pert p	Agenov	ledged by Re	pairer			
	Batre Per A	dignatu	e:				
		Date:			I		1

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.