

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
 AUTOBAY, SINGAPORE 417883
 HP: 96709191 FAX: 66840767

QBE Insurance (S) Pte Ltd
 1 Raffles Quay
 #29-10 South Tower
 Singapore 048583
 Attn: Motor Claims Department

Date: 3 April 2018

**Accident on 14/03/2018 involving vehicles PC2570C & GZ94272
 along Paya Lebar Road**

Estimate cost of repair to vehicle PC2570C Toyota Hiace Hi-roof

1 pc.	tailgate hi-roof	DO/Beal	\$	2,419.10	✓
1 pc.	tailgate rear logo	rec	\$	68.10	✓
1 pc.	tailgate commuter sticker	rec	\$	48.50	✓
1 pc.	tailgate 3.0 emblem	rec	\$	45.00	✓
1 pc.	tailgate inner lock	11	\$	295.20	X
1 pc.	tailgate weatherstrip	11	\$	387.20	X
1 pc.	rear bumper	2	\$	680.10	X
1 pc.	rear end panel outer	2	\$	566.10	X
1 pc.	rear end panel inner	2	\$	929.30	X
			\$	5,438.60	
			Less 25%	\$	1,359.65
			\$	4,078.95	

S.Nett Items:

1 pc.	rear bumper top protector	De	\$	420.00	✓
1 pc.	rear bumper lower skirting	gaut	\$	480.00	✓
1 set	rear bumper clips	rec	\$	50.00	✓
1 pc.	rear windscreen sealant	rec	\$	50.00	40
1 pc.	rear 70km/hr sticker	rec	\$	20.00	10

Labour Charges:

To check wiring	\$	50.00	20
To remove & reinstall rear windscreen	\$	150.00	100
To transfer tailgate mechanism	\$	100.00	60
To spray rust proofing	\$	100.00	30
To remove & refix rear exhaust	\$	100.00	X
Labour for panel beating, welding & renew parts	\$	700.00	400
Spray painting	\$	750.00	400
Total:	\$	7,048.95	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Admit
 dhr

2/5 @ 3100
 3 day.
 3/4/18

Attn: Mr. Marans (Surveyor)
 telephone other 4 -