

ASS. REC. BY:

REF: CS/MSG18006123/ R1/d3k2

Special Instruction:

Surveyor:

Racul

ASSIGNMENT (Office)

Meimien

From (Person):

Irene Tan

of

MSG

Date/Time:

31/1/18 @ 1.35pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL681D

Insured:

SGN 7762G

at Workshop m/s

Ding Auto

Tel:

9231 3123

of

Blk 10, # 01-20 Sin Ming Ind. Est 800-C

Policy No:

290326967MC

Claim No:

554305

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 31/03/2018

1/1/18 @ 249 Jalan Bernam

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

5.19pm @ 31/1/18

Person Contacted:

Kenneth

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLL681D-X

SGN 7762G-X

05/04/18 @ 16.00 p.m. revised to Irene Tan Gel. Ing v.s meimien.

Finalised part by part \$2783.50 (Red: 7602.75; 73%)

Rajan

REF: mslh

4597K

ASSIGNMENT

From: Date: 04-04-2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL 6810
at Workshop m/s Ding Auto
of 249 Jln Boon Lay

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'Wp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SL 6810 Yr Regn: 2017 / 168

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Corolla Altis 1.6 c.c 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 77886 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MK053REH10456285

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

31/03/18

D.O.I.

04/04/18

Survey held at

DING AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 30 APR 2018

Date/Time, File Pass to?

1) 30/4 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I. (\$) 2783.501

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

300

10

310

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Apr 2018 Sendback Est	03 Apr 2018 11:29 S\$10,386.25	03 Apr 2018 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	RIDE NOW PRIVATE LIMITED, Co. Reg. No.: 201628643D		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLL681D	Date of Loss:	31/03/2018 17:00 - :59 [13 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 554305	Policy/Cover Note No.:	29032696TMC (Comprehensive) Coverage: 24/02/2018 - 23/02/2019
Vehicle Reg. No. (Insured):	SGN7762G	Policy No. (Claimant):	999995061
		Excess:	
Repairer:	Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/04/2018]		
Adj Asg. Remarks:	Vehicle lying at 249 Jalan Boon Lay. PLEASE ALIASE Kenneth Ding HP: 92313123		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG_SG (03/04/2018): Cancellation of Assignment: SLL681D

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18006123/R1td3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 03-04-2018	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGN 7762G	Veh. Inspected	SLL 681D	
Policy No.	29032696TMC	Coverage (\$)	0.00	
Claim No.	554305	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	31/03/2018	Inspection Date		
Survey held at	249 JALAN BOON LAY			
Repairer	DING AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

AUNG NYI NYI
249 JALAN BOON LAY
Singapore

Claimant Insurer: AIG Asia Pacific Insurance Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:	999995061	Date of Loss:	31/03/2018
Vehicle Reg. No.:	SLL681D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAN BOON KENG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	13/02/2017
Vehicle Colour:	Blue		
Engine No:	1ZRY347104	Chassis No:	MR053REH104562565
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO STATEMENT		
Remarks:	VEHICLE LYING 249 JALAN BOON LAY		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,606.25
Miscellaneous Items	830.00
Labour	3,950.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	10,386.25
+ GST 7.00% (S\$)	727.04
Nett Amount (S\$)	11,113.29

This claim is handled by: YOU JING FENG

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 05 Apr 2018

Preliminary Advice

Insured Vehicle No	: SGN7762G	Accident Date	: 31/03/2018
TP Vehicle No	: SLL681D	Assignment Date	: 03/04/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 7 days
Date of Inspection	: 04/04/2018		
Inspection At	: Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C Singapore 575645		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,386.25
Revised Amount	:S\$	2,783.50
Check Items (Estimated)	:S\$	2,207.25
Total	:S\$	4,990.75

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/04/2018 16:56
Date Of Accident 31/03/2018 17:50
Exact Location Of Accident BEACH ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLL681D
Insured/Policyholder
Name Of Registered Owner LCRF PTE LTD
Co Reg No 201624597K
Email Address NOEMAIL
Mobile Phone No
Alternative Phone No OFFICE-31584255

Vehicle Particulars

Manufacturer TOYOTA
Model COROLLA ALTIS-1.6 CLASSIC CVT (A)
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 999995061
Cover Note Number

Driver

Name of Driver TAN BOON KENG
NRIC No S1772355C
Date Of Birth 13/09/1966
Occupation OUTDOOR
Date Of Driving Pass 28/06/1994
Driving Experience 23 YEARS AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-92394128
Fax Number
Contact Number
Email Address NOEMAIL

Address	249 JALAN BOON LAY
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGN7762G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



x 33,

02/04/18
1300





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 31/3/2018, at 1750, I driving along
Beach road toward city. suddenly vehicle
SGN 7762 G came out from the small road
and hit into the left of my vehicle. Traffic
police came and record the accident, and told
us to lodge a accident report. There is
no one injured after the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:

02/04/18
1300

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



LIST ITEMS

<u>PAY</u>	<u>UNPAID</u>
480.00	450.00
85.00	155.00
45.00	100.00
80.00	40.00
	80.00
	90.00
	200.00
	80.00
	100.00
	90.00
	200.00
	500.00
	35.00
	185.00
	180.00
	80.00
	165.00
	170.00
	170.00
	990.00
	80.00
	45.00

NETT ITEMS

<u>PAY</u>	<u>UNPAID</u>
300.00	350.00
	180.00

LABOUR

<u>PAY</u>	<u>UNPAID</u>
30.00	170.00
80.00	40.00
60.00	120.00
60.00	40.00
60.00	340.00
700.00	700.00
700.00	500.00
	350.00

300.00

530.00

690.00

4185.00

1690.00

2260.00

4875.00

690.00

4185.00

830.00

300.00

530.00

3950.00

1690.00

2260.00

690.00

103.50 (15% DISC)

793.50 586.50 LIST ITEM AFTER DISC (PAY)

300.00 NETT ITEM (PAY)

1690.00 LABOUR (PAY)

2,783.50 2576.50

90.00
200.00
165.00
170.00
990.00



CHECK ITEM

1615.00

242.25 (15% DISC)

1,857.25

1372.75 LIST ITEM AFTER DISC (CHECK ITEM)

350.00 LABOUR (CHECK ITEM)

2,207.25

1722.75

TOTAL = 4299.25 (PAY ITEM + CHECK ITEM)

4,990.75

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2018)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SLL681D/03/04/2018 11:29

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHR DOOR	0.00	0.00	R *450.00 F
2	1		*LHR DOOR OUTER CHROME MLDG	0.00	0.00	X *155.00 F
3	1		*LHF DOOR CHECKER	0.00	0.00	X *100.00 F
4	1		*LHF DOOR GLASS RUBBER BEADING	0.00	0.00	X *40.00 F
5	1		*LHF DOOR WEATHESTRIIP	0.00	0.00	X *80.00 F
6	1		*LHF DOOR REGULATOR	0.00	0.00	X *90.00 F
7	1		*LHF DOOR REGULATOR MOTOR	0.00	0.00	X *200.00 F
8	1		*LHR DOOR	0.00	0.00	R *480.00 F
9	1		*LHR DOOR OUTER CHROME MLDG	0.00	0.00	R *85.00 F
10	2		*LHR DOOR HINGE	0.00	0.00	R *80.00 F
11	1		*LHR DOOR CHECKER	0.00	0.00	R *100.00 F
12	1		*LHR DOOR GLASS RUBBER BEADING	0.00	0.00	R *45.00 F
13	1		*LHR DOOR WEATHESTRIIP	0.00	0.00	R *80.00 F
14	1		*LHR DOOR REGULATOR	0.00	0.00	R *90.00 F
15	1		*LHR DOOR REGULATOR MOTOR	0.00	0.00	R *200.00 F
16	1		*LHR FENDER	0.00	0.00	R *500.00 F
17	1		*LHR FENDER SPLASH SHIELD	0.00	0.00	R *35.00 F
18	1		*LHS ROCKER PANEL	0.00	0.00	R *185.00 F
19	1		*LHR SHOCK ABSORBER	0.00	0.00	R *180.00 F
20	1		*LHR SHOCK ABSORBER TOP MOUNTING	0.00	0.00	R *80.00 F
21	1		*LHR WHEEL HUB ASSY	0.00	0.00	R *165.00 F
22	1		*LHR STABILIZER BAR	0.00	0.00	R *170.00 F
23	1		*DISC ROTOR LHS	0.00	0.00	R *170.00 F
24	1		*REAR AXLE BEAM	0.00	0.00	R *990.00 F
25	2		*LHF DOOR HINGE LH & RH	0.00	0.00	R *80.00 F
26	1		*LHR FENDER GARNISH	0.00	0.00	R *45.00 F

F=Franchise part.

Sub Total (S\$)	4,875.00
+ Margin on L,N Items 15.00% (S\$)	731.25
Total Parts (S\$)	5,606.25

Ding Auto Pte Ltd/SLL681D/03/04/2018 11:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

No	Qty	Particulars
1	1	LHR RIM
2	1	LHR TYRE

sur 300
~~650.00~~
 sur X 180.00

Sub Total (S\$) 830.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	CHECK WIRING	New	30	200.00
2	RUST PROOFING	New	60	120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	60	180.00
4	R & R TYRE AND RIM	New	60	180.00
5	TO TRANSFER LHF DOOR AND REAR DOOR MECHANISM TO THE NEW DOOR	New	60	400.00
6	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS	New	700	1,400.00
7	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, KNOCK OUT DENTS ON AFFECTED PORTION, ADJUST AND REALIGN BACK TO THE SAME	New	600	1,200.00
8	R & R LHR UNDER CARRIAGE	New	700	350.00

Gross Labour Cost (S\$) 3,950.00

Ding Auto Pte Ltd/SLL681D/03/04/2018 11:29. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
 Hp 90010068
 7 days
 4/3
 04/04/18 @ 1800
 Resurvey after paint

TP INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)**
AUNG NYI NYI
249 JALAN BOON LAY
Singapore

Claimant Insurer: **AIG Asia Pacific Insurance Pte. Ltd.**

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:	999995061	Date of Loss:	31/03/2018
Vehicle Reg. No.:	SLL681D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAN BOON KENG		
Make/Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Vehicle Reg. Date:	13/02/2017
Vehicle Colour:	Blue		
Engine No:	1ZRY347104	Chassis No:	MR053REH104562565
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Description of Accident/Loss	REFER TO STATEMENT		
Remarks:	VEHICLE LYING 249 JALAN BOON LAY		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS		Amount
Parts		5,606.25
Miscellaneous Items		830.00
Labour		3,950.00
Paintwork Labour		0.00
Towing		0.00
Gross Total (S\$)		10,386.25
+ GST 7.00% (S\$)		727.04
Nett Amount (S\$)		11,113.29

This claim is handled by: YOU JING FENG

AIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Apr 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Ding Auto Pte Ltd/SLL681D/03/04/2018 11:29	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*LHR DOOR	0.00	0.00	R *450.00 F
2	1		*LHR DOOR OUTER CHROME MLDG	0.00	0.00	X *155.00 F
3	1		*LHF DOOR CHECKER	0.00	0.00	X *100.00 F
4	1		*LHF DOOR GLASS RUBBER BEADING	0.00	0.00	X *40.00 F
5	1		*LHF DOOR WEATHESTRIIP	0.00	0.00	X *80.00 F
6	1		*LHF DOOR REGULATOR	0.00	0.00	X *90.00 F
7	1		*LHF DOOR REGULATOR MOTOR	0.00	0.00	X *200.00 F
8	1		*LHR DOOR	0.00	0.00	R *480.00 F ✓
9	1		*LHR DOOR OUTER CHROME MLDG	0.00	0.00	R *85.00 F ✓
10	2		*LHR DOOR HINGE	0.00	0.00	X *80.00 F
11	1		*LHR DOOR CHECKER	0.00	0.00	X *100.00 F
12	1		*LHR DOOR GLASS RUBBER BEADING	0.00	0.00	R *45.00 F ✓
13	1		*LHR DOOR WEATHESTRIIP	0.00	0.00	R *80.00 F ✓
14	1		*LHR DOOR REGULATOR	0.00	0.00	? *90.00 F
15	1		*LHR DOOR REGULATOR MOTOR	0.00	0.00	? *200.00 F
16	1		*LHR FENDER	0.00	0.00	R *500.00 F
17	1		*LHR FENDER SPLASH SHIELD	0.00	0.00	X *35.00 F
18	1		*LHS ROCKER PANEL	0.00	0.00	R *185.00 F
19	1		*LHR SHOCK ABSORBER	0.00	0.00	X *180.00 F
20	1		*LHR SHOCK ABSORBER TOP MOUNTING	0.00	0.00	X *80.00 F
21	1		*LHR WHEEL HUB ASSY	0.00	0.00	? *165.00 F
22	1		*LHR STABILIZER BAR	0.00	0.00	? *170.00 F
23	1		*DISC ROTOR LHS	0.00	0.00	X *170.00 F
24	1		*REAR AXLE BEAM	0.00	0.00	? *990.00 F
25	1		*LHF DOOR HINGE LH & RH	0.00	0.00	X *80.00 F
26	1		*LHR FENDER GARNISH	0.00	0.00	X *45.00 F

F=Franchise part.

Sub Total (\$\$)	4,875.00
+ Margin on L,N Items 15.00% (\$\$)	731.25
Total Parts (\$\$)	5,606.25

Ding Auto Pte Ltd/SLL681D/03/04/2018 11:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Parts \$690.00 + 10%

= 769.00

SN \$ 300.00

Labour \$ 1690.00

Total \$ 2759.00

Estimates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	LHR RIM	300
2	LHR TYRE	180.00
Sub Total (S\$)		830.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	CHECK WIRING	New	30 200.00
2	RUST PROOFING	New	60 120.00
3	TO CONDUCT WHEEL ALIGNMENT	New	60 180.00
4	R & R TYRE AND RIM	New	60 100.00
5	TO TRANSFER LHF DOOR AND REAR DOOR MECHANISM TO THE NEW DOOR	New	60 400.00
6	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS	New	700 1400.00
7	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, KNOCK OUT DENTS ON AFFECTED PORTION, ADJUST AND REALIGN BACK TO THE SAME	New	700 1200.00
8	R & R LHR UNDER CARRIAGE	New	350.00
Gross Labour Cost (S\$)			3,950.00

Ding Auto Pte Ltd/SLL681D/03/04/2018 11:29. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repair
Hp 90010068
7 days
Part By Part
04/04/18 @ 1800
Resurvey after paint



天美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

DING AUTO PTE LTD.(LCR)

249 JALAN BOON LAY BESIDE STA INSPECTION

TEL : 64521208 FAX : 64520614

ATTN : FENG

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9809



Dept Direct: 6417 9794

Dept Direct: 6417 9796

Dept Direct: 6417 9798

Dept Direct: 6

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201804-1091

DATE : 05/04/2018

CUSTOMER ID : DIN00

VEH REG. NO. : SLL681H

TERMS : 90 day

PO NO. :

PAGE NO. : Page 1 of

CURR : S

SQ STOCKID

DESCRIPTION

StkLoc

QTY

U/PRICE

AMOUNT

1. T67004-02430

RR DOOR L.H

WH

1

480.00

480.00

ZRE171

W

2. T75740-02360

RR DOOR GLASS OUTER M.DG

WH

1

85.00

85.00

L.H

ALTIS-ZRE171

W

3. T68152-02320

RR DOOR RUNCHANNEL L.H

WH

1

45.00

45.00

ZRE171

W

4. T67872-02260

RR DOOR RUBBER L.H

WH

1

80.00

80.00

ZRE171

W

SUB-TOTAL : 690.00

ADD GST 7.00 % 48.30

E. & O.E

TOTAL AMOUNT S\$: 738.30

[P] 05/04/2018 4:20:41PM

[E] 05/04/2018 4:19:18PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte Ltd

Sales Executive STEVEN



AR201804-10910

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 Apr 2018 Sendback Est	03 Apr 2018 11:29 S\$10,386.25	03 Apr 2018 16:35 Edit Adj Rpt	S\$2,783.50 Edit Estimates	S\$2,783.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured: RIDE NOW PRIVATE LIMITED , Co. Reg. No.: 201628643D									
Main Claimant: LCRF PTE LTD , Co. Reg. No.: 201624597K									
Vehicle Reg. No.:	SLL681D	Date of Loss:	31/03/2018 17:00 - :59 [13 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 554305	Policy/Cover Note No.:	29032696TMC (Comprehensive) Coverage: 24/02/2018 - 23/02/2019						
Vehicle Reg. No. (Insured):	SGN7762G	Policy No. (Claimant):	999995061						
		Excess:							
Repairer: Ding Auto Pte Ltd (HQ) Blk 10, #01-20, Sin Ming Industrial Estate Sector C, 575645 Sin Ming - Tel: 64521208									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/05/2018]									
Adj Asg. Remarks: Vehicle lying at 249 Jalan Boon Lay. PLEASE ALIASE Kenneth Ding HP: 92313123									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
MSIG_SG (03/04/2018): Cancellation of Assignment: SLL681D									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SLL681D (554305)
[SGN7762G]
TP
LCRF PTE LTD
Mar 31 2018 5:00PM
[RIDE NOW PRIVATE LIMITED]
Ding Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View [View in Browser](#)
Assessment Reports

1 per page



No	Finalized On	Ding Auto Pte Ltd (HQ)	Thumbnail	Print
1	02/04/18 17:05	Accident Statement	 Load HTM	☐
2	03/04/18 11:29	Repairer Estimates	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/04/18 16:00	Adjuster Immediate Advice	 Load HTM	☐

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/18 11:24	General View	 Load JPG ☒	☒
2	30/04/18 11:24	General View	 Load JPG ☒	☒
3	30/04/18 11:24	General View	 Load JPG ☒	☒
4	30/04/18 11:24	General View	 Load JPG ☒	☒
5	30/04/18 11:24	General View	 Load JPG ☒	☒
6	30/04/18 11:24	General View	 Load JPG ☒	☒
7	30/04/18 11:24	General View	 Load JPG ☒	☒
8	30/04/18 11:24	General View	 Load JPG ☒	☒
9	30/04/18 11:24	General View	 Load JPG ☒	☒
10	30/04/18 11:24	General View	 Load JPG ☒	☒
11	30/04/18 11:24	General View	 Load JPG ☒	☒
12	30/04/18 11:24	General View	 Load JPG ☒	☒
13	30/04/18 11:24	General View	 Load JPG ☒	☒
14	30/04/18 11:24	General View	 Load JPG ☒	☒
15	30/04/18 11:24	General View	 Load JPG ☒	☒
16	30/04/18 11:24	General View	 Load JPG ☒	☒
17	30/04/18 11:24	General View	 Load JPG ☒	☒
18	30/04/18 11:24	General View	 Load JPG ☒	☒
19	30/04/18 11:24	General View	 Load JPG ☒	☒
20	30/04/18 11:24	General View	 Load JPG ☒	☒
21	30/04/18 11:24	General View	 Load JPG ☒	☒
22	30/04/18 11:24	General View	 Load JPG ☒	☒
23	30/04/18 11:24	General View	 Load JPG ☒	☒
24	30/04/18 11:24	General View	 Load JPG ☒	☒
25	30/04/18 11:24	General View	 Load JPG ☒	☒
26	30/04/18 11:24	General View	 Load JPG ☒	☒
27	30/04/18 11:24	General View	 Load JPG ☒	☒
28	30/04/18 11:24	General View	 Load JPG ☒	☒
29	30/04/18 11:24	General View	 Load JPG ☒	☒
30	30/04/18 11:24	Reinspection Photo	 Load JPG ☒	☒
31	30/04/18 11:24	Reinspection Photo	 Load JPG ☒	☒

Assessment Reports			1 per page	☒
No	Finalized On		Thumbnail	Print
32	30/04/18 11:24	Ding Auto Pte Ltd (HQ) Reinspection Photo	 Load JPG	☒
33	30/04/18 11:24	Reinspection Photo	 Load JPG	☒
34	30/04/18 11:24	Reinspection Photo	 Load JPG	☒
35	30/04/18 11:24	Reinspection Photo	 Load JPG	☒
36	30/04/18 11:24	Reinspection Photo	 Load JPG	☒
37	30/04/18 11:24	Reinspection Photo	 Load JPG	☒
38	30/04/18 11:24	Reinspection Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) 				
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18006123/R1TD3E2

Date: 30/04/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29032696TMC

Claimant Vehicle No : SLL681D

Insured Vehicle No : SGN7762G

Date of Loss: 31/03/2018

Nature of Claim: TP

Claim No: 554305

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL681D

Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)

Engine No: 1ZRY347104

Reg. Date: 13/02/2017 (Man. Year: 2016)

Chassis No: MR053REH104562565

Colour: Grey

Odometer: 77006 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16

Rear Tyre Size: 205/55R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,606.25	793.50	4,812.75	85.85
Miscellaneous Items	830.00	300.00	530.00	63.86
Labour	3,950.00	1,690.00	2,260.00	57.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,386.25	2,783.50	7,602.75	73.20
+ GST 7.00/7.00% (S\$)	727.04	194.85	532.19	73.20
Nett Amount (S\$)	11,113.29	2,978.35	8,134.94	73.20

INSPECTION

Date of Assignment: 03/04/2018

Date Inspected: 04/04/2018 Inspected At:

249 Jalan Boon Lay
 Repairer: Ding Auto Pte Ltd (HQ)
 Blk 10, #01-20, Sin Ming Industrial Estate
 Sector C
 Singapore 575645

Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Apr 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 CLASSIC CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLL681D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHR DOOR (WCP)	Repair	450.00 F	*- F
2	1		*LHR DOOR OUTER CHROME MLDG (WCP)	Serviceable	155.00 F	*- F
3	1		*LHF DOOR CHECKER (WCP)	Serviceable	100.00 F	*- F
4	1		*LHF DOOR GLASS RUBBER BEADING (WCP)	Serviceable	40.00 F	*- F
5	1		*LHF DOOR WEATHESTRIIP (WCP)	Serviceable	80.00 F	*- F
6	1		*LHF DOOR REGULATOR (WCP)	Serviceable	90.00 F	*- F
7	1		*LHF DOOR REGULATOR MOTOR (WCP)	Serviceable	200.00 F	*- F
8	1		*LHR DOOR (WCP)	Bent	480.00 F	*480.00 F
9	1		*LHR DOOR OUTER CHROME MLDG (WCP)	Necessary	85.00 F	*85.00 F
10	2		*LHR DOOR HINGE (WCP)	Serviceable	80.00 F	*- F
11	1		*LHR DOOR CHECKER (WCP)	Serviceable	100.00 F	*- F
12	1		*LHR DOOR GLASS RUBBER BEADING (WCP)	Necessary	45.00 F	*45.00 F
13	1		*LHR DOOR WEATHESTRIIP (WCP)	Necessary	80.00 F	*80.00 F
14	1		*LHR DOOR REGULATOR (WCP)	Serviceable	90.00 F	*- F
15	1		*LHR DOOR REGULATOR MOTOR (WCP)	Serviceable	200.00 F	*- F
16	1		*LHR FENDER (WCP)	Repair	500.00 F	*- F
17	1		*LHR FENDER SPLASH SHIELD (WCP)	Serviceable	35.00 F	*- F
18	1		*LHS ROCKER PANEL (WCP)	Repair	185.00 F	*- F
19	1		*LHR SHOCK ABSORBER (WCP)	Serviceable	180.00 F	*- F
20	1		*LHR SHOCK ABSORBER TOP MOUNTING (WCP)	Serviceable	80.00 F	*- F
21	1		*LHR WHEEL HUB ASSY (WCP)	Serviceable	165.00 F	*- F
22	1		*LHR STABILIZER BAR (WCP)	Serviceable	170.00 F	*- F
23	1		*DISC ROTOR LHS (WCP)	Serviceable	170.00 F	*- F
24	1			Not Necessary	990.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*REAR AXLE BEAM (WCP)			
25	2		*LHF DOOR HINGE LH & RH (WCP)	Serviceable	80.00 F	*- F
26	1		*LHR FENDER GARNISH (WCP)	Serviceable	45.00 F	*- F
F=Franchise part.						
					Sub Total (S\$)	4,875.00 690.00
					+ Margin on L,N Items 15.00/15.00% (S\$)	731.25 103.50
					Total Parts (S\$)	5,606.25 793.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	LHR RIM (Scratched)	650.00	300.00
2	1	LHR TYRE (Serviceable)	180.00	0.00
Sub Total (S\$)			830.00	300.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	200.00	30.00
2	RUST PROOFING	New	120.00	80.00
3	TO CONDUCT WHEEL ALIGNMENT	New	180.00	60.00
4	R & R TYRE AND RIM	New	100.00	60.00
5	TO TRANSFER LHF DOOR AND REAR DOOR MECHANISM TO THE NEW DOOR	New	400.00	60.00
6	TO PUTTY AND SPRAY PAINT ON THE AFFECTED AREAS	New	1,400.00	700.00
7	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,KNOCK OUT DENTS ON AFFECTED PORTION,ADJUST AND REALIGN BACK TO THE SAME	New	1,200.00	700.00
8	R & R LHR UNDER CARRIAGE	New	350.00	-
Gross Labour Cost (S\$)			3,950.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >