

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

2-Apr-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6413 S

1 pc	Rear bumper ✓	\$	696.00
1 pc	Rear bumper lower cover ✓	\$	206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 ✓	\$	58.00
1 pc	Rear bumper inner sponge ✗	\$	114.00
1 pc	Rear bumper reinforcement ✗	\$	607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 ✗	\$	106.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 ✗	\$	36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 ✗	\$	36.00
		\$	<u>1,859.00</u>
		Less 10%	\$ 185.90
		\$	<u>1,673.10</u>

### S/NETT

1 set	Rear bumper clips ✓	\$	48.00
1 set	Reverse sensor ✓	\$	<del>280.00</del> 200
	Sundry	\$	<del>50.00</del> ✗
	To dismantle / replace/test reverse sensor to new bumper and reset to the same	\$	<del>120.00</del> 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	<del>180.00</del> ✗
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$	<del>700.00</del> 200
	To putty and spray painting on rear bumper, end panel	\$	<del>450.00</del> 180
	To apply rustproofing on the repaired and replaced panels.	\$	<del>120.00</del> ✗
		\$	<u>3,621.10</u>

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

JKK Auto Consultants hence notify  
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE  
ANY UNFORESEEN DAMAGES.

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Kaha 11/11/18  
3/4/18 10.15 hrs.  
2 days  
4/5  
After Repair photo