

6130/mn

67458520 u

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

29-05-18

Attn: Marcus.

Date of Accident : 01-04-18

OUR REF : GBG 7055K/T/16

BACHY SOLETANCHE SINGAPORE PTE LTD

80 Raffles Place

#32-01 UOB Plaza

Singapore 048624

ESTIMATE BILL ON VEH. NO. : GBG 7055KMODEL : ISUZU TFR86JDRCHASSIS NO : MPATFR86JHT002641LIST ITEM

Tail Gate		20/300 1,300.00 ✓
Tail Gate Hingde	2pcs @ 45.00	11 90.00 X
Tail Gate Side Lock	2pcs @ 75.00	11 150.00 X
Tail Gate Checker	2pcs @ 65.00	11 130.00 X
Tail Gate Sticker "2.5 TD"		neu 35.00 //
Tail Gate Sticker "ISUZU"		neu 34.00 //
Tail Gate Sticker "D-Max"		neu 32.00 /
Tail Lamp - RH		scr 155.00 /
Rear Number Plate Lamp	2pcs @ 65.00	one 130.00 1pc
Rear Number Plate Garnish		Dis 115.00 ✓
Rear Bumper Assy		scr 1,400.00 /
Rear Bumper Step Garnish		Dis 420.00 /
Rear Bumper Bracket	2pcs @ 55.00	scr 110.00 /
		15/3 4,101.00
Less Discount 10%:		410.10
		3,690.90
		3666
		3116.1

SPECIAL NETT ITEM

Tail Gate Inner Aluminium Plate	11 350.00 X
70km/h Sticker	neu 20.00 10
9 Pax Sticker	neu 20.00 10
Reverse Sensor	scr 380.00 200

Rear Number Plate

45.00 15

LABOUR CHARGE

Towing.

80.00 X

To Check Wiring System.

80.00 30

To Tuff Coat Affected Areas.

180.00 50

To Remove & Refix Reverse Sensor.

150.00 50

/

To Respray Affected Areas.

1,200.00 800

To Renew Damaged Parts, Straighten & Repair Rear Rh & LH Fender,
Rear End Panel & Aligned All Parts.

1,200.00 800

TOTAL :	7,395.90
GST 7% :	517.71
AMOUNT DUE :	<u>7,913.61</u>