



UNIQUE MOTORSPORTS PTE LTD

11 Tannery Lane Singapore 207930 (Head Office)
1007/1009 Serangoon Road Singapore 328168 (Show Room)
1 Kaki Bukit Ave 6 #02-54/55 Autobay @ Kaki Bukit Singapore 417883
48 Toh Guan Road East #02-140 Enterprise Hub Singapore 608586
280 Woodlands Industrial Park E5 #01-43 Harvest Singapore 757322

Tel: 6292 5578 (3 lines) Fax: 6295 5579
Tel: 6341 5378 (3 lines) Fax: 6341 7379
Tel: 6844 6378 (3 lines) Fax: 6844 6379
Tel: 6515 4978 (3 lines) Fax: 6515 4979
Tel: 6339 2178 (3 lines) Fax: 6339 3379

Date: 02/04/2018

Make / Model: Bajaj Pulsar NS200

Registration No: FBL3163G

Damage Assessment

S/N	Description	Condition	Qty	Unit Price	Total Price
1	Windscreen / <i>CRA</i>		1	\$62.00	\$62.00
2	Handle Bar – Left / <i>BT</i>		1	\$106.00	\$106.00
3	Signal Light Front – Left / <i>CRA</i>		1	\$95.00	\$95.00
4	Clutch Lever / <i>Cut</i>		1	\$71.00	\$71.00
5	Balancer / <i>Cut</i>		1	\$39.00	\$39.00
6	Mirror – Left / <i>Cut</i>		1	\$82.00	\$82.00
7	Rear Box Assy 42L / <i>Cut</i>		1	\$220.00	\$220.00
8	In Vehicle Unit / <i>DM</i>		1	\$156.00	\$156.00
9	Patrol Light Front – Left / <i>DM</i>		1	\$450.00	\$450.00
10	Customised Patrol Light Bracket / <i>BT</i>		1	\$120.00	\$120.00
11	Number Plate – Front / <i>Cut</i>		1	\$15.00	\$15.00
12	Respray Front Fender		1	\$60.00	\$60.00
13	Perform Electrical Check		1	\$20.00	\$20.00
14	Towing From Accident Scene – Workshop		1	\$35.00	\$35.00
15	Workmanship		1	\$200.00	\$200.00
16					\$0.00
17					\$0.00
18					\$0.00
19					\$0.00
20					\$0.00

150
400
100
50
120

Sub Total \$1,731.00
GST 7% \$121.17
Grand Total \$1,852.17

to Consultant's hence notify
-pa - owin
• esurvey before - ara - ating
• display damage part(s) on repair
• inspection subject to confirmation
• No party survey is on a "Without Prejudice" basis
• No alteration modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Prepared By: Alvin Koh
Acknowledged by Repairer
Signature:
Date:

UNIQUE MOTORSPORTS PTE LTD
GST Reg. No. 200907910H
11 Tannery Lane
Singapore 207930
Tel / Fax: 6292 5578 / 6295 5579

1276
10% : 1148.4
1373.4
20% : 1100
2 Days
ump sum repair
After repair photos
Page 1
Eno Qiang
8288 0282
03/4/18