



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD 5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Ref: CS/EGI18006140/Avbn2 Date: 17/10/2018 Code: EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 5489K	Veh. Inspected	GBA 48J
	Policy No.		Coverage (\$)	0.00
	Claim No.	YP5489K/SA/pl	Excess (\$)	0.00
	Assign From	YEE PEI LI	Assign Date	03/04/2018
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	JTFHT02P200001856	Colour	WHITE
	Odometer	227882 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15C	OHTSU	6 mm
	L/H Front Tyre	195 R15C	OHTSU	6 mm
	R/H Rear Tyre	195 R15C	JOURNEY	6 mm
	L/H Rear Tyre	195 R15C	JOURNEY	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/04/2018	Inspection Date	03/04/2018
	Survey held at	T & C AUTOMOTIVE NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	