

INS. CASE OWNER:

Janet

CC 4/EQ11800

6142,

Kaa3

LKK:

IDAC:

Surveyor:

KSC

DOI:

44-18

Date / Time:

3/4/18

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

YN 72465

Name of Insured:

EASTERN HARVEST FOOD (S) P/L

Insured Tel No.:

HP:

D.O.A.:

2/4/18

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Liu Junjie

Driver Tel No.:

85894364

(V/L: YES/NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

M.T.

JUNE AVE 6 S AVE 3

Junction.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SKD 85737



INSRS:

WSP:

Tel:

Liability:

RMKS:

Autowork



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

11/11/18

16085737 X, YN 72465 X

GID rear ended to TP.

offer 44963.75 as per TP LOD. NO DV required.

and settle in file pass in k to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

> THIN 23/5 2019

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Kenneth

Repair Cost:

US

SS 4400.00

(4 days)

Reduction:

\$2618.71

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B28, Ass. Ltr

Repair Cost:

SS 4400.00

Loss of Rental (LOR):

SS

561.75

(5 days)

x

\$112.35 (w/ GST)

Loss of Use (LOU):

SS

-

(S

x

days)

Loss of Income (LOI):

SS

-

(S

x

days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

3.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/Independent)

Legal Cost

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

IP

3) Survey fee:

\$4001-

Total:

SS

4963.75

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

4963.75

Name 1:

Autowork House

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

OIC
19/12
du

14

REF:

/A26 261

ASSIGNMENT

From:

Date: 04042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

Autowork House

of

Sin Ming

Insured:

Policy No:

Claims No:

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKD 8573J Yr Regn: 01, 12

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen Passat 1798

Colour:

m. D. Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

101570

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVW888307CE547839

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/40R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm

R/Bal. 8 mm

L/Bal. 7 mm

L/Bal. 8 mm

D.O.A. 2/4/18

D.O.I. 4/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

5/4 File pass to Catherine

LIS 344001- (Red: 2618-71/661.)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + RS \$

1 / Photo

1 / Other

2 /

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD			Ref : CC4/EQI18006142/Kua3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Date : 03-04-2018	
			Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 7246S	Veh. Inspected	SKD 8573J	
Policy No.	DMCPHQ17-006445	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	03/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/04/2018	Inspection Date	04/04/2018	
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

NG WAI KHEONG
c/o 46 Lentor Plain
Singapore 786548

Not Authorized
21 Sep 34400h
Recovery After Paint
4 days

Date: 03/04/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : VOLKSWAGEN PASSAT CC /SKD8573J		
1 pc	rear bumper	1,465.00
1 pc	rear bumper reinforcement	785.00
1 pc	rear bumper sponge 153.00	463.00
1 pc	rear bumper centre chrome moulding	167.30
1 pc	rear bumper side chrome moulding	155.00
1 pc	rear bumper lower pad	167.30
1 pc	rear bumper park sensor @ 365.10	1,460.40
1 pc	rear bumper tow cover	67.30
2 pcs	rear bumper side reflector @ 185.00	370.00
2 pcs	rear bumper side retainer @ 45.00	90.00
2 pcs	rear bumper corner retainer @ 45.00	90.00
1 pc	rear boot rib 1643.75	1,650.00
1 pc	rear boot weatherstrip	246.10
1 pc	rear boot lock	246.00
1 pc	rear boot lock catch	116.70
2 pcs	rear boot lamp @ 258.10	516.20
1 pc	rear boot centre emblem/lock handle	327.00
2 pcs	rear tail lamp @ 315.90	631.80
1 pc	rear end panel	594.00
1 pc	rear end panel garnish	311.40
1 pc	'PASSAT CC' emblem	66.70
1 pc	'TSI' emblem	36.50
2 pcs	number plate lamp @ 116.40	232.80
Sub-total		11,931.90
Less 10%		1,193.19
Sub-total		10,738.71
1 pc	number plate casing	35.00
1 pc	number plate	35.00
sub-total		10,808.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be submitted, and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

s.nett
s.nett

sub-total

35.00
35.00

	Balance brought forward.	10,808.71	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1,000.00	500/
	To check wiring system.	50.00	20/
	To apply waterproof sealant on affected areas.	nn 150.00	X
	To apply rust proofing on affected areas.	150.00	30/
	To spray painting on affected areas.	860.00	500/
	Total	13,018.71	

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

NG WAI KHEONG
c/o 46 Lenton Plain
Singapore 786548

*Not Authorized
L1 Sur &?
Resurvey After Paint
4 days*

Date: 03/04/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : VOLKSWAGEN PASSAT CC /SKD8573J		
1 pc	rear bumper	Bu 1,465.00 ✓
1 pc	rear bumper reinforcement	785.00 ?
1 pc	rear bumper sponge	Sm 463.00 X
1 pc	rear bumper centre chrome moulding	me 167.30 —
1 pc	rear bumper side chrome moulding	me 155.00 —
1 pc	rear bumper lower pad	Sm 167.30 X
1 pc	rear bumper park sensor	@ 365.10 Ser 1,460.40 Lt
1 pc	rear bumper tow cover	CM 67.30 —
2 pcs	rear bumper side reflector	@ 185.00 Sm 370.00 X
2 pcs	rear bumper side retainer	@ 45.00 Sm 90.00 X
2 pcs	rear bumper corner retainer	@ 45.00 Sm 90.00 X
1 pc	rear boot rib	Bu 1,650.00 ✓
1 pc	rear boot weatherstrip	Sm 246.10 X
1 pc	rear boot lock	R 246.00 X
1 pc	rear boot lock catch	R 116.70 X
2 pcs	rear boot lamp	N/S Ser @ 761.10 1,522.20 Lt
1 pc	rear boot centre emblem/lock handle	Per 327.00 —
2 pcs	rear tail lamp	@ 651.10 d/s Ser 1,302.20 Lt
1 pc	rear end panel	R 594.00 X
1 pc	rear end panel garnish	Sm 311.40 X
1 pc	'PASSAT CC' emblem	me 66.70 ✓
1 pc	'TSI' emblem	me 36.50 ✓
2 pcs	number plate lamp	@ 116.40 me 232.80 X
Sub-total		11,931.90
Less 10%		1,193.19
Sub-total		10,738.71
1 pc	number plate	s.nett 35.00
1 pc	number plate casing	s.nett 35.00 } 4 days
sub-total		10,808.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be itemised and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

	Balance brought forward.	10,808.71	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1,000.00	500/
	To check wiring system.	50.00	20/
	To apply waterproof sealant on affected areas.	na 150.00	X
	To apply rust proofing on affected areas.	150.00	30/
	To spray painting on affected areas.	860.00	500/
	Total	13,018.71	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	871J
Vehicle Details	
Vehicle No.:	SKD8573J
Vehicle to be Exported:	Yes
Intended Deregistration Date:	10 Oct 2019
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT CC 1.8T AT 3574H7
Primary Colour:	Brown
Manufacturing Year:	2011
Engine No.:	CDA263715
Chassis No.:	WVWZZZ3CZCE547839
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$32,160.00
Original Registration Date:	13 Jan 2012
First Registration Date:	13 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$32,160.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Jan 2022
PARF Rebate Amount:	\$19,296.00
Intended COE Rebate Details	
COE Expiry Date:	12 Jan 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$65,801.00
COE Rebate Amount:	\$14,840.00
Total Rebate Amount:	\$34,136.00

The information contained herein is correct as at 09 Oct 2019

OK

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Tuesday, 3 April 2018 12:01 PM
To: assignments
Subject: FW: Our ref: YN7246S, Your ref: SKD8573J-PRS
Attachments: 03042018094800-0001.pdf

12:55pm @ 3/4/18
vehicle in
Person @ American

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [mailto:janet.tan@eqinsurance.com.sg]
Sent: Tuesday, 3 April 2018 11:53 AM
To: autoworxhouse@hotmail.com; Admin A <admin-a@lkkauto.com>
Subject: Our ref: YN7246S, Your ref: SKD8573J-PRS

Without Prejudice
Save As To Costs

Dear Samantha

Please be informed that we shall appoint LKK Auto Consultants to attend to the PRS.

However, our insured has yet to report. We shall revert on liability soonest possible.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Glynstar



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the sender.

AUTOWORX HOUSE

176 Sin Ming Drive, #02-01 Sin Ming Autocare Singapore 575721
• Tel: 6452 8211 • Fax: 6451 7420

EQ Insurance Company Ltd.
Attn: Motor Claims Department

2/4/18

RECEIVED
- 3 APR 2018

EQ INSURANCE CO. LTD.

Dear Sir,

RE: Request for PRI for SKD P173J in an accident involving Y172465
@ Ang Mo Kio Ave 6 & Ave 3 Junction on 2/4/18 @ 1220hrs.

We have been authorised by Ng Wei Kheong, the registered owner
of motor vehicle: SKD P173J at the material time of accident to make a claim
against your insured.

Please give us the list of panel of your 10 survey firms for our selection to inspect the above
said vehicle or you may assign our choice from either one of the 3 survey firms.


- 1) Premier Appraiser Services
- 2) LKK Auto Consultants Pte Ltd
- 3) AJAX Inspection Services Pte Ltd

We will direct settle the claims with you if the survey is conduct by either of one the firms
mentioned.

Kindly contact us at 64528211 before coming to ensure the vehicle is in the workshop.

Thank you.

Yours Sincerely,



Autoworx House
Email: autoworxhouse@hotmail.com

Mei Kwan (LKKAUTO)

From: Janet Tan <janet.tan@eqinsurance.com.sg>
Sent: Thursday, 10 May, 2018 10:34 AM
To: Mei Kwan (LKKAUTO)
Cc: Admin A; Thin Thin (LKKAUTO); Vivian Lau (LKKAUTO)
Subject: RE: Our ref: YN7246S, Your ref: SKD8573J
Attachments: YN7246S.PDF

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Mei Kwan

OI report as attached.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg



Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the :

From: Janet Tan
Sent: Thursday, April 12, 2018 10:13 AM
To: 'Meikwan@lkkauto.com' <Meikwan@lkkauto.com>
Cc: 'Admin A' <admin-a@lkkauto.com>; 'Thin Thin (LKKAUTO)' <thinthin@lkkauto.com>; 'Vivian Lau (LKKAUTO)' <vivianlau@lkkauto.com>
Subject: FW: Our ref: YN7246S, Your ref: SKD8573J-PRS

Dear Mei Kwan

We are still following up on non reporting.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190

www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: Thursday, April 12, 2018 9:47 AM

To: Janet Tan <janet.tan@eqinsurance.com.sg>

Cc: Admin A <admin-a@lkkauto.com>; Thin Thin (LKKAuto) <thinthin@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>

Subject: RE: Our ref: YN7246S, Your ref: SKD8573J-PRS

WITHOUT PREJUDICE

Your ref: TBA

LKK ref: CC4/EQ118006142/Kua3

Dear Janet,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SKD 8573J

Date of survey: 04.04.2018

Enclosed for your perusal is:

- TP estimate (marked)
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

We have not authorized repairs.

Kindly advise whether insured has reported. If so, kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Thin Thin and she can be contacted at DID: 68412360.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 3 April, 2018 12:57 PM
To: 'Janet Tan' <janet.tan@eqinsurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Our ref: YN7246S, Your ref: SKD8573J-PRS

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janet Tan [<mailto:janet.tan@eqinsurance.com.sg>]
Sent: Tuesday, 3 April 2018 11:53 AM
To: autoworxhouse@hotmail.com; Admin A <admin-a@lkkauto.com>
Subject: Our ref: YN7246S, Your ref: SKD8573J-PRS

Without Prejudice
Save As To Costs

Dear Samantha

Please be informed that we shall appoint LKK Auto Consultants to attend to the PRS.

However, our insured has yet to report. We shall revert on liability soonest possible.

Regards,

Janet Tan
Senior Executive | Claims



EQ Insurance Company Limited
5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6496 9032 | tel 65 6223 9433 ext 032 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the :

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 17 December 2019 12:08 PM
To: 'AUTOWORXHOUSE@HOTMAIL.COM'
Subject: RE: YOUR REF: SKD 8573J (OUR REF: CC4/EQI18006142/Kga3) *** ACCIDENT INVOLVING YN 7246S & SKD 8573J ON 02/04/2018 ***

Without Prejudice

Dear Sir/Mdm,

We refer to the email dd 09/10/2019.

Kindly note NO DV is required for this matter.

Thus, we shall proceed to submit and close off the matter.

Thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Cecilia Chong (LKK Auto)
Sent: Wednesday, 9 October 2019 2:50 PM
To: AUTOWORXHOUSE@HOTMAIL.COM
Subject: YOUR REF: SKD 8573J (OUR REF: CC4/EQI18006142/Kga3) *** ACCIDENT INVOLVING YN 7246S & SKD 8573J ON 02/04/2018 ***

WITHOUT PREJUDICE

Dear Sir/Mdm,

We are pleased to offer total amount of \$4963.75 (all-in) as per your LOD.

Kindly confirm acceptance.

Please note that NO DV is required for final settlement amount less than \$20k.

Many thanks

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 20/12/2019

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	YN 7246S	(Insd Veh)	Your Ref. No. : DMCPHQ17-006445
	SKD 8573J	(TP Veh)	Our Ref. No. : CC4/EQ18006142/Kga3q2
Date of Accident	2/4/2018		

Liability	100%	
Final Repair Cost	: \$ 4,400.00	
Loss of Use	: \$	days
Rental (If any)	: \$ 561.75	5 days
Others:	: \$ 2.00	
	: \$	
	4,963.75	
Final Settlement Sum	: \$ 4,963.75	
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	AUTOWORX HOUSE	: \$ 4,963.75
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI18006142/Kga3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 20-12-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7246S	Veh. Inspected	SKD 8573J
Policy No.	DMCPHQ17-006445	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JANET	Assign Date	03/04/2018

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN PASSAT (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WWZZZ3CZCE547839	Colour	METALLIC DARK GREY
Odometer	101570	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40 R18	GOODYEAR	7 mm
L/H Front Tyre	235/40 R18	GOODYEAR	7 mm
R/H Rear Tyre	235/40 R18	GOODYEAR	8 mm
L/H Rear Tyre	235/40 R18	GOODYEAR	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS

5. General Information

Accident Date	02/04/2018	Inspection Date	04/04/2018
Survey held at	AUTOWORX HOUSE 176 SIN MING DRIVE #02-01 SINGAPORE 575721		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 8573J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	BUCKLED	1,465.00	1,465.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	785.00	-
1	REAR BUMPER SPONGE	CRACKED	463.00	153.00
1	REAR BUMPER CENTRE CROME MOULDING	NECESSARY	167.30	167.30
1	REAR BUMPER SIDE CROME MOULDING	NECESSARY	155.00	155.00
1	REAR BUMPER LOWER PAD	SERVICEABLE	167.30	-
4	REAR BUMPER PARK SENSOR @\$365.10	SCRATCHED(1 PCS ONLY)	1,460.40	365.10
1	REAR BUMPER TOW COVER	CRACKED	67.30	67.30
2	REAR BUMPER SIDE REFLECTOR @\$185.00	SERVICEABLE	370.00	-
2	REAR BUMPER SIDE RETAINER @\$45.00	SERVICEABLE	90.00	-
2	REAR BUMPER CORNER RETAINER @\$45.00	SERVICEABLE	90.00	-
1	REAR BOOT RIB	BUCKLED	1,650.00	1,643.75
1	REAR BOOT WEATHERSTRIP	SERVICEABLE	246.10	-
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	246.00	-
1	REAR BOOT LOCK CATCH	TO REPAIR SEE LABOUR	116.70	-
2	REAR BOOT LAMP @\$761.10	N/S SCRATCHED	1,522.20	258.10
1	REAR BOOT CENTRE EMBLEM / LOCK HANDLE	SCRATCHED	327.00	327.00
2	REAR TAIL LAMP @\$651.10	O/S CUT	1,302.20	315.90
1	REAR END PANEL	TO REPAIR SEE LABOUR	594.00	-
1	REAR END PANEL GARNISH	SERVICEABLE	311.40	-
1	'PASSAT CC' EMBLEM	NECESSARY	66.70	66.70
1	'TSI' EMBLEM	NECESSARY	36.50	36.50
2	NUMBER PLATE LAMP @\$116.40	SERVICEABLE	232.80	-
	LESS 10% DISCOUNT		-1,193.19	-502.07
			10,738.71	4,518.58
SPECIAL NETT ITEMS				
1	NUMBER PLATE (SN)	BENT	35.00	40.00

Report Ref No. CC4/EQI18006142/Kga3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	NUMBER PLATE CASING (SN)}	BENT	35.00	-
			70.00	40.00
	LABOUR			
	TO REMOVE AND REPLACE THE PARTS MENTIONED ABOVE, PANEL BEAT AND REALIGN THE NECESSARY AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, REAR BOOT LOCK, REAR BOOT LOCK CATCH AND REAR END PANEL.		1,000.00	500.00
	TO CHECK WIRING SYSTEM.		50.00	20.00
	TO APPLY WATERPROOF SEALANT ON AFFECTED AREAS.	NOT NECESSARY	150.00	-
	TO APPLY RUST PROOFING ON AFFECTED AREAS.		150.00	30.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		860.00	500.00
			2,210.00	1,050.00
GRAND TOTAL			13,018.71	5,608.58
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,400.00

Report Ref No. CC4/EQ118006142/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.