

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL : 6452 8211 FAX : 6451 7420

ESTIMATE

NG WAI KHEONG
c/o 46 Lentor Plain
Singapore 786548

Not Authorised
LI Sur 84400h
Re-survey After Paint
4 days

Date: 03/04/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
RE : VOLKSWAGEN PASSAT CC /SKD8573J		
1 pc	rear bumper	Bu 1,465.00
1 pc	rear bumper reinforcement	R 785.00
1 pc	rear bumper sponge 153-a	CM 463.00
1 pc	rear bumper centre chrome moulding	M 167.30
1 pc	rear bumper side chrome moulding	M 155.00
1 pc	rear bumper lower pad	Sn 167.30
1 pc	rear bumper park sensor	@ 365.10
1 pc	rear bumper tow cover	CM 67.30
2 pcs	rear bumper side reflector	@ 185.00
2 pcs	rear bumper side retainer	@ 45.00
2 pcs	rear bumper corner retainer	@ 45.00
1 pc	rear boot rib 1643.75	Bu 1,650.00
1 pc	rear boot weatherstrip	Sn 246.10
1 pc	rear boot lock	R 246.00
1 pc	rear boot lock catch	R 116.70
2 pcs	rear boot lamp e 258.10	@ 761.10
1 pc	rear boot centre emblem/lock handle	1,522.20
2 pcs	rear tail lamp e 315.90	@ 651.10
1 pc	rear end panel	1,302.20
1 pc	rear end panel garnish	R 594.00
1 pc	'PASSAT CC' emblem	Sn 311.40
1 pc	'TSI' emblem	R 66.70
2 pcs	number plate lamp	M 36.50
		Sub-total 11,931.90
		Less 10% 1,193.19
		Sub-total 10,738.71
1 pc	number plate casing	s.nett 35.00
1 pc	number plate	s.nett 35.00
		sub-total 10,808.71

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

	Balance brought forward.	10,808.71	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	1,000.00	500/
	To check wiring system.	50.00	20/
	To apply waterproof sealant on affected areas.	nn 150.00	X
	To apply rust proofing on affected areas.	150.00	30/
	To spray painting on affected areas.	860.00	500/
	Total	13,018.71	