

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0409/2018/CCS
Date : 04-Apr-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no: SGT 323 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Chan Shaw Fong
Address : Blk 8 Selegie House
#01-12
Singapore 180008
Telephone : HP +65 91596035
Type of Claim : Third Party Claims
Policy No. : D17MTPV01006074
Vehicle No : **SBT 85 B**
Model Code : Audi A7 SB 2.8 FSI QU
Model / Year : Jun-11
Engine No : CHV 001352
Chassis No : WAUZZZ4G0BN005498
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 02-Apr-18
Place of Accident : Dakota Residences 38 Dakota Crescent 399938

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBT 85 B.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$	480.00	✓
2	To dismantle and renew front bumper and rhs headlight. Align rhs front fender. Re-organise front crash management components. Reinstall all parts removed.	\$	2,100.00	500
3	To respray front bumper and rhs front fender.	\$	1,600.00	550
4	To carry out diagnostic checks.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,372.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBT 85 B.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER ✓ <i>Cut</i>	\$	2,766.00
2	FRONT BUMPER CLOSING ELEMENT - CENTRE ?	\$	191.00
3	FRONT BUMPER CLOSING ELEMENT - LH/RH ?	2 \$	174.00
4	FRONT BUMPER FIXING PARTS X <i>NN</i>	\$	236.00
5	FRONT BUMPER GUIDE - RH ?	\$	37.00
6	FRONT BUMPER BRACE - RH X <i>NN</i>	\$	25.00
7	FRONT PARKING AID SENSOR - RH OUTER ?	\$	240.00
8	FRONT WHEEL SPOILER - RH OK <i>TN</i>	\$	202.00
9	FRONT FENDER STONE GUARD FILM - RH X <i>NN</i>	\$	99.00
10	HEADLIGHT - RH ?	\$	3,101.00
11	HEADLIGHT MOUNTING - RH UPPER / LOWER ?	2 \$	206.00
12	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS :		\$	7,577.00
TOTAL LABOUR CHARGES :		\$	4,372.00
GRAND TOTAL :		\$	11,949.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Lim Qiang*
Surveyed Date : *09/4/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *before paint photos.*
3 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant