



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

Not allowed here 2 day
EUROKARS GROUP
Take photo after repair
8/5/18

AXA INSURANCE PTE LTD		NAME : Mr Yeo Jiunn Wah	WIP : 15699
8 SHENTON WAY		ADDRESS : Apt Blk 37 Tampines Street 34	EXCESS :
#24-01 AXA TOWER		#07-43	DATE: 3-Apr-18
SINGAPORE 068811		Singapore 529240	
ATTN. :	MOTOR CLAIMS	TEL : 96172551	<i>p/p \$1652.70</i>
FAX :			

VEH NO :	SLF5784P	DATE IN :		CONTACT PERSON :	VION 6395 7877
CHASSIS NO :	JM6GJ1072G0240437	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA6 2.0L	DATE REG.:	31-Aug-16	POLICY NO. :	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	1	MGJR9-50-221ABB	<i>12</i>	\$ 1,172.80
2	1	MGJR9-50-2J1	<i>11</i>	\$ 39.00
3	1	MGJR9-50-2H1	<i>11</i>	\$ 39.00
4	1	MKD53-50-251	<i>11</i>	\$ 5.10
5	1	MGHK1-50-260	<i>12</i>	\$ 512.60
6	1	MD350-51-5L0E	<i>11</i>	\$ 50.40
7	1	MD350-51-5M0E	<i>11</i>	\$ 50.40
8	1	MG4YL-50-EL1 62	<i>11</i>	\$ 23.70
9	1	MG4YL-50-EK1 62	<i>11</i>	\$ 23.70
10	6	MB45A-56-146A	<i>11</i>	\$ 16.80
11	4	MC274-50-133	<i>11</i>	\$ 14.00
12	6	MH260-50-841	<i>11</i>	\$ 16.80
13	1	M9991-00-501	<i>11</i>	\$ 2.80
14	1	MGJA1-51-163	<i>11</i>	\$ 26.30
15	1	MGJA1-51-153	<i>11</i>	\$ 26.30
16	2	MKD53-51-146B	<i>11</i>	\$ 7.80
17	2	MGHP9-51-146	<i>11</i>	\$ 6.60
18	2	MGJ6A-51-14Y	<i>11</i>	\$ 29.80
TOTAL PARTS				\$ 2,063.90
LESS 10%				\$ 206.39
TOTAL PARTS COST				\$ 1,857.51

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>660</i> \$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	<i>630</i> \$ 1,500.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	11 X	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	11 X	NETT \$ 100.00
TOTAL LABOUR				\$ - \$ 4,660.00
TOTAL PARTS				\$ - \$ 1,857.51
TOTAL				\$ - \$ 6,517.51
LESS EXCESS				\$ - \$ -
TOTAL AFTER EXCESS				\$ -
GST 7%				\$ - \$ -
GRAND TOTAL				\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: