



TRANS EUROKARS PTE LTD
NO:5 UBI CLOSE, SINGAPORE 408605
ESTIMATE COST OF REPAIRS

EUROKARS GROUP

Not followed
2 day
Take photo after repair
8/5/18

AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN.: MOTOR CLAIMS FAX:		NAME: Mr Yeo Jiunn Wah ADDRESS: Apt Blk 37 Tampines Street 34 #07-43 Singapore 529240 TEL: 96172551	WIP: 15699 EXCESS: DATE: 3-Apr-18
---	--	---	---

VEH NO:	SLF5784P	DATE IN:		CONTACT PERSON:	VION 6395 7877
CHASSIS NO:	JM6GJ1072G0240437	MILEAGE:		TYPE OF CLAIM:	THIRD PARTY CLAIM
MODEL:	MAZDA6 2.0L	DATE REG.:	31-Aug-16	POLICY NO.:	

NATURE OF WORKS

Parts Description

NO	QTY		REVISED	PRICES
1	REAR BUMPER	1	MGJR9-50-221ABB	\$ 1,172.80
2	RETAINER(LHS), REAR BUMPER	1	MGJR9-50-2J1	\$ 39.00
3	RETAINER(RHS), REAR BUMPER	1	MGJR9-50-2H1	\$ 39.00
4	BRACKET CENTER, REAR BUMPER	1	MKD53-50-251	\$ 5.10
5	REAR REINFORCEMENT	1	MGHK1-50-260	\$ 512.60
6	REFLECTOR LHS	1	MD350-51-5L0E	\$ 50.40
7	REFLECTOR RHS	1	MD350-51-5M0E	\$ 50.40
8	COVER(LHS), TOWING	1	MG4YL-50-EL1 62	\$ 23.70
9	COVER(RHS), TOWING	1	MG4YL-50-EK1 62	\$ 23.70
10	FASTENER, REAR BUMPER	6	MB45A-56-146A	\$ 16.80
11	CLIP, REAR BUMPER	4	MC274-50-133	\$ 14.00
12	GROMMET, REAR BUMPER	6	MH260-50-841	\$ 16.80
13	GROMMET, REAR BUMPER	1	M9991-00-501	\$ 2.80
14	GASKET(LHS), TAILLAMP	1	MGJA1-51-163	\$ 26.30
15	GASKET(RHS), TAILLAMP	1	MGJA1-51-153	\$ 26.30
16	FASTENER, TAILLAMP	2	MKD53-51-146B	\$ 7.80
17	FASTENER, TAILLAMP	2	MGHP9-51-146	\$ 6.60
18	GROMMET, TAILLAMP	2	MGJ6A-51-14Y	\$ 29.80
TOTAL PARTS				\$ 2,063.90
LESS 10%				\$ 206.39
TOTAL PARTS COST				\$ 1,857.51

Labour Description

1	MZ-BR-REAR02	TO REPLACE REAR BUMPER AND REAR REINFORCEMENT. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	660	\$ 1,800.00
2	MZ-SP-SREAR2	TO RESPRAY REAR BUMPER AND REAR REINFORCEMENT.	630	\$ 1,500.00

3	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS.	nn X	\$ 660.00
4	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	120	\$ 250.00
5	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	150	\$ 350.00
6	MZ-BR-SUNDRI	SUNDRIES.	nn X	NETT \$ 100.00
TOTAL LABOUR				\$ - \$ 4,660.00
TOTAL PARTS				\$ - \$ 1,857.51
TOTAL				\$ - \$ 6,517.51
LESS EXCESS				\$ - \$ -
TOTAL AFTER EXCESS				\$ -
GST 7%				\$ - \$ -
GRAND TOTAL				\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

TRANS EUROKARS PTE LTD

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: