

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5375A**AAD1804-004***Not Authenticated
C1 Rep @ 1400*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5375A

VF1ABL15AUC279848

RENAULT

LATITUDE

30.3.2018

*Radio***PART****LIST**

1	HEADLAMP LH	\$	<i>Sn</i> 1,184.43 X
1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 ✓
1	WHEELARCH FRT LH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER LH	\$	<i>Be</i> 15.79
1	FENDER INSULATOR LH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
1	DOOR HINGE UPPER LH L70Y	\$	<i>R</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>Sn</i> 194.77
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69
1	DOOR LOCK FRT LH	\$	<i>R</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>Sn</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>Sn</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>Sn</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>Sn</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>Sn</i> 120.97
1	DOOR PANEL REAR LH L70Y	\$	<i>R</i> 2,844.66
1	DOOR GUIDE REAR LH L70Y	\$	<i>Sn</i> 176.82
1	DOOR GUIDE SCREW	\$	<i>Sn</i> 10.85
1	DOOR HINGE UPPER LH L70Y	\$	<i>R</i> 274.50
1	DOOR HINGE LOWER L70Y	\$	<i>R</i> 300.55
1	DOOR HINGE BOLT	\$	<i>Sn</i> 10.85
1	DOOR HINGE NUT L70Y	\$	<i>Sn</i> 14.60
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sn</i> 203.06
1	DOOR CHECK BOLT	\$	<i>Sn</i> 22.69
1	DOOR CHECK NUT	\$	<i>Sn</i> 3.75

Trans-cab Auto Services Pte Ltd**AAD1804-004**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5375A

1	DOOR LOCK REAR LH L70Y	\$	908.75
1	DOOR LOCK SCREW L70Y	\$	6.12
1	DOOR CATCH SCREW L70Y	\$	10.06
1	DOOR HANDLE OUTER REAR LH L70Y	\$	126.49
1	DOOR HANDLE CAP REAR LH L70Y	\$	35.52
1	DOOR HANDLE SEAL REAR LH L70Y	\$	7.89
1	DOOR HANDLE COVER REAR LH L70Y	\$	13.22
1	DOOR HANDLE MODULE REAR LH L70Y	\$	133.60
1	DOOR REGULATOR REAR LH L70Y	\$	1,135.10
1	DOOR REGULATOR MOTOR REAR LH L70Y	\$	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	6.31
1	DOOR FINISHER REAR LH L70Y	\$	423.10
1	DOOR MOULDING REAR LH L70Y	\$	176.82
1	DOOR MOULDING CLIP L70Y	\$	5.92
1	DOOR MOULDING SCREW L70Y	\$	6.91
1	DOOR CASING REAR LH L70Y	\$	1,509.06
1	DOOR WATER SHIELD REAR LH L70Y	\$	30.39
1	DOOR CASING CLIP	\$	12.63
1	DOOR CASING LIGHT L70Y	\$	48.74
1	DOOR FINISHER INNER REAR LH L70Y	\$	323.44
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	46.97
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR FINISHER BRACKET INNER REAR LH L70Y	\$	20.33
1	DOOR GRAB HANDLE REAR LH L70Y	\$	210.96
1	DOOR BLIND REAR LH L70Y	\$	741.80
1	DOOR WHEATHESTRIIP REAR LH L70Y	\$	410.66
1	DOOR SEAL REAR LH L70Y	\$	162.02
1	DOOR GLASS RUNNER SEAL REAR LH L70Y	\$	229.31
1	DOOR WAIST SEAL OUTER REAR LH L70Y	\$	334.69
1	DOOR WAIST SEAL INNER REAR LH L70Y	\$	115.64
1	FENDER PANEL REAR LH	\$	3,299.13
1	FENDER PANEL INNER TRIM REAR	\$	671.45
1	WHEELARCH REAR LH	\$	543.47
1	BUMPER COVER REAR	\$	1,108.46
1	BUMPER LOWER REAR	\$	768.84
1	BUMPER BRACKET CTR REAR	\$	113.47

X
JVC

Trans-cab Auto Services Pte Ltd

AAD1804-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5375A

1	BUMEP R RETAINER LH REAR	\$	SH 44.99	} X
1	BUMPER BEAM REAR	\$	R 777.52	
1	BUMPER BEAM BRACKET LH REAR	\$	R 225.95	
1	DOOR MIRROR ASSY LH	\$	SH 1,483.40	
1	TAILLAMP LH	\$	SH 552.55	

	\$	30,847.89
10%	\$	3,084.79
	\$	27,763.10

Special Nett

1SET	BUMPER CLIP FRT	\$	na 66.00	} X
1	BUMPER BRACKET CLIP FRT LH	\$	na 12.00	
1	BUMPER SUPPORT CLIP FRT LH	\$	na 10.50	
1SET	BUMPER GRILLE LOWER CLIP	\$	na 69.00	
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	na 70.00	
2	FRAME FULL SUPPORT PANEL NUT	\$	SH 20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	SH 30.00	
1SET	WHEELARCH CLIP FRT LH	\$	na 30.50	
1	FRONT DOOR STICKER 'Trans-cab'	\$	na 80.00	60SN
1	FRONT DOOR STICKER 'Chassis'	\$	na 50.00	15SN
1	REAR DOOR STICKER '6555 3333'	\$	na 80.00	X

TOTAL	\$	518.00
--------------	----	---------------

TOTAL PARTS	\$	28,281.10
--------------------	----	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	2,450.00	400L
----	----------	------

Putty and spray painting of the affected portion.

\$	2,200.00	440L
----	----------	------

To rust-proofing of the affected areas.

\$	170.00	30L
----	--------	-----

Trans-cab Auto Services Pte Ltd

AAD1804-004

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5375A

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i>	380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$		220.00	<i>601</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	<i>X</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	380.00	<i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i>	380.00	<i>X</i>
To replace, refix and top up coolant for radiator	\$	<i>nn</i>	170.00	<i>X</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i>	170.00	<i>X</i>

TOTAL	\$	6,860.00
--------------	-----------	-----------------

Over All Total	\$	35,141.10
-----------------------	-----------	------------------

PART BY PART (REPAIR DAY)*7 DAYS**3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after-spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: