

JA AUTOCARE PTE LTD

8 Kaki Bukit Ave 4
#02-37 Premier @ Kaki Bukit
Singapore 415875
Tel : 94513429

LonPac Insurance BHD
100 Beach road
#19-00
Singapore 189702
Attn: Motor Claims Department

Estimate

Date : 04.04.2018
Vehicle No. : SLC 2399D
Make/Model : Mit Elantra
Chassis/Eng# :
Accident Date : 02.04.2018

- 01) Rear bumper
- 02) Rear bumper bracket @\$58.00 x 2
- 03) Rear bumper retainer @\$65.00 x 2
- 04) Rear bumper clips
- 05) Rear bumper lower garnish
- 06) rear bumper sponge
- 07) Rear bumper reinforcement
- 08) Boot lid
- 10) ELANTRA EMBLEM
- 11) ELITE Emblem
- 12) Tail lamp assy lh

Part cost	\$	1,550.00	✓
	\$	116.00	?
	\$	130.00	✓
	\$	60.00	✓
	\$	520.80	✓
	\$	380.00	?
	\$	680.50	?
	\$	1,850.00	✓
	\$	100.00	✓
	\$	80.00	✓
	\$	680.50	?
	\$	6,147.80	
Less 20%	\$	(1,229.56)	
	\$	4,918.24	

S/Nett

- 13) Reverse Sensor

\$	Shot	250.00	2000
\$		250.00	

Labour charges

- 14) To checking wiring
- 15) To dismantle & refix reverse sensor
- 16) to apply anti rust chemical
- 17) To knock out dent on affected areas and renew parts
- 18) To putty & respray painting

\$		100.00	200
\$		60.00	500
\$	200	100.00	x
\$		1,000.00	4000
\$		1,000.00	4000
\$		2,260.00	

for JA AUTOCARE PTE LTD

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 7,428.24