

COMFORTDELGRO ENGINEERING PTE LTD

Date: 03.04.2018

REPAIR ESTIMATE

*China Taiping*

Time: 14:30:57

Page: 1

*TS*

*LKK kalvin CP (P)*

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305138091  
REGN NO : SHD8588C  
MILEAGE : 000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 15.09.2016  
DATE/TIME IN : 03.04.2018 10:20  
ACCIDENT DATE : 02.04.2018

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-0579-G	REAR BUMPER	1	603.60	20.00	482.88	<i>X Repair</i>
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	225.00	20.00	180.00	<i>X</i>
0003	04-01-0101-0111-A	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	<i>X</i>

SUB-TOTAL : 680.48

JOB NATURE

0000	20-05	REAR BUMPER MAT				50.00	<i>/</i>
0001	L	PANEL BEATING				<del>280.00</del>	<i>100</i>
0002	23-502	SPRAYPAINT ON AFFECTED AREA				<del>250.00</del>	<i>200</i>
0003	L	R/I REVERSE SENSOR				<del>120.00</del>	<i>X</i>

SUB-TOTAL : 700.00

TOTAL : 1,380.48

MVA NAME & SIGNATURE  
DATE :

SURVEYOR NAME & SIGNATURE

AUTHORISED : YES / NO

*Lmfs*

*Kalvin (LKK)*  
*3/4/18 1500h*  
*2 Regs.*  
*PIP*  
*After Repair p the*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: