

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

29-Mar-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8769 A

1 pc	Front bumper <i>X repair</i>	\$	531.00
1 pc	Front bumper n/s fog lamp cover <i>X</i>	\$	66.00
1 pc	Front bumper n/s protector <i>X repair</i>	\$	51.00
		\$	648.00
		Less 10%	\$ 64.80
		\$	583.20

S/NETT

1 set	Front bumper clips <i>X</i>	\$	48.00
	<i>Front number plate</i> <i>\$35</i>		
	Sundry	\$	50.00 <i>X</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of same	\$	500.00 <i>200</i>
	To putty and spray painting on front bumper, bonnet grille	\$	400.00 <i>180</i>
		\$	1,581.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Kelvin (UK)

3/4/18 1605hrs
2 Days

4/5
After Repair photo