

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40/63 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: EST096/18/TP
Your Ref: TP claim against SHD6741P
3-Apr-18

India International Insurance Pte Ltd
64 Cecil Street #04-05
IOB Building
Singapore 049711

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Toyota Camry no: SKV6654C

Date of accident: 26-03-2018

Parts supply:

1 pc Boot	UX		S\$	806.90	X
1 pc Boot emblem - CAMRY	neu ✓			55.60	✓
1 pc Boot emblem - 2.0	neu ✓			31.05	✓
1 pc Boot emblem - Logo	neu ✓			41.90	✓
1 pc Boot centre garnish	UX			335.90	X
2 pcs Boot lamps @\$229.60	UX			459.20	X
1 pc Boot inner lock	UX			361.90	X
2 pcs Boot hinges @\$89.60	UX			179.20	X
1 pc Boot insulator	UX			426.50	X
13 pcs Boot insulator clips @\$3.50	UX			45.50	X
2 pcs Taillamps @\$361.90	01524	1PC		723.80	1PC
1 pc Rear bumper	D.S			789.60	✓
1 pc Rear bumper reinforcement	RD			361.50	✓
2 pcs Rear bumper retainers @\$55.60	01524	1PC		111.20	1PC
2 pcs Rear bumper brackets @\$65.90	01524	1PC		131.80	1PC
8 pcs Rear bumper clips @\$3.50	neu ✓			28.00	✓
1 pc Rear bumper tow cover	UX			28.90	X
1 pc Rear bumper foam	RS X			65.90	X
1 set Reverse sensor (S/Nett)	shhd			250.00	✓
1 pc Exhaust muffler bush	UX			38.90	X
1 pc Exhaust silencer	RX			983.30	X
1 pc Rear end panel	Bdy			691.50	✓
1 pc Rear end panel garnish	FWI ✓			365.80	✓
				7,313.85	

Less 25%: (1,828.46)

S/Nett Items

1 pc Rear no. plate with cover (S/Nett)	UX			45.00	X
1 set Rear reverse sensor (S/Nett)	Repair ✓			250.00	X

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.		750.00	600
To respray affected part.		800.00	700
To remove and refit exhaust system.		150.00	50
To apply underseal		80.00	50
To check wirings.		30.00	✓

S\$ 7,590.39

ESTIMATE

LKK Auto starts hence notify the Repairer following:
 • To resurvey before spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

W. of Albert
2800k
5/4/18
tele phone after repair

3098.35
2323.76

3753.76
3003.01