

INS CASE OWNER:

Clara

CC 4, PWD 1800

6172, P12031

LKK:
IDAC:

Surveyor:

MRO

DOI:

ASSIGNMENT

419/18

Date / Time:

414/18

Registered in Meritona:

414/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SGR 6356 G

Name of Insured:

MAY (HON) SIONG

Insured Tel No.:

HP: 91390922

Excess Sec II :SS

D.O.A.: 30/3/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

120180003886

Policy No.:

PNPV 2017-0002375x

Make / Model:

M-4110

Place of Accident:

MAYAPO HOTEL SG

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

SKP 6022



INSRS:

WSP: Borneo

Tel:

Liability: Pandan

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

15/5
AfterSKP 6022-41/18/18003886 / 91390922-1:000-2018/18
SGR 6356 G-X

11-9-18

Remove case library case.

23-7-18

File PPD TO TYPIS TO PREPARE REPORT.

RECEIVED 11 SEP 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 11-6-18

Confirm with: 308104

Confirm by: MIB

Repair Cost: 14 S\$2,213.40

(3 days)

Reduction:

74 %

Email

Call

FINAL SETTLEMENT

Date/Time: 03-09-18

Confirm with: Srt

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

37

If NO or B 28, Ass. Lia:

Repair Cost:

WILGA S\$ 3,438.55

DID REPAIR ENOUGH TP.

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 200.00

(\$ 100 x 3 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

(Tick only one)

GIA/LTA Search

S\$ 5.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3,740.55

Global Sum S\$:

FINAL PAYMENT

Date/Time: 03-09-18

Confirm with: Srt

Email

Call

Payee 1:

S\$ 3,740.55

Name 1:

BORNEO MOTOR (SINGAPORE) PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

COMPLAINT
419/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

500

Surveysor *John*

REF:

8 6122/1243

07280

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SKP 6022

Yr Regn: 2011 / Aug

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA LEXUS NX 200T c.c. 1998

Colour: Black A/C Insured / Std / NI / NA

Sp. Reading: 10132 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTJBARBZX02105068

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/60x18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A: 30/03/18 D.O.I: 04/05/12

Survey held at: PARKER MARR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P: 3, 213-40 (P/P: 2, 536 4/2/1)

Date/Time: File Pass to?

☐ : Preli. Report

1)

Date/Time: File Return to?

☐ : Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RS \$

) Photos

) Others

• TOTAL

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD			Ref : CC4/FWD18006172/R1ea3	
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4 SINGAPORE 038986			Date : 04-04-2018	
			Code : FWD	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGR 6356G	Veh. Inspected	SKP 602Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	1201800003886	Excess (\$)	0.00	
Assign From		Assign Date	04/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	30/03/2018	Inspection Date	04/05/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Attn: Sn & Sn. Liability Check

Account Detail	Account No S1000020 / TPCLAIM	Customer Detail
THIRD PARTY CLAIM T/P FWD LKK Catherine Survey on 24/5/18 9-930 am 67418434 Survey on 25/4/18 9 am 430 am	Document No 0	Mr Goh Chong Han 945 Bukit Timah Road #08-53 Singapore 589660 Mobile: 98200785
	Document Date 03/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AWTLTQ	L3	AGZ15R	28/08/2017	SKP0602Z	0	15210 4TP/SKP0602Z/30031

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJBARB2X02105068	8ARW414994	60	Wally Tan G H	03/04/2018	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES <i>hcn</i> POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 88.00
2	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)				204.00
3	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)				204.00
4	B	BP-LAB REMOVE/REPLACE REAR BUMPER COVER AND REALIGN.				816 1020.00
5	B	BP-RES SPRAY PAINT ON REAR BUMPER COVER.				700 875.00
6	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)				612.00
7	1	L52155-78010 SUPPORT, RR BUMPER	1.00	89.40		X 89.40
8	2	L52156-78010 SUPPORT, RR BUMPER	1.00	89.40		X 89.40
9	3	L52015-78010 ARM SUB-ASSY, RR	1.00	143.20		X 143.20
10	4	L52016-78010 ARM SUB-ASSY, RR	1.00	143.20		X 143.20
11	5	L52171-78010 REINFORCEMENT, RR	1.00	796.90		X 796.90
12	6	L52159-78904 COVER, RR BUMPER	1.00	621.30		Repair 621.30

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 03/04/2018
TIME 12:41

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SKP0602Z

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Goh Chong Han 945 Bukit Timah Road #08-53 Singapore 589660 Mobile: 98200785
	Document No 0	
	Document Date 03/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AWTLTQ	L3	AGZ15R	28/08/2017	SKP0602Z	0	15210 4TP/SKP0602Z/300311

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJBARBZX02105068	8ARW414994	60	Wally Tan G H	03/04/2018	0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	7	L52169-78010 COVER, RR BUMPER,	1.00	414.20		DE 414.20
14	8	L75392-35220 RETAINER OUTSIDE	8.00	3.30		ne 26.40
15	9	L50768-78010 COVER SUB-ASSY, RR	1.00	243.60		ne 243.60
16	0	S52161-OK040 BUMPER CLIPS	8.00	3.90		ne 31.20
17	1	L89348-78020 RETAINER, ULTRASONIC	2.00	16.00		ne 32.00
18	2	L89348-78030 RETAINER, ULTRASONIC	2.00	61.90		ne 123.80

Resue
4p 90010068
3 days
04/05/18 0915
Pay by mt

KK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 2,754.60	5,749.60
		Labour 2,995.00	GST 7.00% 402.47
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	
			Amount Due 6,152.07

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 03/04/2018
TIME 12:41PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SKP0602Z

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Arti: Rasul
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No S1000031 / FWD		Customer Detail	
FWD Singapore Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986		Document No 0		Mr Goh Chong Han 945 Bukit Timah Road #08-53 Singapore 589660 Mobile: 98200785	
		Document Date 09/06/2018			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AWTLTQ	L3	AGZ15R	28/08/2017	SKP06022	10681	15210 -4DS/SKP06022/30031:

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTJBARBZX02105068	8ARW414994	60	Wally Tan G H	03/04/2018	0.00	26/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS.:FWD ACC DATE:30.03.18 T/P VEHICLE NO.:SGR6356G DATE-IN:22.05.18 DATE SURVEY:04.05.18 NO OF REPAIR DAYS:3 DAYS YOUR REF:1201800003886 BY:RASUL (LKK) *DIRECT SETTLEMENT*				50.00
2	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)	*			204.00
3	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)	*			204.00
4	B	BP-LAB REMOVE/REPLACE REAR BUMPER COVER AND REALIGN.	*			816.00
5	B	BP-RES SPRAY PAINT ON REAR BUMPER COVER.	*			700.00
6	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)	18			612.00
7	1	L52169-78010 COVER, RR BUMPER,	1.00	414.20		414.20
8	2	L75392-35220 RETAINER OUTSIDE	8.00	3.30		26.40
9	3	S52161-0K040 PIECE, RR BUMPER	8.00	3.90		31.20
10	4	L89348-78020 RETAINER, ULTRASONIC	2.00	16.00		32.00
11	5	L89348-78030 RETAINER, ULTRASONIC	2.00	61.90		123.80

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	3,213.60
	Please acknowledge receipt of vehicle  3 days	Parts	627.60	GST 7.00% 224.95 Less 0.00 Amount Due 3,438.55
		Labour	2,586.00	
		Materials	0.00	
		Lubrication/Fluid	0.00	
		Others	0.00	

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES:

VEHICLE NO SKP06022

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

LKK Auto Consultants Pte Ltd (Co.Reg.No.199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 10 May 2018

Preliminary Advice

Insured Vehicle No	: SGR6356G	Accident Date	: 30/03/2018
TP Vehicle No	: SKP602Z	Assignment Date	: 04/04/2018
Make	: LEXUS NX200T	Est. Duration of Repair	: 3 days
Date of Inspection	: 04/05/2018		
DAYS	: Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,749.60
Revised Amount	:S\$	3,213.60
Check Items (Estimated)	:S\$	243.60
Total	:S\$	3,457.20

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.



Borneo Motors

Co-Reg No: 1967000862

Borneo Motors (Singapore) Pte Ltd
Inchcape Bodycare Centre
Level 4, Inchcape Centre
2 Pandan Crescent
Singapore 128462
Tel: +65 6631 1855/1500
Fax: +65 6872 7260
www.borneomotors.com.sg

Our Ref: BMS2018/07/LK8149/DS(WT)

Your Ref: 1201800003886

20 Jul 2018

BY HAND (INS COPY)

M/S. FWD SINGAPORE PTE LTD C/O LKK AUTO CONSULTANTS PTE LTD

Attn : Asher Sng

Dept : Motor Claims

RE : ACCIDENT INVOLVING SKP602Z AND SGR6356G ON 30 Mar 2018

Dear Officer,

We refer to the above captioned.

The accident was caused by the negligence of your insured and as a result, our client has incurred the following losses:

A. Repair Cost - \$3,438.55	B. LTA Search - \$2.00
C. Excess -	D. Loss of Use - \$300.00(\$100x3days)
E. Loss of Rental -	F. Others -
G. Medical Claims - -Undertake By Claimant ☐	Total Claim - \$3,740.55

We would appreciate if you could revert to us with an offer to settlement within **8 working weeks** as required under NIMA Protocol.

Enclosed are the following documents for your kind perusal:

- | | |
|--|--|
| (✓) Original Tax Invoice | (X) Vehicle Registration Card |
| (X) Car Rental Invoice/Agreement/Medical Receipt | (✓) Driver's driving license / Identity card |
| (✓) GIAS/Police Report/s | (X) Original Photograph X _____ |
| (✓) Certificate of Insurance | (X) Original/Photocopy Survey |
| (✓) Letter of Authority | (✓) LTA Search Fees |

*Cheque is to be made payable to **BORNEO MOTORS (SINGAPORE) PTE LTD** & mail it to, Inchcape Bodycare Centre Level 4, Inchcape Centre, 2 Pandan Crescent, Singapore 128462, Attn: TPR Department*

Yours faithfully,

TPR Team

Claims Service Department

F:68727260 E: claimstatusenquiry@borneomotors.com.sg

(As this is a computer generated letter, no signature is required.)

LETTER OF AUTHORITY

ACCIDENT INVOLVING SKP 602 Z and SGR 6356 G on 30.3.18
Own vehicle's number Other vehicle's number Date of accident

along Claymore Connect carpark,
Accident location

BY THE LETTER OF AUTHORITY, I/we Goh Chong Han
Name of Policy Holder / IC Passport/Company Registration number

of 945 Bl. Timah Rd # 08-53 S(589660)
Address of Policy Holder

owner of Vehicle Registration No. SKP 602 Z hereby appoint **BORNEO MOTORS (SINGAPORE) PTE LTD** (hereinafter refers to **BMS**), a company incorporated in Singapore and having its registered office at 33 Lang Kee Road, Singapore 438102, to do all or any of the following:

1. To submit, resolve and make any claims which I/we may have against the other party/parties to the Accident and under the insurance policy/policies taken up by such party/parties or alternatively under Insurance Policy number VPA/P1981701 taken up by I/me/us and pay the compulsory excess in respect of the cost of repairs suffered by I/me/us arising from the Accident (loss and damage);
2. To collect payment(s) due in respect of any such claim(s) for the loss and damage, such payment to be made by way of Cheque in favour of BORNEO MOTORS (SINGAPORE) PTE LTD and give a valid receipt and discharge therefor;
3. For any of the purposes aforesaid, to execute sign and deliver all documents whatsoever in relation thereto;
4. Generally do all such acts as I shall deem necessary for the purpose of settling such claim.


I/We hereby declare that all acts, instruments and documents done by virtue of this letter of authority on my/our behalf shall be as good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by I/me/us in my/our own proper person(s) and I/we hereby ratify and confirm all acts, instruments and documents done or executed by virtue of the authority and powers hereby conferred.

I/We hereby further declare that the letter of authority hereby conferred shall remain irrevocable.

I/We further confirm that the acceptance by BMS of the settlement amount in respect of such constitute the full discharge of my/our claim(s) in respect of such loss and damage.


IN WITNESS WHEREOF I/we have hereunto set my/our hand and sign this 24 of the month May Year 20 18

Signed & Delivered By:



(To be sign by the policy holder only)
** Please stamp the company chop for vehicle registered under a company's name

Witness By:



RELEASE

Claim Reference:	1201800003886
Surveyor's Reference:	CC4/FWD18006172/R1ea3
TP Reference:	SKP 602Z

We, **BORNEO MOTORS (S) PTE LTD** ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle **SKP 602Z** ("Vehicle") to accept the sum of **\$3,740.55**, being the amount claimed for **\$3,438.55** (repair costs), **\$300.00** (loss of rental/ use), **\$ -** (loss of income), **\$2.00** (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on **30/03/2018** (date of accident) at / along **CLAYMORE CONNECT CP** (location) involving vehicle no/s. **SKP 602Z** and **SGR 6356G**.

This is pursuant to the inspection conducted on **04/05/2018** (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of **SGR 6356G** be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 14 day of SEPT 2018

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



MRB

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.

**TAX INVOICE**

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

TAX INVOICE**Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
FWD Singapore Pte Ltd 6 Temasek Boulevard #18-01 Suntec Tower 4, Singapore 038986	S1000031 / FWD	Mr Goh Chong Han 945 Bukit Timah Road #08-53 Singapore 589660 Mobile: 98200785
	Document No 36005385	
	Document Date 12/06/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	AWTLTQ	L3	AGZ15R	28/08/2017	SKP0602Z	10681	15210 4DS/SKP0602Z/300311
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTJBARBZX02105068	8ARW414994	60	Wally Tan G H	22/05/2018	8.21	09/06/2018	11.31

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS.:FWD ACC DATE:30.03.18 T/P VEHICLE NO.:SGR6356G DATE-IN:22.05.18 DATE SURVEY:04.05.18 NO OF REPAIR DAYS:3 DAYS YOUR REF:1201800003886 BY:RASUL (LKK) *DIRECT SETTLEMENT*				50.00
2	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)	*			204.00
3	B	BP-LAB REMOVE/REFIX REAR BUMPER LOWER EXTENSION. (NETT)	*			204.00
4	B	BP-LAB REMOVE/REPLACE REAR BUMPER COVER AND REALIGN.	*			816.00
5	B	BP-RES SPRAY PAINT ON REAR BUMPER COVER.	*			700.00
6	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)	18			612.00
7	1	L52169-78010 COVER, RR BUMPER,	1.00	414.20		414.20
8	2	L75392-35220 RETAINER OUTSIDE	8.00	3.30		26.40
9	3	S52161-OK040 PIECE, RR BUMPER	8.00	3.90		31.20
10	4	L89348-78020 RETAINER, ULTRASONIC	2.00	16.00		32.00
11	5	L89348-78030 RETAINER, ULTRASONIC	2.00	61.90		123.80

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 627.60	3,213.60
		Labour 2,586.00	GST 7.00% 224.95
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 3,438.55

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 12/06/2018
TIME 13:53

VEHICLE NO

SKP0602Z

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

**Borneo Motors**

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-048393
Date of Request: 02/04/2018

Your Ref No: Online Purchase

Borneo Motors (S) Pte Ltd
33 Leng Kee Road
Singapore 159096

Dear Sir/Madam,

Enquiry Date 02/04/2018
Enquiry By Siti Nabilah Binte Abdul Rahim
TP Vehicle No. SGR6356G
Accident Date 30/03/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2018 Edit Reg		04 Apr 2018 00:00 Edit Adj Rpt	S\$3,213.60 Edit Estimates	S\$3,213.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	Mah Choon Siong , ID: S8713705H								
Main Claimant:	GOH CHONG HAN , ID: S8100728D								
Vehicle Reg. No.:	SKP602Z	Date of Loss:	30/03/2018 22:00 - :59 [7 Months and 2 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1201800003886	Policy/Cover Note No.:	PNPV2017-00002370 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGR6356G	Policy No. (Claimant):	VPA/P1981701						
		Excess:							
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857								
Handling Insurer:	FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 13/04/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• FWD_SG (24/08/2018): Alert - Adj Mandate Approved (S\$3740.55) - SKP602Z - Claim Handler: Clara Li Zi ...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKP602Z (1201800003886)**
[SGR6356G]

TP
GOH CHONG HAN
Mar 30 2018 10:00PM
[Mah Choon Siong]
Borneo Motors (S) Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	10/05/18 21:24	Adjuster Immediate Advice	Load HTML	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 11:06	Odometer Reading	Load JPG	☒
2	11/06/18 11:06	Chassis Number	Load JPG	☒
3	11/06/18 11:06	General View	Load JPG	☒
4	11/06/18 11:06	General View	Load JPG	☒
5	11/06/18 11:06	General View	Load JPG	☒
6	11/06/18 11:06	General View	Load JPG	☒
7	11/06/18 11:06	General View	Load JPG	☒
8	11/06/18 11:06	General View	Load JPG	☒
9	11/06/18 11:06	General View	Load JPG	☒
10	11/06/18 11:06	General View	Load JPG	☒
11	11/06/18 11:06	General View	Load JPG	☒
12	11/06/18 11:06	General View	Load JPG	☒
13	11/06/18 11:06	General View	Load JPG	☒
14	11/06/18 11:06	General View	Load JPG	☒
15	11/06/18 11:06	General View	Load JPG	☒
16	11/06/18 11:06	General View	Load JPG	☒
17	11/06/18 11:06	General View	Load JPG	☒
18	11/06/18 11:06	General View	Load JPG	☒
19	11/06/18 11:06	General View	Load JPG	☒
20	11/06/18 11:06	General View	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/18 15:12	EMAIL - FWD TO OI DD 04.04.2018.	Load PDF	
2	04/04/18 15:12	ACKNOWLEDGEMENT EMAIL TO FWD DD 04.04.2018	Load PDF	
3	04/04/18 15:12	TP ESTIMATE	Load PDF	
4	04/04/18 15:12	TP GIA REPORT	Load PDF	
5	14/05/18 23:42	TP ESTIMATE - MARKED	Load PDF	
6	27/07/18 14:39	WORKSHOP INVOICE	Load PDF	
7	27/07/18 14:39	GIA SEARCH	Load PDF	
8	27/07/18 14:39	LOD	Load PDF	
9	19/09/18 08:49	AUTHORISATION TO ACT FORM	Load PDF	

Letters/Correspondences			1 per page	☒
No	Finalized On		Thumbnail	Print
10	19/09/18 08:49	LKK Auto Consultants Pte Ltd (HQ) Release Voucher	 Load PDF	
No	Finalized On		Thumbnail	Print
1	11/04/18 10:39	FWD Singapore Pte. Ltd. (HQ) OI GIA Report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SGR6356G (Insd veh)	Model:	LEXUS NX200T 2.0 (A)
	SKP602Z (TP veh)		
Date of Accident:	30/03/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	6,152.07
Final Repair Cost	:	\$	3,438.55
Loss of Use	:	\$	300.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,740.55

3.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop:** Agreed Liability _____ (%)

B) For **GIA Registered Workshop:** BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Borneo Motors (Singapore) Pte Ltd	:	\$ 3,740.55
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

19 Sep
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18006172/R1EA3Q2

Date: 19/09/2018

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00002370

Claimant Vehicle No: SKP602Z Insured Vehicle No: SGR6356G

Date of Loss: 30/03/2018 Nature of Claim: TP Claim No: 1201800003886

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKP602Z**
 Make & Model: LEXUS NX200T, 2.0 (A) Engine No: 8ARW414994
 Reg. Date: 28/08/2017 (Man. Year: 2016) Chassis No: JTJBARBZX02105068
 Colour: Black Odometer: 10132 km
 Engine Capacity: 1998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R18 Rear Tyre Size: 225/60 R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,834.60	677.60	2,157.00	76.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	2,536.00	379.00	13.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,749.60	3,213.60	2,536.00	44.11
+ GST 7.00/7.00% (S\$)	402.47	224.95	177.52	44.11
Nett Amount (S\$)	6,152.07	3,438.55	2,713.52	44.11
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,740.55		

INSPECTION

Date of Assignment: 04/04/2018

Date Inspected: 04/05/2018 Inspected At:

Borneo Motors (S) Pte Ltd (Pandan)
2 Pandan Crescent
Singapore 128462

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2018)
Parts: M1-SUV	LEXUS NX200T 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKP602Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*50.00 FS
2	1		*SUPPORT ,RR BUMPER	Serviceable	89.40 FS	*- FS
3	1		*SUPPORT ,RR BUMPER	Serviceable	89.40 FS	*- FS
4	1		*ARM SUB-ASSY ,RR	Serviceable	143.20 FS	*- FS
5	1		*ARM SUB-ASSY ,RR	Serviceable	143.20 FS	*- FS
6	1		*REINFORCEMENT ,RR	Serviceable	796.90 FS	*- FS
7	1		*COVER ,RR BUMPER	Repair	621.30 FS	*- FS
8	1		*COVER ,RR BUMPER	Deformed	414.20 FS	*414.20 FS
9	8		*RETAINER OUTSIDE	Necessary	26.40 FS	*26.40 FS
10	1		*COVER SUB-ASSY ,RR	Not Necessary	243.60 FS	*- FS
11	8		*BUMPER CLIPS	Necessary	31.20 FS	*31.20 FS
12	2		*RETAINER ,ULTRASONIC	Necessary	32.00 FS	*32.00 FS
13	2		*RETAINER ,ULTRASONIC	Necessary	123.80 FS	*123.80 FS

F=Franchise part. S=SpclNett.

Total Parts (S\$)	2,834.60	677.60
--------------------------	-----------------	---------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE /REFIX REVERSE SENSORS	New	204.00	204.00
2	REMOVE /REFIX REAR BUMPER LOWER EXTENSION	New	204.00	204.00
3	REMOVE /REPLACE REAR BUMPER COVER AND REALIGN	New	1,020.00	816.00
4	SPRAY PAINT ON REAR BUMPER COVER	New	875.00	700.00
5	TO RESET ECU AND REPROGRAMME	New	612.00	612.00
Gross Labour Cost (S\$)			2,915.00	2,536.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >