

ASS. REC. BY:

REF: CS/FCI18006178/Aqbn2

Special Instruction:

Surveyor:

Adrian

ASSIGNMENT (Office)

From (Person): CWS May Chua

of

FCL

Date/Time: 04042018 204pm

Estimated Cost:

Bill to:

OD / TS / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJW 3832G

Insured:

SHA 5740P

at Workshop m/s

Tiek Hai Motor

Tel:

6842 9089

of

Blok 1 Kaki Bukit Ave 6 #01-54

Policy No:

D-18088936MFSH

Claim No:

D18002616MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 31-03-2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wpi

05042018 @ 3pm - 4pm

H.O.D. Endorsement:

Date/Time: 04042018 214pm

Person Contacted:

Connie

Vehicle IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	SJW 3832G - x
	SHA 5740P - CS/FCI17003668/Rlvbm2 DCA: 17032017
06/4/18 @ 2.01pm	Informed May Chua, we are pending estimate from repairer.
13/4/18 @ 4.34pm	revised to May Chua by email.
	US \$ 3000, 4 days (Fed \$ 6267.89, 68%)

REF:

FCI

ASSIGNMENT

From:

Date:

05/04/18

Estimated Cost

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJW 3832G

at Workshop m/s

Tick Hai Motor

of

Blk 1 Kaki Blk Ave 6 # 01-54

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

3pm - 4pm

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

w/p

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SJW 3832G

Yr Regn:

2009, Dec.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 318

C.C. 1995

Colour:

Gold.

A/C: Insured / Std / NI / NA

Sp. Reading

163511

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NBA PF72020A 753408.

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD-A/Rim or

Tyre Size:

F:

205/55R16

R:

205/55R16

BS / DUN / EXNOVA / GY / ☒ FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

05/04/18.

Survey held at

Tick Hai.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 16 JUL 2018

* Note:

MV: 35K (cash)
PV: 22.5K
Nett: 12.5K.

Date/Time. File Pass to?

☐

Preli. Report

1) 16/7 1st Cap.

☐

Final Report

Date/Time. File Return to?

Days Of Repair:

4

Resurvey No. of Trip:

2

Survey Fee:

Transportation

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

) \$ + RS \$

) Photos

) Others

TOTAL

170
50
50+50
40
360

Report Format:

TP

Lump Sum / I.B.T. (\$)

3000



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18006178/Aqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 04-04-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 5740P	Veh. Inspected	SJW 3832G
Policy No.		Coverage (\$)	0.00
Claim No.	D18002616MFSH	Excess (\$)	0.00
Assign From	CWS (MAY CHUA)	Assign Date	04/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	31/03/2018	Inspection Date	05/04/2018
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18002616MFSH

Date: 13 July 2018

Our Ref: CS/FCI18006178/Aqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJW 3832G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/04/2018 at the premises of M/s TICK HAI MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 9,267.89 .
Revised Estimate Amount	: S\$ 3,793.22 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	02-04-2018	Our Ref No. D18002616MFSH
Accident Date	31-03-2018	Claim Type. Third Party
Insured Vehicle	SHA5740P	Third Party Vehicle. SJW3832G
Survey Location	1 Kaki Bukit Avenue 6 #01-54Autobay @ Kaki Bukit	
Contact Person.	MS CONNIE SEE	
Contact No.	68429089/ 81397246	Fax No. 0
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TICK HAI MOTOR & WELDING SERVICES	Attention. NIL
Cc : TP Solicitor	CHIA S ARUL LLC	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/236571)



PRI Documents



Close



PRI Header Details

Claim No	D18002616MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & CH
Workshop Name	TICK HAI MOTOR & WELDING SERVICES (Contact Person : MS CONNIE SEE)	Survey Location & Contact Details	1 Kaki Bukit Avenue 6 #01-54Autobay @ Kaki Mobile: 81397246 , Phone: 68429089 , Fax: EmailId: ALYWIN@CHIAARUL.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA5740P	TP Vehicle No	SJW38
PRI Recieved Date	03-04-2018 06:14:11 PM	Surveyor Appointed Date	04-04-2018 02:04:34 PM	Surveyor Accept Date	04-04-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	04-04-2018	Upload Survey Report *:	
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	----------------------

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 13 July 2018 4:34 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002616MFSH/1
Attachments: CSFC18006178Aqb.pdf

Dear May,

Enclosed herewith preliminary advice of SJW 3832G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 April 2018 2:01 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002616MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SJW 3832G on 05/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 4 April 2018 2:43 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002616MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 6 April 2018 2:01 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18002616MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SJW 3832G on 05/04/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 4 April 2018 2:43 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18002616MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 4 April, 2018 2:04 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18002616MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team



\$3380 Drive Away! Low Mileage PML Unit. Low Depreciation. Regularly Serviced. Beautiful New Body Paintwork. Easy To Maintain Silver Colour. Nice, Neat And Clean Interior. 1x Free Servicing At Our Auth...

Dynamic Motoring

Posted: 28-Mar-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i

\$38,000

\$12,710 /yr

11-Nov-2009

1,995 cc

99,000 km

Luxury

Available

Sold/In Used, well Maintained By Owner Mileage 90,000.100 Percent Accident Free Nice No. Plate

Posted: 09-Feb-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW

DIRECT OWNER



BMW 3 Series 318i

\$36,188

\$11,470 /yr

12-Nov-2009

1,995 cc

-

Luxury

Available

Must View! Cheapest In The Market! Best Selling And Most Popular Continental Sedan! Superb Condition Inside Out! Low Mileage Done! No Repairs. Neat Price Negotiable! Max Loan Available! Flexible Loa...

Posted: 02-Apr-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW



Those Are Some Nice Rims

Don't let your tyre retire. Find all your car tyre and rim replacements are right here. A list of the best workshops available, each accompanied by real user reviews, photos and ranking so you make the right choice! Wheel you take care of your car forever?

Find out more!



BMW 3 Series 318i

\$37,800

\$12,770 /yr

12-Nov-2009

1,995 cc

-

Luxury

Available

Nice 3 Digit Number Plate! Extended Warranty And Servicing Package Available! Affordable Luxurious Sedan, Well Maintained In Excellent Condition, Space And Let The Car Speak For Itself! Buy With A Peac...

Perfect Automobile

Posted: 10-Feb-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i

\$37,555

\$12,070 /yr

25-Nov-2009

1,995 cc

119,152 km

Luxury

Available

Graded by **STP**

2 Year Loan Interest. Free 12 Months Warranty Package! Free Car Servicing! Free Car Spa Polish Package! Highest Trade In With Lowest In House. Easy Loan, \$3k Deposit, Low Down Payment. Call Now...

Perfect Credit Pte Ltd

Posted: 17-Mar-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i

\$37,900

\$12,330 /yr

25-Nov-2009

1,995 cc

152,000 km

Luxury

Available

Matte Grey Unit, Well Taken Care And Maintained By Owner. Selling Due To Upgrading. Original Paintwork And Condition. Very Spacious Interior And Exterior In Great Condition. ...

Posted: 14-Mar-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW

CONFIRMED



BMW 3 Series 318i

\$39,800

\$13,470 /yr

26-Nov-2009

1,995 cc

130,000 km

Luxury

Available

Interior/Exterior Condition Looks New. Gorgeous Exterior With Beige Interior. Powerful Engine And Smooth Transmission And Regular Servicing. Buy With Peace Of Mind. In House And Trade In Available!

Perfect Automobile & Trading

Posted: 29-Mar-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i

\$35,900

\$11,080 /yr

10-Dec-2009

1,995 cc

73,000 km

Luxury

Available

One Of The Most Reasonably Priced BMW 318i With Matching Luxurious Beige Leather Upholstery Owned By Expat Owner Selling Due To Upgrading. Serviced And Maintained Regularly.100% Accident Free...

Posted: 08-Feb-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW

CONFIRMED



BMW 3 Series 318i

\$35,500

\$10,860 /yr

11-Dec-2009

1,995 cc

-

Luxury

Available

Short Kit, Carbon Diffuser, White Angel DRL, All Plastic Handles Replaced. No Sticky Buttons. No Repairs Needed. New Engine Gaskets, Seals, Oil, A/C Compressor. Always Parked Under Shelter...

Posted: 07-Mar-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW

DIRECT OWNER



BMW 3 Series 318i

\$39,000

\$12,750 /yr

17-Dec-2009

1,995 cc

105,000 km

Luxury

Available

Well Serviced And Well Maintained By Lady Owner. New Set Of 18" Tyres.

Posted: 29-Mar-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW

DIRECT OWNER



BMW 3 Series 318i

\$35,800

\$10,700 /yr

31-Dec-2009

1,995 cc

85,000 km

Luxury

Available

Extremely Well Maintained, 100% Accident Free! Original Condition With No Touch Up Done, Genuine Low Mileage, Fully Maintained By Owner. Don't Miss To Appreciate Anytime, Before It's Gone!

Posted: 15-Mar-2018 Tags: 2009 BMW 318i, BMW 318i, BMW, 318i, Used BMW



BMW 3 Series 318i

\$37,800

\$11,780 /yr

31-Dec-2009

1,995 cc

-

Luxury

Available

Enquire for Registered Vehicle

Vehicle	Owner's
Owner	Singapore NRIC
Vehicle	3411Z
Vehicle	SJW3832G
Vehicle	Yes
Inte	Date:
Vehicle	06 Apr 2018
Vehicle	B.M.W.
Vehicle	318I 2.0L A/T ABS D/AIRBAG 2WD 4DR
Price	Brown
Man	2009
Engi	A602I581N46B20BZ
Char	WBAPF72020A793408
Max	100.0 kW (134 bhp)
Open	\$35,452.00
Orig	01 Dec 2009
First	01 Dec 2009
Tran	4
Actu	\$35,452.00
Inte	Details
PAR	Yes
PAR	30 Nov 2019
PAR	\$19,498.00
Inte	Details
COE	30 Nov 2019
COE	E - Open Category
COE	10
QP	\$18,267.00
COE	\$2,970.00
Total	\$22,468.00
The info	is correct as at 06 Apr 2018

OK

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883

TEL: 6842 9089 FAX: 6841 2869

REG NO : 48992400W

TP1st Cap
XiaoChun

Vehicle Number: SJW3832G

S/N	Item Description	List Price (\$)
1	Rear Bumper <i>deformed</i>	\$ 1,251.90
2	Rear Bumper Side Bracket x 2 pcs <i>New</i>	\$ 121.98
3	Rear Bumper Reinforcement (Upper) <i>New</i>	\$ 41.73
4	Rear Bumper Reinforcement (Lower) <i>Best</i>	\$ 449.40
5	Taillamp (LH) <i>coupled</i>	\$ 224.70
6	Taillamp Lower Side Retainer (LH) <i>New</i>	\$ 85.00
7	End Panel <i>Best</i>	\$ 882.75
8	End Panel Top Garnish <i>New</i>	\$ 128.40
9	Rear Boot <i>New</i>	\$ 1,284.00
10	Rear Boot Taillamp (LH) <i>New New</i>	\$ 296.93
11	Rear Boot Rubber <i>New</i>	\$ 93.09
12	Rear Boot BMW Centre Logo <i>New</i>	\$ 74.58
14	Exhaust <i>Best</i>	\$ 1,155.60
Total :		\$ 6,090.06
Less 10% :		\$ 609.01
Amount :		\$ 5,481.05

3203.58
2883.22

S/N	Special Nett Item	Amount (\$)
1	End Panel Sealant <i>New</i>	\$ 50.00
2	Reverse Sensor x 4 pcs <i>1 piece damaged</i>	\$ 1,016.84
Amount :		\$ 1,066.84

250

Labour	Amount (\$)
To check rear electrical wiring system	\$ 180.00
To transfer rear boot component parts to new rear boot	\$ 100.00
To remove & reinstall exhaust pipe	\$ 280.00
To apply anti-rusting coating on new and affected areas	\$ 200.00
To remove & reinstall rear boot's interior trims for necessary repair	\$ 180.00
Labour to remove, cut, change & panel beating	\$ 980.00
To putty and respray affected areas	\$ 800.00
the Repairer of the following:	
• To resurvey before/after spray painting	
• To display damaged parts during resurvey	
• Parts prices are subject to confirmation	
• Third party survey is on a "Without Prejudice" basis	
• No illegal modification(s) is allowed	
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	
Labour Total :	\$ 2,720.00
Total (Parts & Labour)	\$ 9,267.89

30
x
80
x
x
300
250

660

total 3543.22
L/s 28K
04Pays

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18006178/Aqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 17-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 5740P	Veh. Inspected	SJW 3832G	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18002616MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	04/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	BMW 318	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	WBAPF72020A793408	Colour	GOLD	
Odometer	163511	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	FIRESTONE	6 mm	
L/H Front Tyre	205/55 R16	FIRESTONE	6 mm	
R/H Rear Tyre	205/55 R16	FIRESTONE	6 mm	
L/H Rear Tyre	205/55 R16	FIRESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/03/2018	Inspection Date	05/04/2018	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJW 3832G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEFORMED	1,251.90	1,251.90
2	REAR BUMPER SIDE BRACKET	NECESSARY	121.98	121.98
1	REAR BUMPER REINFORCEMENT (UPPER)	NOT NECESSARY	41.73	-
1	REAR BUMPER REINFORCEMENT (LOWER)	BENT	449.40	449.40
1	TAILLAMP (LH)	CRACKED	224.70	224.70
1	TAILLAMP LOWER SIDE RETAINER (LH)	NOT NECESSARY	85.00	-
1	END PANEL	TO REPAIR SEE LABOUR	882.75	-
1	END PANEL TOP GARNISH	NOT NECESSARY	128.40	-
1	REAR BOOT	NOT NECESSARY	1,284.00	-
1	REAR BOOT TAILLAMP (LH)	NOT NECESSARY	296.93	-
1	REAR BOOT RUBBER	NOT NECESSARY	93.09	-
1	REAR BOOT BMW CENTRE LOGO	NOT NECESSARY	74.58	-
1	EXHAUST	BENT	1,155.60	1,155.60
	LESS 10% DISCOUNT		-609.01	-320.36
			5,481.05	2,883.22
SPECIAL NETT ITEMS				
1	END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
4	REVERSE SENSOR (SN)	DAMAGED (1 PC ONLY)	1,016.84	250.00
			1,066.84	250.00
LABOUR				
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		180.00	30.00
	TO TRANSFER REAR BOOT COMPONENT PARTS TO NEW REAR BOOT.	NOT NECESSARY	100.00	-
	TO REMOVE & REINSTALL EXHAUST PIPE.		280.00	80.00
	TO APPLY ANTI-RUSTING COATING ON NEW AND AFFECTED AREAS.	NOT NECESSARY	200.00	-
	TO REMOVE & REINSTALL REAR BOOT'S INTERIOR TRIMS FOR NECESSARY REPAIR.	NOT NECESSARY	180.00	-
	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING.INCLUSIVE OF THE REPAIR OF END PANEL.		980.00	300.00

Report Ref No. CS/FCI18006178/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND RESPRAY AFFECTED AREAS.		800.00	250.00
			2,720.00	660.00
	GRAND TOTAL		9,267.89	3,793.22
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,000.00

Report Ref No. CS/FC118006178/Aqbn2

MARKET VALUE: \$35,000.00 (EST)-PAPER VALUE: \$22,500.00=NETT VALUE: \$12,500.00

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.